

# Edward T. Steel School: Asbestos Hazard Report

The Philadelphia Regional Center for Children's Environmental Health has partnered with the Healthy Schools Initiative to analyze and report on public information regarding asbestos conditions in schools made available on the School District of Philadelphia's website.

This report is meant to communicate to parents, teachers, and staff the exposure risk at their school and help prioritize the removal of asbestos in high-risk exposure locations.

Our analysis is based on publicly available reports. We have not conducted inspections or verified the reports.

## Key Findings:

- 107 teacher / student occupied spaces have asbestos containing material (ACM)
- 2 spaces had damaged ACM
- 90 spaces contained friable ACM
- **1 of 2 damaged** materials were scheduled to be abated

## Our Recommendations:

- The School District scheduled the abatement for one of two damaged ACM identified during their latest inspection in Jan 2025. The School District did not abate damaged friable asbestos containing paint in the closet across from classroom 113 (see Table 1). We recommend this material to be abated immediately.
- The School District is required to regularly monitor the condition of their ACM by the EPA. We recommend the complete removal of friable ACM instead of encapsulation for materials that have been repeatedly damaged (See Table 1).



## What is asbestos?

**Asbestos is a fibrous material that is resistant to heat, water, and corrosion.**

See this link for a comprehensive list: <https://prcceh.upenn.edu/asbestos>

## Asbestos was used in materials in schools, including:

- Ceiling Tiles
- Floor Tiles
- Pipe Insulation
- Cement
- Paint and Caulk
- Soundproofing
- Fireproofing
- Plaster Materials

## What are the health effects of asbestos?

No immediate health impacts are expected from asbestos exposure in schools. However, breathing asbestos fibers in schools may increase the risk of developing cancer many years from now.

Children are very active, breathing more air while running and playing. Children take more breaths per minute than adults and are lower to the ground where asbestos fibers may settle. This puts them at an increased risk for asbestos exposure.

## Are all asbestos containing materials of equal risk?

Some asbestos containing materials like ceiling and floor tiles have asbestos fibers imbedded in other materials. As long as they are not broken or damaged the asbestos fibers are not released into the air.

Some asbestos containing materials like insulation on pipe remains fibrous and can easily be released in the air when damaged.

## How are damaged asbestos containing materials managed?

Asbestos can be removed. Sometimes damaged materials are managed in place by patching, encapsulating (using a specially formulated paint-like coating) or building an enclosure around damaged and/or accessible materials. All of these are forms of abatement.

The Environmental Protection Agency requires all remaining asbestos containing material to be inspected by the school district every six months. This is documented in an Asbestos Hazard Emergency Response Act Report (AHERA Report).

### Important Terms

*Get to know these terms to make the most out of this report.*

**Damaged Asbestos Containing Material (ACM)** can release asbestos fibers into the air.

**Friable Materials** can be reduced to a powder by applying hand pressure. **DO NOT TOUCH!**

**Non-Friable materials** are not easily damaged.

**Significantly damaged materials** are more than 10% damaged.

**Abated ACM** means repaired, removed, or reduced risk of exposure.

## Detailed Review for Thomas K. Finletter School

This school has 131 spaces with asbestos containing materials. 107 of them are in teacher / student occupied spaces. The School District last inspected ACM in Jan 2025 and published the AHERA report in Feb 2025. Since then, the School District scheduled the abatement of one of two damaged asbestos containing paint materials identified during this inspection.



We recommend that the school district immediately abate the damaged asbestos containing paint found in the closet across from classroom 113. We recommend that the School District completely remove friable ACM that have been repeatedly damaged in the past as listed in Table 1. Abatement was scheduled in 2025, however the website does not confirm that the abatement was completed. A list of all the ACM in the school and their damage/abatement schedule can be found in the tables at the end of this report.

### Information Reviewed to Make this Report:

The 2024/25 AHERA report from the School District of Philadelphia, and asbestos abatement notifications from the Air Management Services Online Portal.

**Not included** in this report are planned repairs to damaged asbestos materials that have not been uploaded to the Air Management Services website or any updated after April 25, 2025. To see the most current information, scan these QR Codes. After scanning, search for your school.

#### School Districts of Philadelphia Asbestos Reports:



AHERA Reports are documents generated from EPA required asbestos inspections

#### Office of the Controller Asbestos Project:



Asbestos abatement notification forms



Report what you see!

Parents and teachers should report hazardous conditions in schools on the Healthy Schools app.

Scan here to  
download the app:



### Disclaimer:

This report analyzes custodial and mechanical spaces like boiler rooms **only** when ACM is significantly damaged (damage > 10%).

## Questions?

Find more resources on our website!

- Photo gallery of different types of damaged asbestos containing materials
- Guide to how we classify materials in schools
- Our analysis and reporting methodology
- What we do with the information in this report

[prcceb.upenn.edu/asbestos](http://prcceb.upenn.edu/asbestos)



Email us at [prcceb@pennteamedicine.upenn.edu](mailto:prcceb@pennteamedicine.upenn.edu) or call 215-573-9076

Table 1: Friable Asbestos Containing Materials Identified

**NOTE:** Friable materials can be reduced to a powder by applying hand pressure.  
***Do not touch it!*** Damaged and significantly damaged friable materials readily release harmful asbestos fibers into the air.

Location	Friable Asbestos Containing Material	Reported as Damaged or Significantly Damaged? (Blank = No)	Abatement scheduled since the inspection? (Blank = No)
Staff Restroom across from Classroom 105	Paint associated with Wall, CMU		
Pre-K Bathroom across from Office 103	Paint associated with Wall, CMU		
Cafeteria Storage Room	Paint associated with Wall, CMU		
Teacher's Lounge adjacent to Cafeteria (across from Main Office)	Paint associated with Wall, CMU		
Cafeteria Kitchen	Paint associated with Wall, CMU		
Office Suite adjacent to Main Lobby Common Area	Paint associated with Wall, CMU		
Office Suite adjacent to Main Lobby Left Office	Paint associated with Wall, CMU		
Office Suite adjacent to Main Lobby Center Office	Paint associated with Wall, CMU		
Office Suite adjacent to Main Lobby Right Office	Paint associated with Wall, CMU		
Main Office	Paint associated with Wall, CMU		
Main Office Copier Room	Paint associated with Wall, CMU		
Main Office Assistant Principal's Office	Paint associated with Wall, CMU		

# Edward T. Steel School: Asbestos Hazard Report

Principal's Office	Paint associated with Wall, CMU		
Main Office Conference Room	Paint associated with Wall, CMU		
Principal's Office Closet	Paint associated with Wall, CMU		
Main Office Conference Room Closet	Paint associated with Wall, CMU		
Custodial Closet adjacent to Main Office	Paint associated with Wall, CMU		
Head Start Office 103 adjacent to Classroom 105	Paint associated with Wall, CMU		
Office 104 Front Office	Paint associated with Wall, CMU		
Principal's Office Restroom	Paint associated with Wall, CMU		
Classroom 105	Paint associated with Wall, CMU		
Classroom 105 Closet	Paint associated with Wall, CMU		
Teacher Lounge 106	Paint associated with Wall, CMU		
Teacher Lounge 106 Supply Room	Paint associated with Wall, CMU		
Classroom 107	Paint associated with Wall, CMU		
Classroom 107 Restroom	Paint associated with Wall, CMU		
Unisex Locker Room 108 adjacent to Nurse's Office	Paint associated with Wall, CMU		
Server Room adjacent to Teacher's Lounge 106	Paint associated with Wall, CMU		
Unisex Locker Room 108 adjacent to Nurse's Office Restroom	Paint associated with Wall, CMU		
Classroom 109	Paint associated with Wall, CMU		
Classroom 109 Restroom	Paint associated with Wall, CMU		
Classroom 109 Storage	Paint associated with Wall, CMU		
Nurse's Office Restroom	Paint associated with Wall, CMU		
Nurse's Office Examination Room between Restroom and Office	Paint associated with Wall, CMU		
Nurse's Office	Paint associated with Wall, CMU		
Nurse's Office Exam Room between Restroom and Unisex Locker Room	Paint associated with Wall, CMU		
Nurse's Office Storage Room adjacent to Former Therapist Office 110	Paint associated with Wall, CMU		
Storage Room 110 (Former Therapist Office)	Paint associated with Wall, CMU		
Nurse's Office Waiting Area	Paint associated with Wall, CMU		
Classroom 111	Paint associated with Wall, CMU		
Classroom 111	Paint associated with Wall, CMU		

# Edward T. Steel School: Asbestos Hazard Report

Classroom 111 Restroom	Paint associated with Wall, CMU		
Classroom 111 and 113 Storage Room	Paint associated with Wall, CMU		
Boiler Room	Paint associated with Wall, CMU		
Building Engineer's Office	Paint associated with Wall, CMU		
Building Engineer's Office Restroom	Paint associated with Wall, CMU		
Classroom 113	Paint associated with Wall, CMU		
Classroom 113 Restroom	Paint associated with Wall, CMU		
Storage Room adjacent to Boiler Room	Paint associated with Wall, CMU		
Closet across from Classroom 113	Paint associated with Wall, CMU	Damaged.	
Auditorium	Textured Plaster Wall		
Girl's Restroom adjacent to Gymnasium	Heat Shield Insulation associated with Radiator Insulation		
Girl's Restroom adjacent to Gymnasium	Paint associated with Wall, CMU		
Boy's Restroom adjacent to Gymnasium	Heat Shield Insulation associated with Radiator Insulation		
Boy's Restroom adjacent to Gymnasium	Paint associated with Wall, CMU		
Auditorium Stage	Paint associated with Wall, CMU		
Gymnasium	Paint associated with Wall, CMU		
Gymnasium Office	Paint associated with Wall, CMU		
Gymnasium Office Restroom	Heat Shield Insulation associated with Radiator Insulation		
Gymnasium Office Restroom	Paint associated with Wall, CMU		
Gymnasium Storage Room	Heat Shield Insulation associated with Radiator Insulation		
Gymnasium Storage Room	Paint associated with Wall, CMU		
Girl's Locker Room	Paint associated with Wall, CMU		
Boy's Restroom adjacent to Boy's Locker Room	Paint associated with Wall, CMU		
Vestibule outside Boy's Locker Room	Paint associated with Wall, CMU	Damaged. Previously damaged in August 2024 AHERA report.	Scheduled to be encapsulated in April 2025.
Vestibule outside Girl's Locker Room	Paint associated with Wall, CMU		
Hallway from Main Lobby to Teacher's Lounge 106	Paint associated with Wall, CMU		
Hallway from Main Entrance Lobby to Classroom 109	Paint associated with Wall, CMU		



# Edward T. Steel School: Asbestos Hazard Report

Hallway from Nurse's Office to Gymnasium	Paint associated with Wall, CMU		
Hallway from Classroom 109 to Gymnasium	Paint associated with Wall, CMU		
Main Entrance Lobby Stairwell	Heat Shield Insulation associated with Radiator Insulation		
Main Entrance Lobby Stairwell	Paint associated with Wall, CMU		
Main Entrance Lobby	Paint associated with Wall, CMU		
Stairwell adjacent to Gym	Heat Shield Insulation associated with Radiator Insulation		
Stairwell to Auditorium Right of Stage	Paint associated with Wall, CMU		
Stairwell adjacent to Classroom 113	Heat Shield Insulation associated with Radiator Insulation		
Stairwell adjacent to Classroom 113	Paint associated with Wall, CMU		
Stairwell to Auditorium Left of Stage	Paint associated with Wall, CMU		
Classroom 201	Paint associated with Wall, CMU		
Classroom 202	Paint associated with Wall, CMU		
Classroom 202 Closet	Paint associated with Wall, CMU		
Classroom 203	Paint associated with Wall, CMU		
Classroom 204	Paint associated with Wall, CMU		
Classroom 205	Paint associated with Wall, CMU		
Classroom 206	Paint associated with Wall, CMU		
Classroom 207	Paint associated with Wall, CMU		
Classroom 208	Paint associated with Wall, CMU		
Classroom 209	Paint associated with Wall, CMU		
Classroom 210	Paint associated with Wall, CMU		
Girl's Restroom adjacent to Classroom 211	Paint associated with Wall, CMU		
Boy's Restroom adjacent to Classroom 211	Paint associated with Wall, CMU		
Custodial Closet adjacent to Classroom 211	Paint associated with Wall, CMU		
Classroom 213	Paint associated with Wall, CMU		
Classroom 214	Paint associated with Wall, CMU		
Girl's Restroom adjacent to Classroom 214	Paint associated with Wall, CMU		

# Edward T. Steel School: Asbestos Hazard Report

Boy's Restroom adjacent to Classroom 214	Paint associated with Wall, CMU		
Custodial Closet adjacent to Classroom 214	Paint associated with Wall, CMU		
Office 215 adjacent to Women's Restroom	Paint associated with Wall, CMU		
Women's Restroom by Classroom 215	Paint associated with Wall, CMU		
Men's Restroom by Classroom 215	Paint associated with Wall, CMU		
Classroom 213 Office	Paint associated with Wall, CMU		
Office 216	Paint associated with Wall, CMU		
Office 216 Storage Room	Paint associated with Wall, CMU		
Mechanical Room adjacent to Classroom 219	Paint associated with Wall, CMU		
Mechanical Room adjacent to Classroom 220	Paint associated with Wall, CMU		
Storage Room adjacent to Classroom 202	Paint associated with Wall, CMU		
Classroom 219	Paint associated with Wall, CMU		
Classroom 220	Paint associated with Wall, CMU		
Storage Room across from Classroom 211	Paint associated with Wall, CMU		
Storage Room adjacent to Classroom 220	Paint associated with Wall, CMU		
Storage Room adjacent to Elevator Mechanical Room	Paint associated with Wall, CMU		
Elevator Mechanical Room	Paint associated with Wall, CMU		
Hallway from Classrooms 210 to 209	Paint associated with Wall, CMU		
Hallway from Office 216 to Classroom 220	Paint associated with Wall, CMU		
Hallway from Classroom 215 to 219	Paint associated with Wall, CMU		
IMC Office Odd Side adjacent to Stairwell	Paint associated with Wall, CMU		
IMC Storage Room Odd Side Rear	Paint associated with Wall, CMU		
IMC Material Production Room	Paint associated with Wall, CMU		
IMC Material Production Room Telecommunication Equipment Room	Paint associated with Wall, CMU		
IMC Material Production Room Telecommunication Equipment Room	Paint associated with Wall, CMU		
Stairwell adjacent to Classroom 201	Paint associated with Wall, CMU		
Stairwell adjacent to Office 216	Paint associated with Wall, CMU		
Stairwell adjacent to Women's Restroom by Classroom 215	Paint associated with Wall, CMU		
Stairwell to IMC between Mechanical Rooms	Paint associated with Wall, CMU		



# Edward T. Steel School: Asbestos Hazard Report

Stairwell to IMC on Odd Side	Paint associated with Wall, CMU		
Stairwell to IMC adjacent to Material Production Room	Paint associated with Wall, CMU		
Classroom 302 Closet	Paint associated with Wall, CMU		
Classroom 305	Paint associated with Wall, CMU		
Classroom 307	Paint associated with Wall, CMU		
Classroom 310	Paint associated with Wall, CMU		
Classroom 311	Paint associated with Wall, CMU		
Girl's Restroom adjacent Classroom 311	Paint associated with Wall, CMU		
Boy's Restroom adjacent Classroom 311	Paint associated with Wall, CMU		
Custodial Closet adjacent Classroom 311	Paint associated with Wall, CMU		
Classroom 312	Paint associated with Wall, CMU		
Classroom 313	Paint associated with Wall, CMU		
Classroom 314	Paint associated with Wall, CMU		
Girl's Restroom adjacent to Classroom 314	Paint associated with Wall, CMU		
Boy's Restroom adjacent to Classroom 314	Paint associated with Wall, CMU		
Custodial Closet adjacent to Classroom 314	Paint associated with Wall, CMU		
Classroom 314 Closet	Paint associated with Wall, CMU		
Classroom 313 Restroom	Paint associated with Wall, CMU		
Former Teacher's Lounge	Paint associated with Wall, CMU		
Men's Restroom near Classroom 313	Heat Shield Insulation associated with Radiator Insulation		
Men's Restroom near Classroom 313	Paint associated with Wall, CMU		
Women's Restroom adjacent to Former Teacher's Lounge	Heat Shield Insulation associated with Radiator Insulation		
Women's Restroom adjacent to Former Teacher's Lounge	Paint associated with Wall, CMU		
Storage Room 316	Heat Shield Insulation associated with Radiator Insulation		
Storage Room 316	Paint associated with Wall, CMU		
Mechanical Room across from Classroom 301	Paint associated with Wall, CMU		
Mechanical Room across from Classroom 302	Paint associated with Door Component, Other		

# Edward T. Steel School: Asbestos Hazard Report

Mechanical Room across from Classroom 302	Paint associated with Wall, CMU		
Storage Room adjacent to Classroom 302	Paint associated with Wall, CMU		
Classroom 320	Paint associated with Wall, CMU		
Storage across from Classroom 311	Paint associated with Wall, CMU		
Storage Room adjacent to Classroom 320	Paint associated with Wall, CMU		
Storage Room adjacent to Elevator	Heat Shield Insulation associated with Radiator Insulation		
Storage Room adjacent to Elevator	Paint associated with Wall, CMU		
Hallway from Classroom 304 to Storage Room 316	Heat Shield Insulation associated with Radiator Insulation		
Hallway from Classroom 304 to Storage Room 316	Paint associated with Wall, CMU		
Hallway from Men's Restroom to Classroom 305	Paint associated with Wall, CMU		
Hallway from Men's Restroom to Classroom 305	Heat Shield Insulation associated with Radiator Insulation		
Hallway from Men's Restroom to Classroom 305	Paint associated with Wall, CMU		
Hallway from Classrooms 307 to 310	Heat Shield Insulation associated with Radiator Insulation		
Hallway from Classrooms 307 to 310	Paint associated with Wall, CMU		
Stairwell adjacent to Classroom 301	Paint associated with Wall, CMU		
Stairwell adjacent to Storage Room 316	Paint associated with Wall, CMU		
Stairwell near Classroom 313	Paint associated with Wall, CMU		
Stairwell to Roof between Mechanical Rooms	Paint associated with Wall, CMU		

**Table 2: Non-Friable Asbestos Containing Materials Identified**

**NOTE: Significantly Damaged non-friable materials (damage  $\geq$  10% of the material) can release harmful asbestos fibers into the air.**

Location	Material Name	Reported as Damaged or Significantly Damaged?	Abatement scheduled since the inspection?
Cafeteria	Mastic associated with Floor Tile		
Cafeteria	Floor Tile VAT 12" x 12"		
Cafeteria	Floor Tile VAT 12" x 12"		
Cafeteria	Transite associated with Window Sill		
Cafeteria Storage Room	Floor Tile VAT 12" x 12"		
Teacher's Lounge adjacent to Cafeteria (across from Main Office)	Floor Tile VAT 12" x 12"		

# Edward T. Steel School: Asbestos Hazard Report

Cafeteria Kitchen	Transite associated with Window Sill		
Elevator	Floor Tile VAT 12" x 12"		
Office Suite adjacent to Main Lobby Common Area	Glue Dots associated with Blackboard		
Office Suite adjacent to Main Lobby Common Area	Floor Tile VAT 12" x 12"		
Office Suite adjacent to Main Lobby Left Office	Floor Tile VAT 12" x 12"		
Office Suite adjacent to Main Lobby Center Office	Glue Dots associated with Blackboard		
Office Suite adjacent to Main Lobby Center Office	Floor Tile VAT 12" x 12"		
Office Suite adjacent to Main Lobby Right Office	Floor Tile VAT 12" x 12"		
Main Office	Glue Dots associated with Blackboard		
Main Office	Floor Tile VAT 12" x 12"		
Main Office Copier Room	Sink Undercoat Mastic		
Main Office Copier Room	Glue Dots associated with Blackboard		
Main Office Copier Room	Floor Tile VAT 12" x 12"		
Main Office Assistant Principal's Office	Sink Undercoat Mastic		
Main Office Assistant Principal's Office	Floor Tile VAT 12" x 12"		
Principal's Office	Glue Dots associated with Blackboard		
Principal's Office	Floor Tile VAT 12" x 12"		
Principal's Office	Floor Tile VAT 12" x 12"		
Main Office Conference Room	Glue Dots associated with Blackboard		
Main Office Conference Room	Floor Tile VAT 12" x 12"		
Principal's Office Closet	Floor Tile VAT 12" x 12"		
Main Office Conference Room Closet	Floor Tile VAT 12" x 12"		
Head Start Office 103 adjacent to Classroom 105	Floor Tile VAT 12" x 12"		
Office 104 Rear Office	Sink Undercoat Mastic		
Office 104 Rear Office	Glue Dots associated with Blackboard		
Office 104 Rear Office	Floor Tile VAT 12" x 12"		
Office 104 Front Office	Glue Dots associated with Blackboard		
Office 104 Front Office	Floor Tile VAT 12" x 12"		
Classroom 105	Glue Dots associated with Blackboard		
Classroom 105	Floor Tile VAT 12" x 12"		
Classroom 105 Closet	Floor Tile VAT 12" x 12"		
Teacher Lounge 106	Glue Dots associated with Blackboard		
Teacher Lounge 106	Floor Tile VAT 12" x 12"		
Teacher Lounge 106 Supply Room	Floor Tile VAT 12" x 12"		
Classroom 107	Glue Dots associated with Blackboard		
Classroom 107	Floor Tile VAT 12" x 12"		
Unisex Locker Room 108 adjacent to Nurse's Office	Floor Tile VAT 12" x 12"		
Unisex Locker Room 108 adjacent to Nurse's Office	Floor Tile VAT 12" x 12"		
Classroom 109	Glue Dots associated with Blackboard		
Classroom 109	Floor Tile VAT 12" x 12"		
Classroom 109 Storage	Floor Tile VAT 12" x 12"		
Nurse's Office Examination Room between Restroom and Office	Sink Undercoat Mastic		
Nurse's Office Examination Room between Restroom and Office	Floor Tile VAT 12" x 12"		
Nurse's Office	Glue Dots associated with Blackboard		

# Edward T. Steel School: Asbestos Hazard Report

Nurse's Office	Sink Undercoat Mastic		
Nurse's Office	Floor Tile VAT 12" x 12"		
Nurse's Office Exam Room between Restroom and Unisex Locker Room	Floor Tile VAT 12" x 12"		
Nurse's Office Exam Room between Restroom and Unisex Locker Room	Transite associated with Transite Panel		
Storage Room 110 (Former Therapist Office)	Mastic associated with Floor Tile		
Storage Room 110 (Former Therapist Office)	Glue Dots associated with Blackboard		
Storage Room 110 (Former Therapist Office)	Sink Undercoat Mastic		
Nurse's Office Waiting Area	Glue Dots associated with Blackboard		
Nurse's Office Waiting Area	Floor Tile VAT 12" x 12"		
Classroom 111	Glue Dots associated with Blackboard		
Classroom 111	Floor Tile VAT 12" x 12"		
Classroom 111 and 113 Storage Room	Floor Tile VAT 12" x 12"		
Boiler Room	Gasket associated with Boiler		
Boiler Room	Caulk associated with Duct Seam		
Classroom 113	Glue Dots associated with Blackboard		
Classroom 113	Floor Tile VAT 12" x 12"		
Closet across from Classroom 113	Floor Tile VAT 12" x 12"		
Auditorium	Floor Tile VAT 12" x 12"		
Auditorium Stage	Transite associated with Window Sill		
Gymnasium	Floor Tile VAT 12" x 12"		
Gymnasium	Transite associated with Window Sill		
Gymnasium Office	Floor Tile VAT 12" x 12"		
Boy's Locker Room	Floor Tile VAT 12" x 12"		
Boy's Locker Room	Floor Tile VAT 12" x 12"		
Girl's Locker Room	Floor Tile VAT 12" x 12"		
Boy's Restroom adjacent to Boy's Locker Room	Floor Tile VAT 12" x 12"		
Vestibule outside Boy's Locker Room	Floor Tile VAT 12" x 12"		
Vestibule outside Girl's Locker Room	Floor Tile VAT 12" x 12"		
Hallway from Main Lobby to Teacher's Lounge 106	Mastic associated with Floor Tile		
Hallway from Main Lobby to Teacher's Lounge 106	Floor Tile VAT 12" x 12"		
Hallway from Main Lobby to Teacher's Lounge 106	Floor Tile VAT 12" x 12"		
Hallway from Main Entrance Lobby to Classroom 109	Mastic associated with Floor Tile		
Hallway from Main Entrance Lobby to Classroom 109	Transite associated with Fire Extinguisher Sill		
Hallway from Main Entrance Lobby to Classroom 109	Floor Tile VAT 12" x 12"		
Hallway from Nurse's Office to Gymnasium	Mastic associated with Floor Tile		
Hallway from Nurse's Office to Gymnasium	Floor Tile VAT 12" x 12"		
Hallway from Classroom 109 to Gymnasium	Mastic associated with Floor Tile		
Hallway from Classroom 109 to Gymnasium	Transite associated with Fire Extinguisher Sill		
Hallway from Classroom 109 to Gymnasium	Glue Dots associated with Blackboard		

# Edward T. Steel School: Asbestos Hazard Report

Hallway from Classroom 109 to Gymnasium	Floor Tile VAT 12" x 12"		
Stairwell to Auditorium Right of Stage	Floor Tile VAT 12" x 12"		
Stairwell adjacent to Classroom 113	Transite associated with Window Sill		
Stairwell to Auditorium Left of Stage	Floor Tile VAT 12" x 12"		
Classroom 201	Glue Dots associated with Blackboard		
Classroom 201	Floor Tile VAT 12" x 12"		
Classroom 201	Transite associated with Window Sill		
Classroom 202	Mastic associated with Floor Tile		
Classroom 202	Glue Dots associated with Blackboard		
Classroom 202	Floor Tile VAT 12" x 12"		
Classroom 202	Transite associated with Window Sill		
Classroom 202 Closet	Mastic associated with Floor Tile		
Classroom 202 Closet	Floor Tile VAT 12" x 12"		
Classroom 203	Glue Dots associated with Blackboard		
Classroom 203	Floor Tile VAT 12" x 12"		
Classroom 203	Transite associated with Window Sill		
Classroom 204	Glue Dots associated with Blackboard		
Classroom 204	Transite associated with Window Sill		
Classroom 204	Floor Tile VAT 12" x 12"		
Classroom 205	Glue Dots associated with Blackboard		
Classroom 205	Floor Tile VAT 12" x 12"		
Classroom 205	Transite associated with Window Sill		
Classroom 206	Glue Dots associated with Blackboard		
Classroom 206	Floor Tile VAT 12" x 12"		
Classroom 206	Transite associated with Window Sill		
Classroom 207	Floor Tile VAT 12" x 12"		
Classroom 207	Transite associated with Window Sill		
Classroom 208	Transite associated with Window Sill		
Classroom 208	Sink Undercoat Mastic		
Classroom 208	Glue Dots associated with Blackboard		
Classroom 208	Mastic associated with Floor Tile		
Classroom 208	Floor Tile VAT 12" x 12"		
Classroom 209	Floor Tile VAT 12" x 12"		
Classroom 209	Transite associated with Window Sill		
Classroom 210	Sink Undercoat Mastic		
Classroom 210	Glue Dots associated with Blackboard		
Classroom 210	Transite associated with Window Sill		
Classroom 211	Glue Dots associated with Blackboard		
Classroom 211	Floor Tile VAT 12" x 12"		
Classroom 211	Transite associated with Window Sill		
Classroom 212	Sink Undercoat Mastic		
Classroom 212	Glue Dots associated with Blackboard		
Classroom 212	Mastic associated with Floor Tile		
Classroom 212	Floor Tile VAT 12" x 12"		
Classroom 212	Floor Tile VAT 12" x 12"		
Classroom 212	Transite associated with Window Sill		
Classroom 213	Floor Tile VAT 12" x 12"		
Classroom 213	Mastic associated with Floor Tile		
Classroom 213	Floor Tile VAT 12" x 12"		
Classroom 214	Sink Undercoat Mastic		
Classroom 214	Glue Dots associated with Blackboard		
Classroom 214	Floor Tile VAT 12" x 12"		
Classroom 214	Transite associated with Window Sill		

# Edward T. Steel School: Asbestos Hazard Report

Office 215 adjacent to Women's Restroom	Floor Tile VAT 12" x 12"		
Classroom 213 Office	Floor Tile VAT 12" x 12"		
Office 216	Mastic associated with Floor Tile		
Office 216	Transite associated with Window Sill		
Office 216	Floor Tile VAT 12" x 12"		
Mechanical Room adjacent to Classroom 219	Mastic associated with Fiberglass Pipe Insulation		
Mechanical Room adjacent to Classroom 220	Mastic associated with Floor Tile		
Classroom 219	Mastic associated with Floor Tile		
Classroom 219	Glue Dots associated with Blackboard		
Classroom 219	Floor Tile VAT 12" x 12"		
Classroom 220	Mastic associated with Floor Tile		
Classroom 220	Glue Dots associated with Blackboard		
Classroom 220	Floor Tile VAT 12" x 12"		
Storage Room adjacent to Elevator Mechanical Room	Floor Tile VAT 12" x 12"		
Hallway from Classrooms 210 to 209	Transite associated with Fire Extinguisher Sill		
Hallway from Classrooms 210 to 209	Mastic associated with Floor Tile		
Hallway from Classrooms 210 to 209	Floor Tile VAT 12" x 12"		
Hallway from Office 216 to Classroom 220	Transite associated with Fire Extinguisher Sill		
Hallway from Office 216 to Classroom 220	Mastic associated with Floor Tile		
Hallway from Office 216 to Classroom 220	Floor Tile VAT 12" x 12"		
Hallway from Classroom 215 to 219	Transite associated with Fire Extinguisher Sill		
Hallway from Classroom 215 to 219	Floor Tile VAT 12" x 12"		
Library	Floor Tile VAT 12" x 12"		
Library	Transite associated with Window Sill		
IMC Office Odd Side adjacent to Stairwell	Mastic associated with Floor Tile		
IMC Office Odd Side adjacent to Stairwell	Glue Dots associated with Blackboard		
IMC Office Odd Side adjacent to Stairwell	Floor Tile VAT 12" x 12"		
IMC Storage Room Odd Side Rear	Floor Tile VAT 12" x 12"		
IMC Material Production Room	Glue Dots associated with Blackboard		
IMC Material Production Room	Floor Tile VAT 12" x 12"		
IMC Material Production Room Telecommunication Equipment Room	Floor Tile VAT 12" x 12"		
Stairwell adjacent to Classroom 201	Floor Tile VAT 12" x 12"		
Stairwell adjacent to Office 216	Floor Tile VAT 12" x 12"		
Stairwell adjacent to Office 216	Transite associated with Window Sill		
Stairwell adjacent to Women's Restroom by Classroom 215	Floor Tile VAT 12" x 12"		
Stairwell adjacent to Women's Restroom by Classroom 215	Transite associated with Window Sill		
Stairwell to IMC between Mechanical Rooms	Floor Tile VAT 12" x 12"		
Stairwell to IMC on Odd Side	Floor Tile VAT 12" x 12"		
Stairwell to IMC adjacent to Material Production Room	Floor Tile VAT 12" x 12"		
Room 301	Sink Undercoat Mastic		
Room 301	Transite associated with Window Sill		



# Edward T. Steel School: Asbestos Hazard Report

Classroom 302	Sink Undercoat Mastic		
Classroom 302	Glue Dots associated with Blackboard		
Classroom 302	Transite associated with Window Sill		
Classroom 302 Closet	Floor Tile VAT 12" x 12"		
Classroom 303	Glue Dots associated with Blackboard		
Classroom 303	Sink Undercoat Mastic		
Classroom 303	Floor Tile VAT 12" x 12"		
Classroom 303	Transite associated with Window Sill		
Classroom 304	Glue Dots associated with Blackboard		
Classroom 304	Floor Tile VAT 12" x 12"		
Classroom 304	Transite associated with Window Sill		
Classroom 305	Glue Dots associated with Blackboard		
Classroom 305	Sink Undercoat Mastic		
Classroom 305	Floor Tile VAT 12" x 12"		
Classroom 305	Transite associated with Window Sill		
Classroom 306	Glue Dots associated with Blackboard		
Classroom 306	Floor Tile VAT 12" x 12"		
Classroom 306	Transite associated with Window Sill		
Classroom 307	Sink Undercoat Mastic		
Classroom 307	Glue Dots associated with Blackboard		
Classroom 307	Floor Tile VAT 12" x 12"		
Classroom 307	Transite associated with Window Sill		
Classroom 308	Glue Dots associated with Blackboard		
Classroom 308	Transite associated with Window Sill		
Classroom 309	Mastic associated with Floor Tile		
Classroom 309	Sink Undercoat Mastic		
Classroom 309	Glue Dots associated with Blackboard		
Classroom 309	Floor Tile VAT 12" x 12"		
Classroom 309	Transite associated with Window Sill		
Classroom 310	Glue Dots associated with Blackboard		
Classroom 310	Sink Undercoat Mastic		
Classroom 310	Transite associated with Window Sill		
Classroom 311	Sink Undercoat Mastic		
Classroom 311	Transite associated with Window Sill		
Classroom 312	Sink Undercoat Mastic		
Classroom 312	Glue Dots associated with Blackboard		
Classroom 312	Transite associated with Window Sill		
Classroom 313	Mastic associated with Floor Tile		
Classroom 313	Sink Undercoat Mastic		
Classroom 313	Glue Dots associated with Blackboard		
Classroom 313	Floor Tile VAT 12" x 12"		
Classroom 313	Transite associated with Window Sill		
Classroom 314	Glue Dots associated with Blackboard		
Classroom 314	Floor Tile VAT 18" x 18"		
Classroom 314	Transite associated with Window Sill		
Classroom 314 Closet	Floor Tile VAT 18" x 18"		
Former Teacher's Lounge	Floor Tile VAT 12" x 12"		
Mechanical Room across from Classroom 301	Mastic associated with Floor Tile		
Mechanical Room across from Classroom 301	Mortar associated with Wall, CMU		
Mechanical Room across from Classroom 302	Mortar associated with Wall, CMU		
Technology Office 319	Glue Dots associated with Blackboard		
Technology Office 319	Mastic associated with Floor Tile		
Classroom 320	Mastic associated with Floor Tile		

# Edward T. Steel School: Asbestos Hazard Report

Classroom 320	Glue Dots associated with Blackboard		
Classroom 320	Floor Tile VAT 12" x 12"		
Storage Room adjacent to Elevator	Floor Tile VAT 12" x 12"		
Hallway from Classroom 304 to Storage Room 316	Transite associated with Fire Extinguisher Sill		
Hallway from Classroom 304 to Storage Room 316	Floor Tile VAT 12" x 12"		
Hallway from Men's Restroom to Classroom 305	Transite associated with Fire Extinguisher Sill		
Hallway from Men's Restroom to Classroom 305	Floor Tile VAT 12" x 12"		
Hallway from Classrooms 307 to 310	Transite associated with Fire Extinguisher Sill		
Hallway from Classrooms 307 to 310	Mastic associated with Floor Tile		
Hallway from Classrooms 307 to 310	Floor Tile VAT 12" x 12"		
Stairwell adjacent to Classroom 301	Floor Tile VAT 12" x 12"		
Stairwell adjacent to Storage Room 316	Floor Tile VAT 12" x 12"		
Stairwell adjacent to Storage Room 316	Transite associated with Window Sill		
Stairwell near Classroom 313	Floor Tile VAT 12" x 12"		
Stairwell near Classroom 313	Transite associated with Window Sill		
Stairwell to Roof between Mechanical Rooms	Floor Tile VAT 12" x 12"		