

Thomas K. Finletter School: Asbestos Hazard Report

The Philadelphia Regional Center for Children's Environmental Health has partnered with the Healthy Schools Initiative to analyze and report on public information regarding asbestos conditions in schools made available on the School District of Philadelphia's website.

This report is meant to communicate to parents, teachers, and staff the exposure risk at their school and help prioritize the removal of asbestos in high-risk exposure locations.

Our analysis is based on publicly available reports. We have not conducted inspections or verified the reports.

Key Findings:

- 82 teacher / student occupied spaces have **asbestos containing material (ACM)**
- 187 spaces contained friable ACM
- ★ 0 spaces had damaged ACM

Our Recommendations:

- The School District is required to regularly monitor the condition of their ACM by the EPA. As of the most recent report from September 2024, there is no damaged ACM in the school. We recommend frequent monitoring of all ACM, especially insulation of any kind, plaster ceilings, paint, and glazing which if damaged is considered friable as listed in Tables 1 and 3 of this report. Teachers, staff, and parents should report any damaged ACM to their principal immediately.



What is asbestos?

Asbestos is a fibrous material that is resistant to heat, water, and corrosion.

See this link for a comprehensive list: <https://prcceh.upenn.edu/asbestos>

Asbestos was used in materials in schools, including:

- Ceiling Tiles
- Floor Tiles
- Pipe Insulation
- Cement
- Paint and Caulk
- Soundproofing
- Fireproofing
- Plaster Materials

What are the health effects of asbestos?

No immediate health impacts are expected from asbestos exposure in schools. However, breathing asbestos fibers in schools may increase the risk of developing cancer many years from now.

Children are very active, breathing more air while running and playing. Children take more breaths per minute than adults and are lower to the ground where asbestos fibers may settle. This puts them at an increased risk for asbestos exposure.

How are damaged asbestos containing materials managed?

Asbestos can be removed. Sometimes damaged materials are managed in place by patching, encapsulating (using a specially formulated paint-like coating) or building an enclosure around damaged and/or accessible materials. All of these are forms of abatement.

The Environmental Protection Agency requires all remaining asbestos containing material to be inspected by the school district every six months. This is documented in an Asbestos Hazard Emergency Response Act Report (AHERA Report).

Are all asbestos containing materials of equal risk?

Some asbestos containing materials like ceiling and floor tiles have asbestos fibers imbedded in other materials. As long as they are not broken or damaged the asbestos fibers are not released into the air.

Some asbestos containing materials like insulation on pipe remains fibrous and can easily be released in the air when damaged.

Important Terms

Get to know these terms to make the most out of this report.

Damaged Asbestos Containing Material (ACM) can release asbestos fibers into the air.

Friable Materials can be reduced to a powder by applying hand pressure. **DO NOT TOUCH!**

Non-Friable materials are not easily damaged.

Significantly damaged materials are more than 10% damaged.

Abated ACM means repaired, removed, or reduced risk of exposure.

Detailed Review for Thomas K. Finletter School

This school has 91 spaces with asbestos containing materials. 82 of them are in teacher / student occupied spaces. The School District last inspected ACM in May 2024 and published the AHERA report in September 2024. No damaged ACM were reported on this AHERA report.



We recommend that the school district continue to frequently monitor friable asbestos containing materials for damage. Friable material found in the most recent report was insulation, plaster ceilings, paint, and glazing which if damaged is considered friable as listed in Tables 1 and 3 of this report.

Information Reviewed to Make this Report:

The 2024/25 AHERA report from the School District of Philadelphia was reviewed.

To see the most current information, scan these QR Codes. After scanning, search for your school.

School Districts of Philadelphia Asbestos Reports:



AHERA Reports are documents generated from EPA required asbestos inspections



Report what you see!

Parents and teachers should report hazardous conditions in schools on the Healthy Schools app.

Scan here to download the app:



Disclaimer:

This report analyzes custodial and mechanical spaces like boiler rooms **only** when ACM is significantly damaged (damage > 10%).

Questions?

Find more resources on our website!

prcceb.upenn.edu/asbestos

- Photo gallery of different types of damaged asbestos containing materials
- Guide to how we classify materials in schools
- Our analysis and reporting methodology
- What we do with the information in this report



Email us at prcceb@penmedicine.upenn.edu or call 215-573-9076

Table 1: Friable Asbestos Containing Materials Identified in the Main Building

NOTE: Friable materials can be reduced to a powder by applying hand pressure. *Do not touch it!* Damaged and significantly damaged friable materials readily release harmful asbestos fibers into the air.

Location	Friable Asbestos Containing Material	Reported as Damaged or Significantly Damaged? (Blank = No)
Classroom 101	Pipe Insulation 2-6 inch	
Classroom 101 Restroom	Pipe Insulation 2-6 inch	
Classroom 101 Restroom	Pipe Fitting Insulation	
Classroom 101 Restroom	Pipe Fitting Insulation	
Classroom 102	Pipe Insulation 2-6 inch	
Classroom 103	Pipe Insulation 2-6 inch	
Classroom 103 Closet	Pipe Insulation 2-6 inch	
Classroom 103 Closet	Pipe Fitting Insulation	
Girl's Restroom by Stairwell	Pipe Insulation 2-6 inch	
Girl's Restroom by Stairwell	Pipe Fitting Insulation	
Classroom 104	Pipe Insulation 2-6 inch	
Classroom 104 Closet by entrance	Pipe Insulation 2-6 inch	
Classroom 104 Closet by entrance	Pipe Fitting Insulation	
Classroom 105	Pipe Insulation 2-6 inch	
Classroom 106	Pipe Insulation 2-6 inch	
Classroom 107	Pipe Insulation 2-6 inch	
Classroom 107 Closet by entrance	Pipe Insulation 2-6 inch	
Classroom 107 Closet by entrance	Pipe Fitting Insulation	
Classroom 108	Pipe Insulation 2-6 inch	
Classroom 108	Pipe Fitting Insulation	

Thomas K. Finletter School: Asbestos Hazard Report



Classroom 108	Pipe Insulation 2-6 inch	
Classroom 108 Closet	Pipe Insulation 2-6 inch	
Classroom 108 Closet	Pipe Fitting Insulation	
Classroom 109	Pipe Insulation 2-6 inch	
Classroom 109	Pipe Fitting Insulation	
Classroom 109	Pipe Insulation 2-6 inch	
Classroom 110	Pipe Insulation 2-6 inch	
Classroom 110	Pipe Fitting Insulation	
Classroom 110	Pipe Insulation 2-6 inch	
Classroom 110 Closet	Pipe Fitting Insulation	
Room 111 Office	Pipe Insulation 2-6 inch	
Room 111 Office	Pipe Fitting Insulation	
Auditorium	Auditorium Plaster Ceiling	
Stage	Electrical Wire Wrap associated with Stage Light	
Pipe shaft in copier and Stationery Room in Main Office	Pipe Insulation >6 inches	
Principal's Office	Pipe Insulation 2-6 inch	
Principal's Office	Pipe Fitting Insulation	
Principal's Office	Pipe Insulation 2-6 inch	
Principal's Office Restroom	Pipe Insulation 2-6 inch	
Principal's Office Restroom	Pipe Fitting Insulation	
Staff Restroom near Room 101	Pipe Insulation 2-6 inch	
Staff Restroom near Room 101	Pipe Fitting Insulation	
Staff Restroom near Room 101	Pipe Insulation 2-6 inch	
Hallway at Rooms 104 to 107	Electrical Wire Wrap associated with Electrical Panel	
Hallway at Rooms 104 to 107	Pipe Insulation 2-6 inch	
Hallway at Rooms 104 to 107	Pipe Fitting Insulation	
Hallway at Rooms 108 to 110	Pipe Insulation 2-6 inch	
Hallway at Rooms 108 to 110	Pipe Fitting Insulation	
Hallway at Rooms 108 to 110	Pipe Insulation 2-6 inch	
Stairwell to Basement at Room 110	Pipe Insulation 2-6 inch	
Stairwell to Basement at Room 110	Pipe Fitting Insulation	
Classroom 201	Pipe Insulation 2-6 inch	
Classroom 201 Closet	Pipe Insulation 2-6 inch	
Classroom 201 Closet	Pipe Fitting Insulation	
Classroom 202	Pipe Insulation 2-6 inch	
Classroom 203	Pipe Insulation 2-6 inch	
Classroom 203 Closet	Pipe Insulation 2-6 inch	
Classroom 203 Closet	Pipe Fitting Insulation	
Girl's Restroom by Stairwell	Pipe Insulation 2-6 inch	
Girl's Restroom by Stairwell	Pipe Fitting Insulation	
Classroom 204	Pipe Insulation 2-6 inch	
Classroom 204 Closet by entrance	Pipe Insulation 2-6 inch	
Classroom 204 Closet by entrance	Pipe Fitting Insulation	
Classroom 205	Pipe Insulation 2-6 inch	
Classroom 206	Pipe Insulation 2-6 inch	
Classroom 207	Pipe Insulation 2-6 inch	
Classroom 207 Closet by entrance	Pipe Insulation 2-6 inch	
Classroom 207 Closet by entrance	Pipe Fitting Insulation	
Classroom 208	Pipe Insulation 2-6 inch	
Classroom 208	Pipe Fitting Insulation	
Classroom 208	Pipe Insulation 2-6 inch	
Classroom 208 Closet	Pipe Insulation 2-6 inch	
Classroom 208 Closet	Pipe Fitting Insulation	

Thomas K. Finletter School: Asbestos Hazard Report



Classroom 209	Pipe Insulation 2-6 inch	
Classroom 209	Pipe Fitting Insulation	
Classroom 209	Pipe Insulation 2-6 inch	
Classroom 210	Pipe Insulation 2-6 inch	
Classroom 210	Pipe Fitting Insulation	
Classroom 210	Pipe Insulation 2-6 inch	
Classroom 210 Closet	Pipe Insulation 2-6 inch	
Classroom 210 Closet	Pipe Fitting Insulation	
Room 210A Office	Pipe Insulation 2-6 inch	
Room 210A Office	Pipe Fitting Insulation	
Room 212 across from Room 207	Pipe Insulation 2-6 inch	
Room 212 across from Room 207	Pipe Fitting Insulation	
Room 200 -Health Service Office across from Room 202	Pipe Fitting Insulation	
Room 200 -Health Service Office across from Room 202	Pipe Insulation 2-6 inch	
Room 200 -Health Service Office across from Room 202	Pipe Insulation 2-6 inch	
Room 200 -Health Service Office across from Room 202	Pipe Fitting Insulation	
Old Kitchen in Room 200	Pipe Insulation 2-6 inch	
Old Kitchen in Room 200	Pipe Fitting Insulation	
Nurse's Office across from Room	Pipe Insulation 2-6 inch	
Nurse's Office across from Room	Pipe Fitting Insulation	
Nurse's Office across from Room	Pipe Insulation 2-6 inch	
Nurse's Office Restroom	Pipe Insulation 2-6 inch	
Nurse's Office Restroom	Pipe Fitting Insulation	
Vice Principal's Office	Pipe Insulation 2-6 inch	
Vice Principal's Office	Pipe Insulation 2-6 inch	
Vice Principal's Office	Pipe Fitting Insulation	
Staff Restroom inside Room 217 near Room 201	Pipe Insulation 2-6 inch	
Staff Restroom inside Room 217 near Room 201	Pipe Fitting Insulation	
Hallway at Rooms 204 to 207	Pipe Fitting Insulation	
Hallway at Rooms 204 to 207	Pipe Fitting Insulation	
Hallway at Rooms 204 to 207	Pipe Insulation 2-6 inch	
Hallway at Rooms 208 to 210	Pipe Insulation 2-6 inch	
Hallway at Rooms 208 to 210	Pipe Fitting Insulation	
Hallway at Rooms 208 to 210	Pipe Insulation 2-6 inch	
Stairway near Classroom 203	Pipe Insulation 2-6 inch	
Stairway near Classroom 203	Pipe Fitting Insulation	
Stairway near Classroom 208	Pipe Fitting Insulation	
Stairway near Classroom 208	Pipe Insulation 2-6 inch	
Classroom 301	Pipe Insulation 2-6 inch	
Classroom 301 Closet	Pipe Insulation 2-6 inch	
Classroom 303	Pipe Insulation 2-6 inch	
Classroom 303 Closet	Pipe Insulation 2-6 inch	
Classroom 304	Pipe Insulation 2-6 inch	
Girl's Restroom by Stairwell	Pipe Insulation 2-6 inch	
Classroom 305	Pipe Insulation 2-6 inch	
Classroom 306	Pipe Insulation 2-6 inch	
Classroom 307	Pipe Insulation 2-6 inch	
Boy's Restroom by Stairwell	Pipe Insulation 2-6 inch	
Classroom 308	Pipe Insulation 2-6 inch	
Classroom 308 Closet	Pipe Insulation 2-6 inch	
Classroom 309	Pipe Insulation 2-6 inch	

Thomas K. Finletter School: Asbestos Hazard Report

Classroom 310	Pipe Insulation 2-6 inch	
Classroom 310 Closet	Pipe Insulation 2-6 inch	
Room 210A Office	Pipe Insulation 2-6 inch	
Classroom 311	Pipe Insulation 2-6 inch	
Classroom 311	Pipe Insulation 2-6 inch	
Room 311 Restroom	Pipe Insulation 2-6 inch	
Classroom 311 Storage	Pipe Insulation 2-6 inch	
Hallway at Rooms 304 to 307	Pipe Insulation 2-6 inch	
Hallway at Rooms 304 to 307	Pipe Fitting Insulation	
Hallway at Rooms 304 to 307	Pipe Insulation 2-6 inch	
Hallway at Rooms 308 to 310	Pipe Insulation 2-6 inch	
Hallway at Rooms 308 to 310	Pipe Insulation 2-6 inch	
Stairway near Classroom 303	Pipe Insulation 2-6 inch	
Stairway near Classroom 308	Pipe Insulation 2-6 inch	
Storage at Stairwell by Girl's Restroom	Pipe Insulation 2-6 inch	
Storage at Stairwell by Girl's Restroom	Pipe Fitting Insulation	
Classroom 002 Storage	Pipe Insulation 2-6 inch	
Classroom 002 Storage	Pipe Fitting Insulation	
Security Office next to Boy's Restroom	Pipe Insulation 2-6 inch	
Security Office next to Boy's Restroom	Pipe Fitting Insulation	
Custodial Closet next to boy's Restroom	Pipe Insulation 2-6 inch	
Custodial Closet next to boy's Restroom	Pipe Fitting Insulation	
Girl's Restroom by Stairwell	Pipe Insulation 2-6 inch	
Girl's Restroom by Stairwell	Pipe Fitting Insulation	
Incinerator Closet	Incinerator Insulation	
Pump Room in Boiler Room	Pipe Insulation 2-6 inch	
Pump Room in Boiler Room	Pipe Fitting Insulation	
Fan Room in Boiler Room	Glazing associated with Door, Air Wash	
Fan Room in Boiler Room	Glazing associated with Door, Air Wash	
Fan Room in Boiler Room	Seam Packing associated with Plenum, Supply	
Fan Room in Boiler Room	Paint associated with Fan Unit, Interior	
Fan Room in Boiler Room	Paint associated with Fan Unit, Interior	
Fan Room in Boiler Room	Paint associated with Fan Unit, Interior	
Fan Room in Boiler Room	Paint associated with Fan Unit, Interior	
Boiler Room and Vestibule to Mechanical Rooms 9, 10 and 11	Incinerator Insulation	
Boiler Room and Vestibule to Mechanical Rooms 9, 10 and 11	Interior Boiler Insulation	
Boiler Room and Vestibule to Mechanical Rooms 9, 10 and 11	Pipe Insulation >6 inches	
Boiler Room and Vestibule to Mechanical Rooms 9, 10 and 11	Pipe Insulation 2-6 inch	
Boiler Room and Vestibule to Mechanical Rooms 9, 10 and 11	Pipe Fitting Insulation	

Thomas K. Finletter School: Asbestos Hazard Report

Boiler Room and Vestibule to Mechanical Rooms 9, 10 and 11	Duct Insulation	
Classroom 002 next to Girl's Restroom	Pipe Insulation 2-6 inch	
Classroom 002 next to Girl's Restroom	Pipe Fitting Insulation	
Music Room	Pipe Insulation 2-6 inch	
Music Room	Pipe Fitting Insulation	
Music Room	Pipe Insulation 2-6 inch	
Music Room	Pipe Fitting Insulation	
Kitchen	Pipe Fitting Insulation	
Kitchen	Pipe Insulation 2-6 inch	
Kitchen	Pipe Insulation 2-6 inch	
Kitchen	Pipe Fitting Insulation	
Cafeteria/Gym	Pipe Insulation 2-6 inch	
Cafeteria/Gym	Pipe Fitting Insulation	
Art Room	Pipe Insulation 2-6 inch	
Art Room	Pipe Fitting Insulation	
Boy's Restroom by Stairwell	Pipe Insulation 2-6 inch	
Boy's Restroom by Stairwell	Pipe Fitting Insulation	
Hallway at Kitchen	Pipe Fitting Insulation	
Hallway at Boy's Restroom	Pipe Insulation 2-6 inch	
Hallway at Boy's Restroom	Pipe Fitting Insulation	
Exit hallway in Cafe/Gym	Duct Insulation	
Modular Classroom Storage	Sheetrock/Joint Compound Wall	

Table 2: Non-Friable Asbestos Containing Materials Identified in the Main Building

NOTE: Significantly Damaged non-friable materials (damage \geq 10% of the material) can release harmful asbestos fibers into the air.

Location	Material Name	Reported as Damaged or Significantly Damaged?
Classroom 101	Glue Dots associated with Blackboard	
Classroom 101	Floor Tile VAT 12" x 12"	
Classroom 101	Floor Tile VAT 12" x 12"	
Classroom 101 Air Shaft 2	Floor Tile VAT 12" x 12"	
Classroom 101 Restroom	Floor Tile VAT 12" x 12"	
Classroom 101 Restroom	Floor Tile VAT 12" x 12"	
Classroom 101 Restroom	Floor Tile VAT 12" x 12"	
Classroom 101 Restroom	Floor Tile VAT 12" x 12"	
Classroom 101 Closet	Floor Tile VAT 12" x 12"	
Classroom 101 Closet	Floor Tile VAT 12" x 12"	
Classroom 101 Closet near entrance	Floor Tile VAT 12" x 12"	
Classroom 101 Closet near entrance	Floor Tile VAT 12" x 12"	
Classroom 102	Floor Tile VAT 12" x 12"	
Classroom 102	Sink Undercoat Mastic	
Classroom 102	Glue Dots associated with Blackboard	
Classroom 102 Air Shaft 1	Floor Tile VAT 12" x 12"	

Thomas K. Finletter School: Asbestos Hazard Report

Classroom 102 Closet next to restroom	Floor Tile VAT 9" x 9"	
Classroom 103	Glue Dots associated with Blackboard	
Classroom 103	Floor Tile VAT 12" x 12"	
Classroom 103	Floor Tile VAT 12" x 12"	
Classroom 103 Air Shaft 1	Floor Tile VAT 12" x 12"	
Classroom 103 Closet	Floor Tile VAT 12" x 12"	
Classroom 104	Glue Dots associated with Blackboard	
Classroom 105	Glue Dots associated with Blackboard	
Classroom 106	Glue Dots associated with Blackboard	
Classroom 107	Glue Dots associated with Blackboard	
Classroom 107 Closet by entrance	Fire Stop	
Classroom 107 Closet	Fire Stop	
Classroom 108	Glue Dots associated with Blackboard	
Classroom 109	Glue Dots associated with Blackboard	
Classroom 110	Glue Dots associated with Blackboard	
Room 111 Office	Floor Tile VAT 12" x 12"	
Room 111 Office	Floor Tile VAT 12" x 12"	
Main Office	Floor Tile VAT 12" x 12"	
Copier and Stationery Room in Main Office	Fire Stop	
Principal's Office	Mastic associated with Floor Tile	
Principal's Office Storage	Floor Tile VAT 12" x 12"	
Principal's Office Restroom	Mastic associated with Floor Tile	
Staff Restroom near Room 101	Floor Tile VAT 12" x 12"	
Hallway at Rooms 108 to 110	Fire Stop	
Classroom 201	Glue Dots associated with Blackboard	
Classroom 202	Glue Dots associated with Blackboard	
Classroom 203	Glue Dots associated with Blackboard	
Classroom 204	Glue Dots associated with Blackboard	
Classroom 205	Glue Dots associated with Blackboard	
Classroom 206	Glue Dots associated with Blackboard	
Classroom 207	Partition Room Dividers	
Classroom 207	Glue Dots associated with Blackboard	
Classroom 208	Glue Dots associated with Blackboard	
Classroom 209	Glue Dots associated with Blackboard	

Thomas K. Finletter School: Asbestos Hazard Report

Classroom 210	Glue Dots associated with Blackboard	
Old Kitchen in Room 200	Floor Tile VAT 12" x 12"	
Nurse's Office across from Room	Floor Tile VAT 12" x 12"	
Nurse's Office Restroom	Floor Tile VAT 12" x 12"	
Vice Principal's Office	Floor Tile VAT 12" x 12"	
Classroom 301	Glue Dots associated with Blackboard	
Classroom 302	Glue Dots associated with Blackboard	
Classroom 303	Glue Dots associated with Blackboard	
Classroom 304	Glue Dots associated with Blackboard	
Girl's Restroom by Stairwell	Fire Stop	
Classroom 305	Glue Dots associated with Blackboard	
Classroom 306	Glue Dots associated with Blackboard	
Classroom 307	Glue Dots associated with Blackboard	
Classroom 308	Glue Dots associated with Blackboard	
Classroom 309	Glue Dots associated with Blackboard	
Classroom 310	Glue Dots associated with Blackboard	
Room 312 Office	Glue Dots associated with Blackboard	
Classroom 311	Glue Dots associated with Blackboard	
Copier Room at Room 301	Floor Tile VAT 12" x 12"	
Room 311 Restroom	Floor Tile VAT 12" x 12"	
Hallway at Rooms 308 to 310	Fire Stop	
Office inside Cafeteria/Gym	Floor Tile VAT 9" x 9"	
Storage Room inside Cafeteria/Gym beside Office	Floor Tile VAT 12" x 12"	
Storage Room inside Cafeteria/Gym Under Stairwell S7	Floor Tile VAT 12" x 12"	
Art Room Coat Closet	Mastic associated with Floor Tile	
Art Room Coat Closet	Floor Tile VAT 12" x 12"	
Art Room Storage connecting Security Office	Fire Stop	
Art Room Storage connecting Security Office	Floor Tile VAT 12" x 12"	
Security Office next to Boy's Restroom	Mastic associated with Cove Base	
Pump Room in Boiler Room	Fire Stop	
Pump Room in Boiler Room	Transite associated with Electrical Panel	
Fan Room in Boiler Room	Caulk associated with Air Wash Chamber	
Fan Room in Boiler Room	Caulk associated with Intake Chamber	

Thomas K. Finletter School: Asbestos Hazard Report

Boiler Room and Vestibule to Mechanical Rooms 9, 10 and 11	Fire Stop	
Boiler Room and Vestibule to Mechanical Rooms 9, 10 and 11	Sectional Boilers	
Classroom 002 next to Girl's Restroom	Glue Dots associated with Blackboard	
Art Room	Glue Dots associated with Ceiling Tile 1' x 1'	
Boy's Restroom by Stairwell	Transite	
Building Exterior (Main Building)	Caulk associated with Door Frame, Metal	
Rooftop above Third Floor Attic	Tar associated with Roof Flashing	
Building Exterior (Modular Building)	Caulk associated with Window Unit	
Modular Classroom Restroom	Expansion Seam Caulking	
Modular Classroom Storage	Floor Tile VAT 9" x 9"	
Modular Classroom Storage	Expansion Seam Caulking	
Modular Classroom	Expansion Seam Caulking	
Modular Classroom	Floor Tile VAT 9" x 9"	
Modular Classroom	Expansion Seam Caulking	

Table 3: Friable Asbestos Containing Materials Identified in the Little School House

NOTE: Friable materials can be reduced to a powder by applying hand pressure. *Do not touch it!* Damaged and significantly damaged friable materials readily release harmful asbestos fibers into the air.

Location	Material Name	Reported as Damaged or Significantly Damaged?
Middle Storage Room across from Multipurpose Room	Seam Packing associated with Ductwork, Interior	

Table 4: Non-Friable Asbestos Containing Materials Identified in the Little School House

NOTE: Significantly Damaged non-friable materials (damage ≥ 10% of the material) can release harmful asbestos fibers into the air.

Location	Non Friable Asbestos Containing Material	Reported as Damaged or Significantly Damaged? (Blank = No)	Abatement scheduled since the inspection? (Blank = No)
Storage Room next to Building Engineer's Office	Expansion Seam Caulking		
Boiler Room	Expansion Seam Caulking		
Cafeteria Storage Room next to Kitchen	Floor Tile VAT 12" x 12"		
Hallway from Classroom K1 to Classroom A12	Floor Tile VAT 12" x 12"		
Hallway from Building Engineer's Office to Boiler Room	Expansion Seam Caulking		
Classroom K4 Restroom	Fire Stop		
Kitchen	Expansion Seam Caulking		
Kitchen Storage Room	Fire Stop		
Laundry Room next to Women's Restroom	Floor Tile VAT 12" x 12"		
Lobby Area next to Main Office	Floor Tile VAT 12" x 12"		
Teacher' Lounge/Large Storage Room between Middle Storage Room and the Building Engineer's Area	Floor Tile VAT 12" x 12"		