

James Blaine School: Asbestos Hazard Report

The Philadelphia Regional Center for Children's Environmental Health has partnered with the Healthy Schools Initiative to analyze and report on public information regarding asbestos conditions in schools made available on the School District of Philadelphia's website.

This report is meant to communicate to parents, teachers, and staff the exposure risk at their school and help prioritize the removal of asbestos in high-risk exposure locations.

Our analysis is based on publicly available reports. We have not conducted inspections or verified the reports.

Key Findings:

- 86 teacher / student occupied spaces have asbestos containing material (ACM)
- 2 spaces had damaged ACM
- 82 spaces contained friable ACM
- **No damaged** materials were scheduled to be abated

Our Recommendations:

- The School District has not scheduled abatement for either of the two damaged ACM identified during their latest inspection in June 2025. This non-friable ACM was identified as significantly damaged in Nov 2024 and was still reported to be damaged in Jun 2025. We recommend this material be abated immediately.



What is asbestos?

Asbestos is a fibrous material that is resistant to heat, water, and corrosion.

See this link for a comprehensive list: <https://prcceh.upenn.edu/asbestos>

Asbestos was used in materials in schools, including:

- Ceiling Tiles
- Floor Tiles
- Pipe Insulation
- Cement
- Paint and Caulk
- Soundproofing
- Fireproofing
- Plaster Materials

What are the health effects of asbestos?

No immediate health impacts are expected from asbestos exposure in schools. However, breathing asbestos fibers in schools may increase the risk of developing cancer many years from now.

Children are very active, breathing more air while running and playing. Children take more breaths per minute than adults and are lower to the ground where asbestos fibers may settle. This puts them at an increased risk for asbestos exposure.

How are damaged asbestos containing materials managed?

Asbestos can be removed. Sometimes damaged materials are managed in place by patching, encapsulating (using a specially formulated paint-like coating) or building an enclosure around damaged and/or accessible materials. All of these are forms of abatement.

The Environmental Protection Agency requires all remaining asbestos containing material to be inspected by the school district every six months. This is documented in an Asbestos Hazard Emergency Response Act Report (AHERA Report).

Are all asbestos containing materials of equal risk?

Some asbestos containing materials like ceiling and floor tiles have asbestos fibers imbedded in other materials. As long as they are not broken or damaged the asbestos fibers are not released into the air.

Some asbestos containing materials like insulation on pipe remains fibrous and can easily be released in the air when damaged.

Important Terms

Get to know these terms to make the most out of this report.

Damaged Asbestos Containing Material (ACM) can release asbestos fibers into the air.

Friable Materials can be reduced to a powder by applying hand pressure. **DO NOT TOUCH!**

Non-Friable materials are not easily damaged.

Significantly damaged materials are more than 10% damaged.

Abated ACM means repaired, removed, or reduced risk of exposure.

Detailed Review for James Blaine School

This school has 98 spaces with asbestos containing materials. 86 of them are in teacher / student occupied spaces. The School District last inspected ACM in Jun 2025 and published the AHERA report in Jun 2025. The School District has not scheduled abatement for either of the two damaged ACM identified during their latest inspection in Jun 2025.



The significantly damaged non-friable asbestos containing floor tiles in both the classroom 103 closet B (right entry) and in the closet near library 104 across from the custodial closet were identified as significantly damaged in Nov 2024 and were scheduled for total removal by Apr 2025. These materials were identified as still damaged in the inspection conducted in Jun 2025. A list of all the ACM in the school and their damage/abatement schedule can be found in the tables at the end of this report.

Information Reviewed to Make this Report:

The 2024/25 AHERA report from the School District of Philadelphia, and asbestos abatement notifications from the Air Management Services Online Portal.

Not included in this report are planned repairs to damaged asbestos materials that have not been uploaded to the Air Management Services website or any updated after September 26, 2025. To see the most current information, scan these QR Codes. After scanning, search for your school.



Report what you see!

Parents and teachers should report hazardous conditions in schools on the Healthy Schools app.

Scan here to
download the app:



School Districts of Philadelphia Asbestos Reports:



AHERA Reports are documents generated from EPA required asbestos inspections

Office of the Controller Asbestos Project:



Asbestos
abatement
notification
forms

Questions?

Find more resources on our website!

- Photo gallery of different types of damaged asbestos containing materials
- Guide to how we classify materials in schools
- Our analysis and reporting methodology
- What we do with the information in this report

prcceh.upenn.edu/asbestos



Email us at prcceh@penntestmed.upenn.edu or call 215-573-9076

Table 1: Friable Asbestos Containing Materials Identified

NOTE: Friable materials can be reduced to a powder by applying hand pressure.
Do not touch it! Damaged and significantly damaged friable materials readily release harmful asbestos fibers into the air.

Location	Material Name	Reported as Damaged or Significantly Damaged? (Blank = No)	Abatement scheduled since the inspection? (Blank = No)
Classroom 100 Coat Room	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 100 Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 100 Closet B (Adjacent Restroom)	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 101 Coat Room	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 101 Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 101 Closet C (Adjacent Restroom)	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 102 Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 102 Coat Room	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 102 Storage Closet	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 103 Coat Room	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 103 Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		

James Blaine: Asbestos Hazard Report

Classroom 103 Storage Closet	Textured Ceiling Paint associated with Ceiling, Concrete		
Closet Near To Library 104 Across From Custodial Closet	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 105	Textured Ceiling Paint associated with Ceiling, Concrete		
Book Storage Room 105A	Textured Ceiling Paint associated with Ceiling, Concrete		
Custodial Closet across from Library/IMC 106	Textured Ceiling Paint associated with Ceiling, Concrete		
Library Classroom Storage Closet	Textured Ceiling Paint associated with Ceiling, Concrete		
Closet inside Library Classroom Storage	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 107	Glazing associated with Window Unit		
Classroom 107	Sheetrock/Joint Compound Wall		
Classroom 107	Textured Ceiling Paint associated with Ceiling, Concrete		
Women's Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Receiving/Trash Room	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 107 Restroom	Sheetrock/Joint Compound Wall		
Classroom 107 Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Teacher's Lounge	Sheetrock/Joint Compound Wall		
Teacher's Lounge	Glazing associated with Window Unit		
Teacher's Lounge	Textured Ceiling Paint associated with Ceiling, Concrete		
Teacher's Lounge Restroom	Sheetrock/Joint Compound Wall		
Teacher's Lounge Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Office 109	Glazing associated with Window Unit		
Nurse's Office Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Main Office Closet B (Adjacent Principals Office)	Textured Ceiling Paint associated with Ceiling, Concrete		
Principal's Office Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Principal's Office Storage Closet	Textured Ceiling Paint associated with Ceiling, Concrete		
Men's Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Men's Restroom Foyer	Textured Ceiling Paint associated with Ceiling, Concrete		
Cafetorium	Textured Ceiling Paint associated with Ceiling, Concrete		
Physical Education Office	Textured Ceiling Paint associated with Ceiling, Concrete		
Physical Education Office Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Cafeteria Storage	Textured Ceiling Paint associated with Ceiling, Concrete		
Cafeteria Girl's Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Cafeteria Boy's Restroom	Heat Shield Insulation associated with Radiator		

James Blaine: Asbestos Hazard Report

Technology Office 099	Textured Ceiling Paint associated with Ceiling, Concrete		
Pipe Chase in Hallway from Classroom 100 to 106	Vapor Barrier		
Stairwell #3	Textured Ceiling Paint associated with Ceiling, Concrete		
Stairwell #1	Textured Ceiling Paint associated with Ceiling, Concrete		
Stairwell #2	Textured Ceiling Paint associated with Ceiling, Concrete		
Exit Foyer adjacent Auditorium	Vapor Barrier		
Classroom 101/103 Exit Foyer	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 200	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 201	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 202	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 203	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 204	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 205	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 206	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 207	Textured Ceiling Paint associated with Ceiling, Concrete		
Boy's Restroom Pipe Chase	Vapor Barrier		
Classroom 207 Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Men's Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 208	Textured Ceiling Paint associated with Ceiling, Concrete		
Women's Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 209	Textured Ceiling Paint associated with Ceiling, Concrete		
Storage Room 209A (server room/book closet)	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 210	Textured Ceiling Paint associated with Ceiling, Concrete		
Custodial Service Closet	Textured Ceiling Paint associated with Ceiling, Concrete		
Book Storage Room next to Elevator	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 212	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 213	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 214	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 215	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 216	Textured Ceiling Paint associated with Ceiling, Concrete		

James Blaine: Asbestos Hazard Report

Hallway from Classrooms 200 to 209	Textured Ceiling Paint associated with Ceiling, Concrete		
Hallway from Classrooms 200 to 209 Air Shaft	Vapor Barrier		
Hallway from Classrooms 210 to 216	Textured Ceiling Paint associated with Ceiling, Concrete		
Stairwell #1	Textured Ceiling Paint associated with Ceiling, Concrete		
Stairwell #3	Textured Ceiling Paint associated with Ceiling, Concrete		
Stairwell #2	Textured Ceiling Paint associated with Ceiling, Concrete		
Stairwell #2 Pipe Chase	Vapor Barrier		
Classroom 300	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 304	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 306	Textured Ceiling Paint associated with Ceiling, Concrete		
Boy's Restroom Pipe Chase	Vapor Barrier		
Men's Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 308	Textured Ceiling Paint associated with Ceiling, Concrete		
Women's Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 309	Textured Ceiling Paint associated with Ceiling, Concrete		
Book Storage Room 309A	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 310	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 311	Textured Ceiling Paint associated with Ceiling, Concrete		
Storage Room 311A	Textured Ceiling Paint associated with Ceiling, Concrete		
Slop Closet 311B	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 312	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 313	Textured Ceiling Paint associated with Ceiling, Concrete		
Roof Access	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 314	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 315	Textured Ceiling Paint associated with Ceiling, Concrete		
Classroom 316	Textured Ceiling Paint associated with Ceiling, Concrete		
Hallway from Classrooms 310 to 316	Textured Ceiling Paint associated with Ceiling, Concrete		
Hallway from Classrooms 300 to 309	Textured Ceiling Paint associated with Ceiling, Concrete		
Stairwell #1	Textured Ceiling Paint associated with Ceiling, Concrete		
Stairwell #3	Textured Ceiling Paint associated with Ceiling, Concrete		

James Blaine: Asbestos Hazard Report

Stairwell #2	Textured Ceiling Paint associated with Ceiling, Concrete		
Pipe Chase in Stairwell #2	Vapor Barrier		
Building Engineer's Office Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Building Engineer's Office Restroom	Paint associated with Wall, CMU		
Custodial Closet Next to Building Engineer's Office	Paint associated with Wall, CMU		
Custodial Closet Next to Building Engineer's Office	Textured Ceiling Paint associated with Ceiling, Concrete		
Boiler Room	Paint associated with Wall, CMU		
Storage Room B-2	Paint associated with Wall, CMU		
Storage Room B-3	Paint associated with Wall, CMU		
Storage Room B-3	Textured Ceiling Paint associated with Ceiling, Concrete		
Building Engineer's Office	Paint associated with Wall, CMU		
Building Engineer's Office	Textured Ceiling Paint associated with Ceiling, Concrete		
Staff Restroom	Paint associated with Wall, CMU		
Staff Restroom	Textured Ceiling Paint associated with Ceiling, Concrete		
Elevator Equipment Room	Paint associated with Wall, CMU		
Elevator Equipment Room	Textured Ceiling Paint associated with Ceiling, Concrete		
Storage Room B-1	Textured Ceiling Paint associated with Ceiling, Concrete		
Basement Hallway	Paint associated with Wall, CMU		
Basement Hallway	Textured Ceiling Paint associated with Ceiling, Concrete		
Stairs to Basement	Paint associated with Wall, CMU		
Stairs to Basement	Textured Ceiling Paint associated with Ceiling, Concrete		
Stairwell Next to Boiler Room	Paint associated with Wall, CMU		

Table 2: Non-Friable Asbestos Containing Materials Identified

NOTE: Significantly Damaged non-friable materials (damage \geq 10% of the material) can release harmful asbestos fibers into the air.

Location	Material Name	Reported as Damaged or Significantly Damaged? (Blank = No)	Abatement scheduled since the inspection? (Blank = No)
Classroom 100	Sink Undercoat Mastic		
Classroom 100	Floor Tile VAT 12" x 12"		
Classroom 100	Transite associated with Ceiling, Closet		
Classroom 100	Transite associated with Window Sill		
Classroom 100 Coat Room	Mastic associated with Floor Tile		
Classroom 100 Coat Room	Floor Tile VAT 9" x 9"		
Classroom 100 Closet B (Adjacent Restroom)	Mastic associated with Floor Tile		
Classroom 100 Closet B (Adjacent Restroom)	Floor Tile VAT 9" x 9"		

James Blaine: Asbestos Hazard Report

Classroom 100 Closet A (Adjacent Entrance)	Mastic associated with Floor Tile		
Classroom 100 Closet A (Adjacent Entrance)	Floor Tile VAT 12" x 12"		
Classroom 101	Transite associated with Ceiling, Closet		
Classroom 101	Mastic associated with Floor Tile		
Classroom 101	Floor Tile VAT 12" x 12"		
Classroom 101 Closet B (Adjacent Closet A)	Mastic associated with Floor Tile		
Classroom 101 Closet B (Adjacent Closet A)	Floor Tile VAT 12" x 12"		
Classroom 101 Closet C (Adjacent Restroom)	Mastic associated with Floor Tile		
Classroom 101 Closet C (Adjacent Restroom)	Floor Tile VAT 9" x 9"		
Classroom 102	Mastic associated with Floor Tile		
Classroom 102	Transite associated with Ceiling, Closet		
Classroom 102	Sink Undercoat Mastic		
Classroom 102	Transite associated with Window Sill		
Classroom 102	Floor Tile VAT 12" x 12"		
Classroom 102 Coat Room	Mastic associated with Floor Tile		
Classroom 102 Coat Room	Floor Tile VAT 9" x 9"		
Classroom 102 Closet A (Left Entrance)	Mastic associated with Floor Tile		
Classroom 102 Closet A (Left Entrance)	Floor Tile VAT 12" x 12"		
Classroom 102 Closet B (Right Entry)	Mastic associated with Floor Tile		
Classroom 102 Closet B (Right Entry)	Floor Tile VAT 12" x 12"		
Classroom 102 Storage Closet	Mastic associated with Floor Tile		
Classroom 102 Storage Closet	Floor Tile VAT 9" x 9"		
Classroom 103	Transite associated with Window Sill		
Classroom 103 Coat Room	Mastic associated with Floor Tile		
Classroom 103 Coat Room	Floor Tile VAT 9" x 9"		
Classroom 103 Closet A (Left Entry)	Mastic associated with Floor Tile		
Classroom 103 Closet A (Left Entry)	Floor Tile VAT 12" x 12"		
Classroom 103 Closet B (Right Entry)	Mastic associated with Floor Tile		
Classroom 103 Closet B (Right Entry)	Floor Tile VAT 9" x 9"	Significantly damaged. Previously reported as damaged in Nov 2024 and still damaged in Jun 2025.	
Classroom 103 Storage Closet	Mastic associated with Floor Tile		
Classroom 103 Storage Closet	Floor Tile VAT 9" x 9"		
Library Classroom 104 Closet B	Mastic associated with Floor Tile		
Library Classroom 104 Closet B	Floor Tile VAT 12" x 12"		
Closet Near To Library 104 Across From Custodial Closet	Mastic associated with Floor Tile		
Closet Near To Library 104 Across From Custodial Closet	Floor Tile VAT 9" x 9"	Significantly damaged. Previously reported as damaged in Nov 2024 and still damaged in Jun 2025.	
Classroom 105	Mastic associated with Floor Tile		
Classroom 105	Transite associated with Ceiling, Closet		
Classroom 105	Transite associated with Window Sill		
Classroom 105	Floor Tile VAT 9" x 9"		
Classroom 105 Closet A (Left)	Mastic associated with Floor Tile		

James Blaine: Asbestos Hazard Report

Classroom 105 Closet A (Left)	Floor Tile VAT 12" x 12"		
Custodial Closet across from Library/IMC 106	Mastic associated with Floor Tile		
Custodial Closet across from Library/IMC 106	Linoleum		
Custodial Closet across from Library/IMC 106	Floor Tile VAT 12" x 12"		
Classroom 105 Closet B (Middle)	Mastic associated with Floor Tile		
Classroom 105 Closet B (Middle)	Floor Tile VAT 9" x 9"		
Classroom 105 Closet C (Right)	Mastic associated with Floor Tile		
Classroom 105 Closet C (Right)	Floor Tile VAT 9" x 9"		
Library Classroom 104/106	Mastic associated with Floor Tile		
Library Classroom 104/106	Transite associated with Ceiling, Closet		
Library Classroom 104/106	Transite associated with Window Sill		
Library Classroom 104/106	Floor Tile VAT 12" x 12"		
Library Classroom 104/106	Floor Tile VAT 9" x 9"		
Library Classroom 106 Closet A	Mastic associated with Floor Tile		
Library Classroom 106 Closet A	Floor Tile VAT 12" x 12"		
Library Classroom 106 Closet B	Mastic associated with Floor Tile		
Library Classroom 106 Closet B	Floor Tile VAT 12" x 12"		
Library Classroom 106 Closet B	Floor Tile VAT 9" x 9"		
Library Classroom Storage Closet	Mastic associated with Floor Tile		
Library Classroom Storage Closet	Floor Tile VAT 12" x 12"		
Closet inside Library Classroom Storage	Mastic associated with Floor Tile		
Closet inside Library Classroom Storage	Floor Tile VAT 9" x 9"		
Classroom 107	Mastic associated with Floor Tile		
Classroom 107	Transite associated with Ceiling, Closet		
Classroom 107	Transite associated with Window Sill		
Classroom 107	Floor Tile VAT 12" x 12"		
Classroom 107	Floor Tile VAT 9" x 9"		
Classroom 107 Closet A	Mastic associated with Floor Tile		
Classroom 107 Closet A	Floor Tile VAT 9" x 9"		
Classroom 107 Closet B	Mastic associated with Floor Tile		
Classroom 107 Closet B	Floor Tile VAT 9" x 9"		
Women's Restroom	Mastic associated with Floor Tile		
Women's Restroom	Floor Tile VAT 12" x 12"		
Women's Restroom	Floor Tile VAT 9" x 9"		
Women's Restroom	Floor Tile VAT 9" x 9"		
Receiving/Trash Room	Mastic associated with Floor Tile		
Receiving/Trash Room	Floor Tile VAT 12" x 12"		
Teacher's Lounge	Mastic associated with Floor Tile		
Teacher's Lounge	Transite associated with Ceiling, Closet		
Teacher's Lounge	Floor Tile VAT 12" x 12"		
Teacher's Lounge	Transite associated with Window Sill		
Office 109	Mastic associated with Floor Tile		
Office 109	Transite associated with Ceiling, Closet		
Office 109	Transite associated with Window Sill		
Office 109	Floor Tile VAT 9" x 9"		
Nurse's Office	Mastic associated with Floor Tile		
Nurse's Office	Floor Tile VAT 9" x 9"		
Nurse's Office Restroom	Mastic associated with Floor Tile		
Nurse's Office Restroom	Floor Tile VAT 9" x 9"		
Nurse's Office Closet	Mastic associated with Floor Tile		
Nurse's Office Closet	Floor Tile VAT 9" x 9"		
Office 111	Mastic associated with Floor Tile		

James Blaine: Asbestos Hazard Report

Office 111	Floor Tile VAT 12" x 12"		
Main Office Closet A (Opposite Offices)	Mastic associated with Floor Tile		
Main Office Closet A (Opposite Offices)	Floor Tile VAT 12" x 12"		
Main Office Closet A (Opposite Offices)	Floor Tile VAT 9" x 9"		
Main Office Closet B (Adjacent Principals Office)	Mastic associated with Floor Tile		
Main Office Closet B (Adjacent Principals Office)	Floor Tile VAT 9" x 9"		
Main Office Closet C (Adjacent Nurses Office)	Mastic associated with Floor Tile		
Main Office Closet C (Adjacent Nurses Office)	Floor Tile VAT 9" x 9"		
Principal's Office	Mastic associated with Floor Tile		
Principal's Office	Floor Tile VAT 12" x 12"		
Principal's Office Restroom	Mastic associated with Floor Tile		
Principal's Office Restroom	Floor Tile VAT 9" x 9"		
Principal's Office Storage Closet	Mastic associated with Floor Tile		
Principal's Office Storage Closet	Floor Tile VAT 9" x 9"		
Men's Restroom	Mastic associated with Floor Tile		
Men's Restroom	Floor Tile VAT 12" x 12"		
Men's Restroom Foyer	Mastic associated with Floor Tile		
Men's Restroom Foyer	Floor Tile VAT 12" x 12"		
Auditorium	Mastic associated with Floor Tile		
Auditorium	Floor Tile VAT 12" x 12"		
Auditorium	Floor Tile VAT 9" x 9"		
Stage	Mastic associated with Floor Tile		
Stage	Floor Tile VAT 9" x 9"		
Cafetorium	Mastic associated with Floor Tile		
Cafetorium	Transite associated with Fire Extinguisher Sill		
Cafetorium	Floor Tile VAT 12" x 12"		
Mower Storage Room	Mastic associated with Floor Tile		
Physical Education Office	Transite associated with Window Sill		
Physical Education Office	Mastic associated with Floor Tile		
Physical Education Office	Floor Tile VAT 12" x 12"		
Physical Education Office Restroom	Mastic associated with Floor Tile		
Physical Education Office Restroom	Floor Tile VAT 12" x 12"		
Cafeteria Storage	Mastic associated with Floor Tile		
Cafeteria Storage	Floor Tile VAT 12" x 12"		
Kitchen Storage	Mastic associated with Floor Tile		
Kitchen Storage	Floor Tile VAT 12" x 12"		
Cafeteria Girl's Restroom	Transite associated with Window Sill		
Cafeteria Boy's Restroom	Transite associated with Window Sill		
Kitchen	Mastic associated with Floor Tile		
Kitchen	Floor Tile VAT 12" x 12"		
Technology Office 099	Mastic associated with Floor Tile		
Technology Office 099	Transite associated with Ceiling, Closet		
Technology Office 099	Transite associated with Window Sill		
Technology Office 099	Floor Tile VAT 9" x 9"		
Classroom 099 Closet A	Mastic associated with Floor Tile		
Classroom 099 Closet A	Floor Tile VAT 9" x 9"		
Hallway at Auditorium	Mastic associated with Floor Tile		
Hallway at Auditorium	Floor Tile VAT 12" x 12"		
Hallway at Auditorium	Floor Tile VAT 9" x 9"		
Hallway from Classrooms 107 to 108	Transite associated with Fire Extinguisher Sill		

James Blaine: Asbestos Hazard Report

Hallway from Classrooms 107 to 108	Mastic associated with Floor Tile		
Hallway from Classrooms 107 to 108	Floor Tile VAT 12" x 12"		
Hallway from Classrooms 107 to 108	Floor Tile VAT 9" x 9"		
Hallway from Classrooms 100 to 106	Transite associated with Fire Extinguisher Sill		
Hallway from Classrooms 100 to 106	Mastic associated with Floor Tile		
Hallway from Classrooms 100 to 106	Floor Tile VAT 12" x 12"		
Hallway from Classrooms 100 to 106	Transite associated with Window Sill		
Hallway from Classrooms 100 to 106	Floor Tile VAT 9" x 9"		
Hallway between Auditorium and Cafeteria	Mastic associated with Floor Tile		
Hallway between Auditorium and Cafeteria	Floor Tile VAT 12" x 12"		
Hallway between Auditorium and Cafeteria	Floor Tile VAT 9" x 9"		
Stairwell #1	Mastic associated with Floor Tile		
Stairwell #1	Floor Tile VAT 9" x 9"		
Stairwell #2	Mastic associated with Floor Tile		
Stairwell #2	Transite associated with Window Sill		
Stairwell #2	Floor Tile VAT 12" x 12"		
Main Entrance Stairs	Floor Tile VAT 12" x 12"		
Exit Foyer adjacent Auditorium	Mastic associated with Floor Tile		
Exit Foyer adjacent Auditorium	Floor Tile VAT 12" x 12"		
Exit Foyer adjacent Teacher's Lounge	Mastic associated with Floor Tile		
Exit Foyer adjacent Teacher's Lounge	Floor Tile VAT 12" x 12"		
Exit Foyer adjacent Teacher's Lounge	Floor Tile VAT 12" x 12"		
Exit Foyer adjacent Teacher's Lounge	Floor Tile VAT 9" x 9"		
Classroom 101/103 Exit Foyer	Mastic associated with Floor Tile		
Classroom 101/103 Exit Foyer	Floor Tile VAT 12" x 12"		
Classroom 101/103 Exit Foyer	Floor Tile VAT 9" x 9"		
Classroom 200	Transite associated with Ceiling, Closet		
Classroom 200	Floor Tile VAT 12" x 12"		
Classroom 200	Mastic associated with Floor Tile		
Classroom 200	Transite associated with Window Sill		
Classroom 200	Floor Tile VAT 9" x 9"		
Classroom 200 Closet A	Mastic associated with Floor Tile		
Classroom 200 Closet A	Floor Tile VAT 9" x 9"		
Classroom 200 Closet B	Floor Tile VAT 12" x 12"		
Classroom 200 Closet B	Mastic associated with Floor Tile		
Classroom 201	Mastic associated with Floor Tile		
Classroom 201	Transite associated with Ceiling, Closet		
Classroom 201	Transite associated with Window Sill		
Classroom 201	Floor Tile VAT 9" x 9"		
Classroom 201 Closet A	Mastic associated with Floor Tile		
Classroom 201 Closet A	Floor Tile VAT 9" x 9"		
Classroom 202	Floor Tile VAT 9" x 9"		
Classroom 202	Mastic associated with Floor Tile		
Classroom 202	Transite associated with Ceiling, Closet		
Classroom 202	Transite associated with Window Sill		
Classroom 202	Floor Tile VAT 9" x 9"		
Classroom 202 Closet A	Mastic associated with Floor Tile		
Classroom 202 Closet A	Floor Tile VAT 9" x 9"		
Classroom 202 Closet B	Mastic associated with Floor Tile		
Classroom 202 Closet B	Floor Tile VAT 9" x 9"		
Classroom 203	Mastic associated with Floor Tile		
Classroom 203	Transite associated with Ceiling, Closet		
Classroom 203	Transite associated with Window Sill		

James Blaine: Asbestos Hazard Report

Classroom 203	Floor Tile VAT 9" x 9"		
Classroom 203 Closet A	Mastic associated with Floor Tile		
Classroom 203 Closet A	Floor Tile VAT 9" x 9"		
Classroom 203 Closet B	Mastic associated with Floor Tile		
Classroom 203 Closet B	Floor Tile VAT 9" x 9"		
Classroom 204	Transite associated with Ceiling, Closet		
Classroom 204	Floor Tile VAT 12" x 12"		
Classroom 204	Mastic associated with Floor Tile		
Classroom 204	Transite associated with Window Sill		
Classroom 204	Floor Tile VAT 9" x 9"		
Classroom 204 Closet A	Mastic associated with Floor Tile		
Classroom 204 Closet A	Floor Tile VAT 9" x 9"		
Classroom 204 Closet B	Mastic associated with Floor Tile		
Classroom 204 Closet B	Floor Tile VAT 12" x 12"		
Classroom 205	Transite associated with Ceiling, Closet		
Classroom 205	Mastic associated with Floor Tile		
Classroom 205	Floor Tile VAT 9" x 9"		
Classroom 205	Floor Tile VAT 12" x 12"		
Classroom 205	Transite associated with Window Sill		
Classroom 205 Closet A	Mastic associated with Floor Tile		
Classroom 205 Closet A	Floor Tile VAT 9" x 9"		
Classroom 205 Closet B	Floor Tile VAT 12" x 12"		
Classroom 205 Closet B	Mastic associated with Floor Tile		
Classroom 206	Mastic associated with Floor Tile		
Classroom 206	Transite associated with Ceiling, Closet		
Classroom 206	Transite associated with Window Sill		
Classroom 206	Floor Tile VAT 12" x 12"		
Classroom 206	Floor Tile VAT 9" x 9"		
Classroom 206 Closet A	Mastic associated with Floor Tile		
Classroom 206 Closet A	Floor Tile VAT 9" x 9"		
Classroom 206 Closet B	Mastic associated with Floor Tile		
Classroom 206 Closet B	Floor Tile VAT 9" x 9"		
Classroom 207	Mastic associated with Floor Tile		
Classroom 207	Floor Tile VAT 9" x 9"		
Classroom 207	Transite associated with Window Sill		
Classroom 207	Floor Tile VAT 12" x 12"		
Classroom 207 Closet	Mastic associated with Floor Tile		
Boy's Restroom	Transite associated with Window Sill		
Men's Restroom	Mastic associated with Floor Tile		
Men's Restroom	Floor Tile VAT 12" x 12"		
Classroom 208	Mastic associated with Floor Tile		
Classroom 208	Transite associated with Ceiling, Closet		
Classroom 208	Transite associated with Window Sill		
Classroom 208	Floor Tile VAT 12" x 12"		
Classroom 208	Floor Tile VAT 9" x 9"		
Classroom 208 Closet A	Mastic associated with Floor Tile		
Classroom 208 Closet A	Floor Tile VAT 12" x 12"		
Classroom 208 Closet B	Mastic associated with Floor Tile		
Classroom 208 Closet B	Floor Tile VAT 9" x 9"		
Women's Restroom	Mastic associated with Floor Tile		
Women's Restroom	Floor Tile VAT 12" x 12"		
Girl's Restroom	Transite associated with Window Sill		
Classroom 209	Mastic associated with Floor Tile		
Classroom 209	Transite associated with Ceiling, Closet		
Classroom 209	Transite associated with Window Sill		
Classroom 209	Floor Tile VAT 12" x 12"		

James Blaine: Asbestos Hazard Report

Classroom 209 Closet A	Floor Tile VAT 9" x 9"		
Storage Room 209A (server room/book closet)	Mastic associated with Floor Tile		
Storage Room 209A (server room/book closet)	Floor Tile VAT 9" x 9"		
Classroom 209 Closet B	Mastic associated with Floor Tile		
Classroom 209 Closet B	Floor Tile VAT 9" x 9"		
Classroom 210	Mastic associated with Floor Tile		
Classroom 210	Transite associated with Ceiling, Closet		
Classroom 210	Transite associated with Window Sill		
Classroom 210	Floor Tile VAT 12" x 12"		
Classroom 210	Floor Tile VAT 9" x 9"		
Classroom 210 Closet A	Mastic associated with Floor Tile		
Classroom 210 Closet A	Floor Tile VAT 9" x 9"		
Classroom 210 Closet B	Mastic associated with Floor Tile		
Classroom 210 Closet B	Floor Tile VAT 9" x 9"		
Classroom 211	Floor Tile VAT 9" x 9"		
Classroom 211	Mastic associated with Floor Tile		
Classroom 211	Transite associated with Window Sill		
Classroom 211	Floor Tile VAT 12" x 12"		
Classroom 211 Closet A	Mastic associated with Floor Tile		
Classroom 211 Closet A	Floor Tile VAT 9" x 9"		
Book Storage Room next to Elevator	Mastic associated with Floor Tile		
Classroom 212	Mastic associated with Floor Tile		
Classroom 212	Transite associated with Ceiling, Closet		
Classroom 212	Transite associated with Window Sill		
Classroom 212	Floor Tile VAT 12" x 12"		
Classroom 212 Closet A	Mastic associated with Floor Tile		
Classroom 212 Closet A	Floor Tile VAT 9" x 9"		
Classroom 212 Closet B	Mastic associated with Floor Tile		
Classroom 212 Closet B	Floor Tile VAT 12" x 12"		
Classroom 213	Mastic associated with Floor Tile		
Classroom 213	Transite associated with Ceiling, Closet		
Classroom 213	Transite associated with Window Sill		
Classroom 213	Floor Tile VAT 12" x 12"		
Classroom 213	Floor Tile VAT 9" x 9"		
Classroom 213 Closet A	Mastic associated with Floor Tile		
Classroom 213 Closet A	Floor Tile VAT 9" x 9"		
Classroom 213 Closet B	Mastic associated with Floor Tile		
Classroom 213 Closet B	Floor Tile VAT 9" x 9"		
Classroom 214	Mastic associated with Floor Tile		
Classroom 214	Transite associated with Ceiling, Closet		
Classroom 214	Transite associated with Window Sill		
Classroom 214	Floor Tile VAT 9" x 9"		
Classroom 214 Closet A	Mastic associated with Floor Tile		
Classroom 214 Closet A	Floor Tile VAT 9" x 9"		
Classroom 214 Closet B	Mastic associated with Floor Tile		
Classroom 214 Closet B	Floor Tile VAT 9" x 9"		
Classroom 215	Mastic associated with Floor Tile		
Classroom 215	Transite associated with Ceiling, Closet		
Classroom 215	Transite associated with Window Sill		
Classroom 215	Floor Tile VAT 12" x 12"		
Classroom 215	Floor Tile VAT 9" x 9"		
Classroom 215 Closet A	Mastic associated with Floor Tile		
Classroom 215 Closet A	Floor Tile VAT 9" x 9"		
Classroom 215 Closet B	Mastic associated with Floor Tile		

James Blaine: Asbestos Hazard Report

Classroom 215 Closet B	Floor Tile VAT 9" x 9"		
Classroom 216	Mastic associated with Floor Tile		
Classroom 216	Transite associated with Ceiling, Closet		
Classroom 216	Floor Tile VAT 12" x 12"		
Classroom 216	Transite associated with Window Sill		
Classroom 216	Floor Tile VAT 12" x 12"		
Classroom 216 Closet A	Mastic associated with Floor Tile		
Classroom 216 Closet A	Floor Tile VAT 12" x 12"		
Classroom 216 Closet B	Mastic associated with Floor Tile		
Classroom 216 Closet B	Floor Tile VAT 12" x 12"		
Classroom 217	Mastic associated with Floor Tile		
Classroom 217	Floor Tile VAT 9" x 9"		
Classroom 217 Closet A (Near Entrance)	Mastic associated with Floor Tile		
Classroom 217 Closet A (Near Entrance)	Floor Tile VAT 9" x 9"		
Classroom 217 Closet B	Mastic associated with Floor Tile		
Classroom 217 Closet B	Floor Tile VAT 9" x 9"		
Hallway from Classrooms 200 to 209	Transite associated with Fire Extinguisher Sill		
Hallway from Classrooms 200 to 209	Mastic associated with Floor Tile		
Hallway from Classrooms 200 to 209	Floor Tile VAT 12" x 12"		
Hallway from Classrooms 200 to 209	Transite associated with Window Sill		
Hallway from Classrooms 200 to 209	Floor Tile VAT 9" x 9"		
Hallway from Classrooms 210 to 216	Mastic associated with Floor Tile		
Hallway from Classrooms 210 to 216	Transite associated with Fire Extinguisher Sill		
Hallway from Classrooms 210 to 216	Floor Tile VAT 12" x 12"		
Hallway from Classrooms 210 to 216	Floor Tile VAT 9" x 9"		
Stairwell #1	Mastic associated with Floor Tile		
Stairwell #1	Floor Tile VAT 12" x 12"		
Stairwell #1	Floor Tile VAT 9" x 9"		
Stairwell #3	Mastic associated with Floor Tile		
Stairwell #3	Transite associated with Window Sill		
Stairwell #3	Floor Tile VAT 9" x 9"		
Stairwell #2	Mastic associated with Floor Tile		
Stairwell #2	Transite associated with Window Sill		
Stairwell #2	Floor Tile VAT 12" x 12"		
Stairwell #2	Floor Tile VAT 9" x 9"		
Classroom 300	Transite associated with Ceiling, Closet		
Classroom 300	Floor Tile VAT 9" x 9"		
Classroom 300	Mastic associated with Floor Tile		
Classroom 300	Transite associated with Closet		
Classroom 300	Floor Tile VAT 9" x 9"		
Classroom 300 Closet A (front)	Mastic associated with Floor Tile		
Classroom 300 Closet A (front)	Floor Tile VAT 9" x 9"		
Classroom 300 Closet B (rear)	Mastic associated with Floor Tile		
Classroom 300 Closet B (rear)	Floor Tile VAT 9" x 9"		
Classroom 301	Mastic associated with Floor Tile		
Classroom 301	Transite associated with Ceiling, Closet		
Classroom 301	Transite associated with Window Sill		
Classroom 301	Floor Tile VAT 12" x 12"		
Classroom 301 Closet A	Mastic associated with Floor Tile		
Classroom 301 Closet A	Floor Tile VAT 12" x 12"		
Classroom 302	Transite associated with Ceiling, Closet		
Classroom 302	Transite associated with Window Sill		
Classroom 302 Closet B (rear)	Mastic associated with Floor Tile		
Classroom 302 Closet B (rear)	Floor Tile VAT 12" x 12"		

James Blaine: Asbestos Hazard Report

Classroom 303	Mastic associated with Floor Tile		
Classroom 303	Transite associated with Ceiling, Closet		
Classroom 303	Transite associated with Window Sill		
Classroom 303	Floor Tile VAT 12" x 12"		
Classroom 303 Closet A (front)	Mastic associated with Floor Tile		
Classroom 303 Closet A (front)	Floor Tile VAT 12" x 12"		
Classroom 303 Closet B (rear)	Mastic associated with Floor Tile		
Classroom 303 Closet B (rear)	Floor Tile VAT 12" x 12"		
Classroom 304	Floor Tile VAT 12" x 12" associated with Floor Tile		
Classroom 304	Mastic associated with Floor Tile		
Classroom 304	Transite associated with Ceiling, Closet		
Classroom 304	Transite associated with Window Sill		
Classroom 304	Floor Tile VAT 9" x 9"		
Classroom 304 Closet A	Mastic associated with Floor Tile		
Classroom 304 Closet A	Floor Tile VAT 9" x 9"		
Classroom 304 Closet B	Mastic associated with Floor Tile		
Classroom 304 Closet B	Floor Tile VAT 9" x 9"		
Classroom 305	Mastic associated with Floor Tile		
Classroom 305	Transite associated with Ceiling, Closet		
Classroom 305	Transite associated with Window Sill		
Classroom 305	Floor Tile VAT 12" x 12"		
Classroom 305 Closet A (front)	Mastic associated with Floor Tile		
Classroom 305 Closet A (front)	Floor Tile VAT 12" x 12"		
Classroom 305 Closet B (rear)	Mastic associated with Floor Tile		
Classroom 305 Closet B (rear)	Floor Tile VAT 12" x 12"		
Classroom 306	Mastic associated with Floor Tile		
Classroom 306	Transite associated with Ceiling, Closet		
Classroom 306	Transite associated with Window Sill		
Classroom 306	Floor Tile VAT 12" x 12"		
Classroom 306	Floor Tile VAT 9" x 9"		
Classroom 306 Closet A (front)	Floor Tile VAT 12" x 12"		
Classroom 306 Closet A (front)	Mastic associated with Floor Tile		
Classroom 306 Closet B (back)	Mastic associated with Floor Tile		
Classroom 306 Closet B (back)	Floor Tile VAT 12" x 12"		
Classroom 307	Mastic associated with Floor Tile		
Classroom 307	Transite associated with Ceiling, Closet		
Classroom 307	Transite associated with Window Sill		
Classroom 307	Floor Tile VAT 12" x 12"		
Classroom 307 Closet A (front)	Mastic associated with Floor Tile		
Classroom 307 Closet A (front)	Floor Tile VAT 12" x 12"		
Classroom 307 Closet B (rear)	Mastic associated with Floor Tile		
Classroom 307 Closet B (rear)	Floor Tile VAT 12" x 12"		
Men's Restroom	Mastic associated with Floor Tile		
Men's Restroom	Floor Tile VAT 9" x 9"		
Classroom 308	Mastic associated with Floor Tile		
Classroom 308	Transite associated with Ceiling, Closet		
Classroom 308	Transite associated with Window Sill		
Classroom 308	Floor Tile VAT 12" x 12"		
Classroom 308	Floor Tile VAT 9" x 9"		
Classroom 308 Closet A (front)	Mastic associated with Floor Tile		
Classroom 308 Closet A (front)	Floor Tile VAT 12" x 12"		
Classroom 308 Closet B (rear)	Mastic associated with Floor Tile		
Classroom 308 Closet B (rear)	Floor Tile VAT 9" x 9"		
Girl's Restroom	Transite associated with Window Sill		
Women's Restroom	Mastic associated with Floor Tile		
Women's Restroom	Floor Tile VAT 9" x 9"		

James Blaine: Asbestos Hazard Report

Classroom 309	Mastic associated with Floor Tile		
Classroom 309	Transite associated with Ceiling, Closet		
Classroom 309	Floor Tile VAT 12" x 12"		
Classroom 309	Floor Tile VAT 9" x 9"		
Classroom 309 Closet A	Mastic associated with Floor Tile		
Classroom 309 Closet A	Floor Tile VAT 9" x 9"		
Book Storage Room 309A	Mastic associated with Floor Tile		
Book Storage Room 309A	Floor Tile VAT 9" x 9"		
Classroom 309 Closet B	Mastic associated with Floor Tile		
Classroom 309 Closet B	Floor Tile VAT 9" x 9"		
Classroom 310	Mastic associated with Floor Tile		
Classroom 310	Transite associated with Ceiling, Closet		
Classroom 310	Floor Tile VAT 9" x 9"		
Classroom 310 Closet A	Mastic associated with Floor Tile		
Classroom 310 Closet A	Floor Tile VAT 9" x 9"		
Classroom 310 Closet B	Mastic associated with Floor Tile		
Classroom 310 Closet B	Floor Tile VAT 9" x 9"		
Classroom 311	Mastic associated with Floor Tile		
Classroom 311	Floor Tile VAT 12" x 12"		
Classroom 311	Transite associated with Ceiling, Closet		
Classroom 311	Transite associated with Window Sill		
Classroom 311	Floor Tile VAT 12" x 12"		
Classroom 311	Floor Tile VAT 9" x 9"		
Storage Room 311A	Floor Tile VAT 12" x 12" associated with Floor Tile		
Storage Room 311A	Mastic associated with Floor Tile		
Storage Room 311A	Floor Tile VAT 9" x 9"		
Classroom 311 Closet B	Mastic associated with Floor Tile		
Classroom 311 Closet B	Floor Tile VAT 9" x 9"		
Classroom 312	Mastic associated with Floor Tile		
Classroom 312	Transite associated with Ceiling, Closet		
Classroom 312	Transite associated with Window Sill		
Classroom 312	Floor Tile VAT 9" x 9"		
Classroom 312 Closet A (front)	Mastic associated with Floor Tile		
Classroom 312 Closet A (front)	Floor Tile VAT 9" x 9"		
Classroom 312 Closet B (rear)	Mastic associated with Floor Tile		
Classroom 312 Closet B (rear)	Floor Tile VAT 9" x 9"		
Classroom 313	Mastic associated with Floor Tile		
Classroom 313	Transite associated with Ceiling, Closet		
Classroom 313	Floor Tile VAT 12" x 12"		
Classroom 313	Transite associated with Window Sill		
Classroom 313 Closet B	Mastic associated with Floor Tile		
Classroom 313 Closet B	Floor Tile VAT 9" x 9"		
Classroom 314	Mastic associated with Floor Tile		
Classroom 314	Transite associated with Ceiling, Closet		
Classroom 314	Floor Tile VAT 12" x 12"		
Classroom 314	Floor Tile VAT 9" x 9"		
Classroom 314 Closet A	Mastic associated with Floor Tile		
Classroom 314 Closet A	Floor Tile VAT 9" x 9"		
Classroom 315	Mastic associated with Floor Tile		
Classroom 315	Transite associated with Window Sill		
Classroom 315	Floor Tile VAT 9" x 9"		
Classroom 315 Closet A	Mastic associated with Floor Tile		
Classroom 315 Closet A	Floor Tile VAT 9" x 9"		
Classroom 315 Closet B	Mastic associated with Floor Tile		
Classroom 315 Closet B	Floor Tile VAT 9" x 9"		
Classroom 316	Mastic associated with Floor Tile		

James Blaine: Asbestos Hazard Report

Classroom 316	Transite associated with Ceiling, Closet		
Classroom 316	Transite associated with Window Sill		
Classroom 316	Floor Tile VAT 9" x 9"		
Classroom 316 Closet A	Mastic associated with Floor Tile		
Classroom 316 Closet A	Floor Tile VAT 9" x 9"		
Classroom 316 Closet B	Mastic associated with Floor Tile		
Classroom 316 Closet B	Floor Tile VAT 9" x 9"		
Classroom 317	Mastic associated with Floor Tile		
Classroom 317	Transite associated with Window Sill		
Classroom 317	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 317	Floor Tile VAT 9" x 9"		
Classroom 317 Closet A	Mastic associated with Floor Tile		
Classroom 317 Closet A	Floor Tile VAT 9" x 9"		
Classroom 317 Closet B	Mastic associated with Floor Tile		
Classroom 317 Closet B	Floor Tile VAT 9" x 9"		
Hallway from Classrooms 310 to 316	Mastic associated with Floor Tile		
Hallway from Classrooms 310 to 316	Transite associated with Fire Extinguisher Sill		
Hallway from Classrooms 310 to 316	Floor Tile VAT 12" x 12"		
Hallway from Classrooms 310 to 316	Floor Tile VAT 9" x 9"		
Hallway from Classrooms 300 to 309	Floor Tile VAT 12" x 12" associated with Floor Tile		
Hallway from Classrooms 300 to 309	Mastic associated with Floor Tile		
Hallway from Classrooms 300 to 309	Transite associated with Fire Extinguisher Sill		
Hallway from Classrooms 300 to 309	Floor Tile VAT 9" x 9"		
Stairwell #1	Mastic associated with Floor Tile		
Stairwell #1	Floor Tile VAT 12" x 12"		
Stairwell #1	Floor Tile VAT 9" x 9"		
Stairwell #1	Transite associated with Window Sill		
Stairwell #3	Mastic associated with Floor Tile		
Stairwell #3	Transite associated with Window Sill		
Stairwell #3	Floor Tile VAT 12" x 12"		
Stairwell #3	Floor Tile VAT 9" x 9"		
Stairwell #2	Mastic associated with Floor Tile		
Stairwell #2	Floor Tile VAT 12" x 12"		
Stairwell #2	Floor Tile VAT 9" x 9"		
Building Engineer's Office Restroom	Mastic associated with Floor Tile		
Building Engineer's Office Restroom	Floor Tile VAT 12" x 12"		
Storage Room B-2	Transite associated with Window Frame		
Building Engineer's Office	Floor Tile VAT 12" x 12"		
Building Engineer's Office	Mastic associated with Floor Tile		
Staff Restroom	Floor Tile VAT 12" x 12"		
Staff Restroom	Mastic associated with Floor Tile		