

Stephen Decatur School: Asbestos Hazard Report

The Philadelphia Regional Center for Children's Environmental Health has partnered with the Healthy Schools Initiative to analyze and report on public information regarding asbestos conditions in schools made available on the School District of Philadelphia's website.

This report is meant to communicate to parents, teachers, and staff the exposure risk at their school and help prioritize the removal of asbestos in high-risk exposure locations.

Our analysis is based on publicly available reports. We have not conducted inspections or verified the reports.

Key Findings:

- 136 teacher / student occupied spaces have asbestos containing material (ACM)
- 2 spaces had damaged ACM
- 33 spaces contained friable ACM
- **All damaged** materials were scheduled to be abated

Our Recommendations:

- The School District scheduled the abatement for all the two damaged ACM identified during their latest inspection in Feb 2026.
- The School District is required to regularly monitor the condition of their ACM by the EPA. A full list of the ACM found at this school can be found in Table 1 and Table 2. If these materials become damaged, teachers, staff, and parents should report any damaged ACM to their principal immediately.



What is asbestos?

Asbestos is a fibrous material that is resistant to heat, water, and corrosion.

See this link for a comprehensive list: <https://prcceh.upenn.edu/asbestos>

Asbestos was used in materials in schools, including:

- Ceiling Tiles
- Floor Tiles
- Pipe Insulation
- Cement
- Paint and Caulk
- Soundproofing
- Fireproofing
- Plaster Materials

What are the health effects of asbestos?

No immediate health impacts are expected from asbestos exposure in schools. However, breathing asbestos fibers in schools may increase the risk of developing cancer many years from now.

Children are very active, breathing more air while running and playing. Children take more breaths per minute than adults and are lower to the ground where asbestos fibers may settle. This puts them at an increased risk for asbestos exposure.

Are all asbestos containing materials of equal risk?

Some asbestos containing materials like ceiling and floor tiles have asbestos fibers imbedded in other materials. As long as they are not broken or damaged the asbestos fibers are not released into the air.

Some asbestos containing materials like insulation on pipe remains fibrous and can easily be released in the air when damaged.

How are damaged asbestos containing materials managed?

Asbestos can be removed. Sometimes damaged materials are managed in place by patching, encapsulating (using a specially formulated paint-like coating) or building an enclosure around damaged and/or accessible materials. All of these are forms of abatement.

The Environmental Protection Agency requires all remaining asbestos containing material to be inspected by the school district every six months. This is documented in an Asbestos Hazard Emergency Response Act Report (AHERA Report).

Important Terms

Get to know these terms to make the most out of this report.

Damaged Asbestos Containing Material (ACM) can release asbestos fibers into the air.

Friable Materials can be reduced to a powder by applying hand pressure. **DO NOT TOUCH!**

Non-Friable materials are not easily damaged.

Significantly damaged materials are more than 10% damaged.

Abated ACM means repaired, removed, or reduced risk of exposure.

Detailed Review for Stephen Decatur School

This school has 152 spaces with asbestos containing materials. 136 of them are in teacher / student occupied spaces. The School District last inspected ACM in January 2026 and published the AHERA report in February 2026. Since then, the School District scheduled the abatement of all the 2 damaged asbestos containing materials identified during this inspection.



Abatement that has been scheduled in 2026 has been confirmed as completed through air-management verification reports on the School District website. A list of all the ACM in the school and their damage/abatement schedule can be found in the tables at the end of this report.

Information Reviewed to Make this Report:

The 2025/26 AHERA report from the School District of Philadelphia, and asbestos abatement notifications from the Air Management Services Online Portal.

Not included in this report are planned repairs to damaged asbestos materials that have not been uploaded to the Air Management Services website or any updated after August 4, 2026. To see the most current information, scan these QR Codes. After scanning, search for your school.

School Districts of Philadelphia Asbestos Reports:



AHERA Reports are documents generated from EPA required asbestos inspections

Office of the Controller Asbestos Project:



Asbestos abatement notification forms



Report what you see!

Parents and teachers should report hazardous conditions in schools on the Healthy Schools app.

Scan here to
download the app:



Disclaimer:

This report analyzes custodial and mechanical spaces like boiler rooms **only** when ACM is significantly damaged (damage > 10%).

Questions?

Find more resources on our website!

- Photo gallery of different types of damaged asbestos containing materials
- Guide to how we classify materials in schools
- Our analysis and reporting methodology
- What we do with the information in this report

prcceb.upenn.edu/asbestos



Email us at prcceb@pennteamedicine.upenn.edu or call 215-573-9076

Table 1: Friable Asbestos Containing Materials Identified

NOTE: Friable materials can be reduced to a powder by applying hand pressure.
Do not touch it! Damaged and significantly damaged friable materials readily release harmful asbestos fibers into the air.

Location	Material Name	Reported as Damaged or Significantly Damaged? (Blank = No)	Abatement scheduled since the inspection? (Blank = No)
Auditorium FAR-2	Pipe Fitting Insulation		
Exterior Facing Academy Road	Caulk associated with Intake Grille		
Exterior Facing Playground	Caulk associated with Intake Grille		
Exterior Facing Houses	Caulk associated with Intake Grille		
Exterior Facing Annex	Caulk associated with Intake Grille		
Office in Rear Of Boiler Room	Pipe Fitting Insulation		
Boiler Room	Boiler Door Insulation associated with Boiler		
Boiler Room	Tank Insulation		
Boiler Room	Boiler Breeching		
Boiler Room	Pipe Fitting Insulation		
Cafeteria	Pipe Fitting Insulation		
Gymnasium	Pipe Fitting Insulation		
Gymnasium	Pipe Fitting Insulation		
Library/IMC	Paint associated with Ceiling, Concrete		
Hallway from Stairwell near Building Engineer's Office to IMC/Library	Paint associated with Ceiling, Concrete		
Classroom B1	Sheetrock/Joint Compound Wall		
Classroom B1 Storage and Meter Room	Sheetrock/Joint Compound Wall		
Classroom B1 Restroom	Sheetrock/Joint Compound Wall		
Classroom B2	Sheetrock/Joint Compound Wall		

Stephen Decatur School: Asbestos Hazard Report

Classroom B2 Closet	Sheetrock/Joint Compound Wall		
Classroom B2 Restroom	Sheetrock/Joint Compound Wall		
Classroom B2 Restroom	Sheetrock/Joint Compound Wall		
Classroom B3	Sheetrock/Joint Compound Wall		
Classroom B3 Restroom	Sheetrock/Joint Compound Wall		
Classroom B3 Closet	Sheetrock/Joint Compound Wall		
Classroom B4	Sheetrock/Joint Compound Wall		
Classroom B4 Restroom	Sheetrock/Joint Compound Wall		
Classroom B4 Closet	Sheetrock/Joint Compound Wall		
Girl's Restroom	Paint associated with Wall, CMU		
Classroom A1	Paint associated with Wall, CMU		
Boy's Restroom	Paint associated with Wall, CMU		
Classroom A2	Paint associated with Wall, CMU		
Staff Restroom next to Boy's Restroom	Paint associated with Wall, CMU		
Classroom A3	Paint associated with Wall, CMU		
Staff Restroom next to Teacher's Closet	Paint associated with Wall, CMU		
Classroom A4	Paint associated with Wall, CMU		
Teacher's Closet next to Classroom A7	Paint associated with Wall, CMU		
Classroom A5	Paint associated with Wall, CMU		
Classroom A6	Paint associated with Wall, CMU		
Classroom A7	Paint associated with Wall, CMU		
Classroom A8	Paint associated with Wall, CMU		
IT/Mechanical Room	Paint associated with Wall, CMU		
Classroom A9	Paint associated with Wall, CMU		
Teacher's Lounge by Classroom A8	Paint associated with Wall, CMU		
Hallway from near Classroom A8 to Exit Doors	Paint associated with Wall, CMU		
Hallway from Classroom A8 to Girl's Restroom	Paint associated with Wall, CMU		
Hallway from Classroom A1 to Classroom A5	Paint associated with Wall, CMU		

Table 2: Non-Friable Asbestos Containing Materials Identified

NOTE: Significantly Damaged non-friable materials (damage $\geq$ 10% of the material) can release harmful asbestos fibers into the air.

Location	Material Name	Reported as Damaged or Significantly Damaged? (Blank = No)	Abatement scheduled since the inspection? (Blank = No)
Classroom K-1	Transite associated with Fuse Box		
Classroom K-1	ACM Unit Ventilator		
Classroom K-1	Floor Tile VAT 9" x 9"		
Classroom K-1	Floor Tile VAT 12" x 12"		
Classroom K-1	Transite associated with Window Sill		
Classroom K-1	Transite associated with Closet		
Classroom K-1	Glue Dots associated with Blackboard		
Classroom K-1	Expansion Seam Caulking		

Stephen Decatur School: Asbestos Hazard Report

Classroom K-1 Restroom	Mastic associated with Floor Tile		
Classroom K-1 Restroom	Floor Tile VAT 12" x 12"		
Classroom K-1 Restroom	Expansion Seam Caulking		
Classroom K-1 Storage Room	Expansion Seam Caulking		
Classroom K-1 Coat Room	Mastic associated with Floor Tile		
Classroom K-1 Coat Room	Expansion Seam Caulking		
Classroom K-2	Transite associated with Fuse Box		
Classroom K-2	Mastic associated with Floor Tile		
Classroom K-2	ACM Unit Ventilator		
Classroom K-2	Floor Tile VAT 9" x 9"		
Classroom K-2	Floor Tile VAT 12" x 12"		
Classroom K-2	Transite associated with Window Sill		
Classroom K-2	Transite associated with Closet		
Classroom K-2	Glue Dots associated with Blackboard		
Classroom K-2	Expansion Seam Caulking		
Classroom K-2 Storage Room	Mastic associated with Floor Tile		
Classroom K-2 Storage Room	Floor Tile VAT 9" x 9"		
Classroom K-2 Storage Room	Floor Tile VAT 9" x 9"		
Classroom K-2 Storage Room	Expansion Seam Caulking		
Classroom K-2 Restroom	Mastic associated with Floor Tile		
Classroom K-2 Restroom	Floor Tile VAT 12" x 12"		
Classroom K-2 Restroom	Expansion Seam Caulking		
Back Hallway from Classroom K-1 to Classroom K-2	Mastic associated with Floor Tile		
Back Hallway from Classroom K-1 to Classroom K-2	Floor Tile VAT 12" x 12"		
Back Hallway from Classroom K-1 to Classroom K-2	Floor Tile VAT 12" x 12"		
Back Hallway from Classroom K-1 to Classroom K-2	Transite associated with Window Sill		
Back Hallway from Classroom K-1 to Classroom K-2	Expansion Seam Caulking		
Classroom K-2 Coat Room	Mastic associated with Floor Tile		
Classroom K-2 Coat Room	Floor Tile VAT 12" x 12"		
Classroom K-2 Coat Room	Floor Tile VAT 9" x 9"		
Classroom K-2 Coat Room	Floor Tile VAT 9" x 9"		
Classroom K-2 Coat Room	Expansion Seam Caulking		
Classroom 100	Transite associated with Fuse Box		
Classroom 100	Mastic associated with Floor Tile		
Classroom 100	Floor Tile VAT 9" x 9"		
Classroom 100	Transite associated with Window Sill		
Classroom 100	Transite associated with Closet		
Classroom 100	Glue Dots associated with Blackboard		
Classroom 100	Expansion Seam Caulking		
Classroom 100	ACM Unit Ventilator		
Classroom 101	Transite associated with Fuse Box		
Classroom 101	Floor Tile VAT 12" x 12"		
Classroom 101	Mastic associated with Floor Tile		
Classroom 101	Floor Tile VAT 9" x 9"		
Classroom 101	Transite associated with Window Sill		
Classroom 101	Transite associated with Closet		
Classroom 101	Glue Dots associated with Blackboard		
Classroom 101	Expansion Seam Caulking		
Classroom 101	ACM Unit Ventilator		
Boy's Restroom across from Classroom 102	Transite associated with Window Sill		

Stephen Decatur School: Asbestos Hazard Report

Boy's Restroom across from Classroom 102	Transite		
Boy's Restroom across from Classroom 102	Expansion Seam Caulking		
Girl's Restroom across from Classroom 100	Transite associated with Window Sill		
Girl's Restroom across from Classroom 100	Transite		
Girl's Restroom across from Classroom 100	Expansion Seam Caulking		
Custodial Closet between Boys and Girls Restrooms	Expansion Seam Caulking		
Classroom 102	Transite associated with Fuse Box		
Classroom 102	Transite associated with Fuse Box		
Classroom 102	Floor Tile VAT 12" x 12"		
Classroom 102	Mastic associated with Floor Tile		
Classroom 102	Floor Tile VAT 9" x 9"		
Classroom 102	Transite associated with Window Sill		
Classroom 102	Transite associated with Closet		
Classroom 102	Glue Dots associated with Blackboard		
Classroom 102	Expansion Seam Caulking		
Classroom 102	ACM Unit Ventilator		
Classroom 103	Transite associated with Fuse Box		
Classroom 103	Floor Tile VAT 12" x 12"		
Classroom 103	Mastic associated with Floor Tile		
Classroom 103	Floor Tile VAT 12" x 12"		
Classroom 103	Floor Tile VAT 9" x 9"		
Classroom 103	Transite associated with Window Sill		
Classroom 103	Transite associated with Closet		
Classroom 103	Glue Dots associated with Blackboard		
Classroom 103	Expansion Seam Caulking		
Classroom 103	ACM Unit Ventilator		
Classroom 104	Transite associated with Fuse Box		
Classroom 104	ACM Unit Ventilator		
Classroom 104	Floor Tile VAT 12" x 12"		
Classroom 104	Mastic associated with Floor Tile		
Classroom 104	Floor Tile VAT 12" x 12"		
Classroom 104	Floor Tile VAT 9" x 9"		
Classroom 104	Transite associated with Window Sill		
Classroom 104	Transite associated with Closet		
Classroom 104	Glue Dots associated with Blackboard		
Classroom 104	Expansion Seam Caulking		
Sensory Room across from Classroom 103	Floor Tile VAT 12" x 12"		
Sensory Room across from Classroom 103	Mastic associated with Floor Tile		
Sensory Room across from Classroom 103	Expansion Seam Caulking		
Sensory Room across from Classroom 103	Floor Tile VAT 9" x 9"		
"Visual Aids" Storage Room across from Classroom 105	Mastic associated with Floor Tile		
"Visual Aids" Storage Room across from Classroom 105	Expansion Seam Caulking		
"Visual Aids" Storage Room across from Classroom 105	Floor Tile VAT 9" x 9"		
Closet In 'Visual Aids' Storage Room	Mastic associated with Floor Tile		

Stephen Decatur School: Asbestos Hazard Report

Closet In 'Visual Aids' Storage Room	Floor Tile VAT 9" x 9"		
Closet In 'Visual Aids' Storage Room	Expansion Seam Caulking		
Maintenance Equipment Storage Room at end of Hallway to Parking Lot "Toms" printed on Door	Expansion Seam Caulking		
Classroom 105	Transite associated with Fuse Box		
Classroom 105	Mastic associated with Floor Tile		
Classroom 105	Floor Tile VAT 12" x 12"		
Classroom 105	Floor Tile VAT 9" x 9"		
Classroom 105	Transite associated with Window Sill		
Classroom 105	Transite associated with Closet		
Classroom 105	Glue Dots associated with Blackboard		
Classroom 105	Expansion Seam Caulking		
Classroom 105	ACM Unit Ventilator		
Auditorium	Mastic associated with Floor Tile		
Auditorium	Floor Tile VAT 9" x 9"		
Auditorium	Expansion Seam Caulking		
Auditorium Stage	Mastic associated with Floor Tile		
Auditorium Stage	Floor Tile VAT 12" x 12"		
Auditorium Stage	Floor Tile VAT 9" x 9"		
Auditorium Stage	Floor Tile VAT 9" x 9"		
Auditorium Stage	Expansion Seam Caulking		
Principal's Office Closet	Mastic associated with Floor Tile		
Principal's Office Closet	Expansion Seam Caulking	Reported damaged in Jul 2025.	Encapsulated in Sep 2025.
Principal's Office Closet	Floor Tile VAT 9" x 9"		
Principal's Office Restroom	Expansion Seam Caulking		
Principal's Office	Expansion Seam Caulking		
Principal's Office	Transite associated with Window Sill		
Main Office	Transite associated with Fuse Box		
Main Office	Floor Tile VAT 12" x 12"		
Main Office	Mastic associated with Floor Tile		
Main Office	ACM Unit Ventilator		
Main Office	Floor Tile VAT 12" x 12"		
Main Office	Floor Tile VAT 9" x 9"		
Main Office	Transite associated with Window Sill		
Main Office	Expansion Seam Caulking		
Closet in Main Office next to Principal's Office	Mastic associated with Floor Tile		
Closet in Main Office next to Principal's Office	Floor Tile VAT 9" x 9"		
Closet in Main Office next to Principal's Office	Expansion Seam Caulking		
Main Office Storage Room across from Administrative Assistant Office	Mastic associated with Floor Tile		
Main Office Storage Room across from Administrative Assistant Office	Expansion Seam Caulking		
Main Office Storage Room across from Administrative Assistant Office	Floor Tile VAT 9" x 9"		
Administrative Assistant's Office in Main Office Area	Floor Tile VAT 12" x 12"		
Administrative Assistant's Office in Main Office Area	Mastic associated with Floor Tile		

Stephen Decatur School: Asbestos Hazard Report

Administrative Assistant's Office in Main Office Area	Floor Tile VAT 9" x 9"		
Administrative Assistant's Office in Main Office Area	Transite associated with Window Sill		
Administrative Assistant's Office in Main Office Area	Expansion Seam Caulking		
Computer Server Room in Main Office (next to Nurse's Office)	Mastic associated with Floor Tile		
Computer Server Room in Main Office (next to Nurse's Office)	Floor Tile VAT 12" x 12"		
Computer Server Room in Main Office (next to Nurse's Office)	Floor Tile VAT 9" x 9"		
Computer Server Room in Main Office (next to Nurse's Office)	Expansion Seam Caulking		
Hallway in Main Office to Nurse's Office	Mastic associated with Floor Tile		
Hallway in Main Office to Nurse's Office	Floor Tile VAT 9" x 9"		
Hallway in Main Office to Nurse's Office	Expansion Seam Caulking		
Classroom 107	Floor Tile VAT 12" x 12"		
Classroom 107	Transite associated with Fuse Box		
Classroom 107	Mastic associated with Floor Tile		
Classroom 107	ACM Unit Ventilator		
Classroom 107	Floor Tile VAT 9" x 9"		
Classroom 107	Floor Tile VAT 9" x 9"		
Classroom 107	Transite associated with Window Sill		
Classroom 107	Transite associated with Closet		
Classroom 107	Glue Dots associated with Blackboard		
Classroom 107	Expansion Seam Caulking		
Classroom 108	Transite associated with Fuse Box		
Classroom 108	Mastic associated with Floor Tile		
Classroom 108	ACM Unit Ventilator		
Classroom 108	Transite associated with Closet		
Classroom 108	Floor Tile VAT 9" x 9"		
Classroom 108	Transite associated with Window Sill		
Classroom 108	Glue Dots associated with Blackboard		
Classroom 108	Expansion Seam Caulking		
Nurse's Office 106	Mastic associated with Floor Tile		
Nurse's Office 106	Floor Tile VAT 9" x 9"		
Nurse's Office 106	Transite associated with Window Sill		
Nurse's Office 106	Transite		
Nurse's Office 106	Expansion Seam Caulking		
Classroom 108 Restroom	Mastic associated with Floor Tile		
Classroom 108 Restroom	Floor Tile VAT 12" x 12"		
Classroom 108 Restroom	Expansion Seam Caulking		
Dean's Office in Main Office Area	Mastic associated with Floor Tile		
Dean's Office in Main Office Area	Floor Tile VAT 12" x 12"		
Dean's Office in Main Office Area	Floor Tile VAT 9" x 9"		
Dean's Office in Main Office Area	Transite associated with Window Sill		
Dean's Office in Main Office Area	Expansion Seam Caulking		
Nurse's Office Restroom	Expansion Seam Caulking		
Nurse's Office Storage Area	Mastic associated with Floor Tile		
Nurse's Office Storage Area	Floor Tile VAT 9" x 9"		
Classroom 109	Transite associated with Fuse Box		
Classroom 109	Mastic associated with Floor Tile		
Classroom 109	ACM Unit Ventilator		

Stephen Decatur School: Asbestos Hazard Report

Classroom 109	ACM Unit Ventilator		
Classroom 109	Floor Tile VAT 9" x 9"		
Classroom 109	Transite associated with Window Sill		
Classroom 109	Transite associated with Closet		
Classroom 109	Expansion Seam Caulking		
Classroom 110	Transite associated with Fuse Box		
Classroom 110	Mastic associated with Floor Tile		
Classroom 110	ACM Unit Ventilator		
Classroom 110	Floor Tile VAT 9" x 9"		
Classroom 110	Transite associated with Window Sill		
Classroom 110	Glue Dots associated with Blackboard		
Classroom 110	Expansion Seam Caulking		
Boy's Restroom next to Room 109	Transite		
Boy's Restroom next to Room 109	Transite associated with Window Sill		
Boy's Restroom next to Room 109	Expansion Seam Caulking		
Custodial Closet Near BE Office	Expansion Seam Caulking		
Teacher's Lounge (Room 112)	Floor Tile VAT 12" x 12"		
Teacher's Lounge (Room 112)	Mastic associated with Floor Tile		
Teacher's Lounge (Room 112)	Floor Tile VAT 9" x 9"	Damaged.	Damaged material removed in Feb 2026.
Teacher's Lounge (Room 112)	Transite associated with Window Sill		
Teacher's Lounge (Room 112)	Expansion Seam Caulking		
Teacher's Lounge (Room 112)	Glue Dots associated with Blackboard		
Teacher's Lounge (Room 112)	Glue Dots associated with Blackboard		
Girl's Restroom near Room 109	Transite		
Girl's Restroom near Room 109	Transite associated with Window Sill		
Girl's Restroom near Room 109	Expansion Seam Caulking		
Speech Office 114 next to Teacher's Lounge	Mastic associated with Floor Tile		
Speech Office 114 next to Teacher's Lounge	Floor Tile VAT 9" x 9"		
Speech Office 114 next to Teacher's Lounge	Transite associated with Window Sill		
Building Engineer's Office	Mastic associated with Floor Tile		
Building Engineer's Office	Transite associated with Window Sill		
Building Engineer's Office	Floor Tile VAT 9" x 9"		
Building Engineer's Office	Expansion Seam Caulking		
Gender Neutral Restroom near Room 106	Expansion Seam Caulking		
Women's Restroom next to Elevator	Transite associated with Stall, Restroom		
Women's Restroom next to Elevator	Expansion Seam Caulking		
Classroom 107 Storage Area	Mastic associated with Floor Tile		
Classroom 107 Storage Area	Floor Tile VAT 12" x 12"		
Classroom 107 Storage Area	Floor Tile VAT 9" x 9"		
Classroom 107 Storage Area	Floor Tile VAT 9" x 9"		
Classroom 107 Storage Area	Expansion Seam Caulking		
Classroom 107 Storage Area	Expansion Seam Caulking		
Classroom 107 Restroom	Expansion Seam Caulking		
Hallway/Lobby between Auditorium and Main Office	Mastic associated with Floor Tile		
Hallway/Lobby between Auditorium and Main Office	Floor Tile VAT 12" x 12"		
Hallway/Lobby between Auditorium and Main Office	Floor Tile VAT 9" x 9"		
Hallway/Lobby between Auditorium and Main Office	Floor Tile VAT 12" x 12"		

Stephen Decatur School: Asbestos Hazard Report

Hallway/Lobby between Auditorium and Main Office	Expansion Seam Caulking		
Main Entrance Door Way	Mastic associated with Floor Tile		
Main Entrance Door Way	Floor Tile VAT 12" x 12"		
Main Entrance Door Way	Floor Tile VAT 12" x 12"		
Main Entrance Door Way	Floor Tile VAT 9" x 9"		
Hallway between Classrooms K-1 and K-2 and Auditorium and Stage	Mastic associated with Floor Tile		
Hallway between Classrooms K-1 and K-2 and Auditorium and Stage	Floor Tile VAT 12" x 12"		
Hallway between Classrooms K-1 and K-2 and Auditorium and Stage	Floor Tile VAT 9" x 9"		
Hallway between Classrooms K-1 and K-2 and Auditorium and Stage	Expansion Seam Caulking		
Hallway from Classroom 105 and "Visual Aids" Room to Classroom 100	Floor Tile VAT 12" x 12"		
Hallway from Classroom 105 and "Visual Aids" Room to Classroom 100	Mastic associated with Floor Tile		
Hallway from Classroom 105 and "Visual Aids" Room to Classroom 100	Floor Tile VAT 12" x 12"		
Hallway from Classroom 105 and "Visual Aids" Room to Classroom 100	Transite associated with Fire Extinguisher Sill		
Hallway from Classroom 105 and "Visual Aids" Room to Classroom 100	Floor Tile VAT 9" x 9"		
Hallway from Classroom 105 and "Visual Aids" Room to Classroom 100	Floor Tile VAT 9" x 9"		
Hallway from Classroom 105 and "Visual Aids" Room to Classroom 100	Expansion Seam Caulking		
Hallway from Building Engineer's Office to Elevator	Floor Tile VAT 12" x 12"		
Hallway from Building Engineer's Office to Elevator	Mastic associated with Floor Tile		
Hallway from Building Engineer's Office to Elevator	Transite associated with Fire Extinguisher Sill		
Hallway from Building Engineer's Office to Elevator	Floor Tile VAT 12" x 12"		
Hallway from Building Engineer's Office to Elevator	Floor Tile VAT 12" x 12"		
Hallway from Building Engineer's Office to Elevator	Floor Tile VAT 9" x 9"		
Hallway from Building Engineer's Office to Elevator	Expansion Seam Caulking		
Hallway from Main Hallway near Classroom 103 to Parking Lot	Floor Tile VAT 12" x 12"		
Hallway from Main Hallway near Classroom 103 to Parking Lot	Mastic associated with Floor Tile		

Stephen Decatur School: Asbestos Hazard Report

Hallway from Main Hallway near Classroom 103 to Parking Lot	Floor Tile VAT 9" x 9"		
Hallway from Main Hallway near Classroom 103 to Parking Lot	Expansion Seam Caulking		
Hallway from Main Hallway near Classroom 103 to Parking Lot	Expansion Seam Caulking		
Stairwell #3 across from Classroom 100	Expansion Seam Caulking		
Stairwell #1 near Building Engineer's Office	Expansion Seam Caulking		
Stairwell #2 near Classroom 105	Expansion Seam Caulking		
Classroom 200	Transite associated with Fuse Box		
Classroom 200	Mastic associated with Floor Tile		
Classroom 200	ACM Unit Ventilator		
Classroom 200	Floor Tile VAT 9" x 9"		
Classroom 200	Transite associated with Window Sill		
Classroom 200	Transite associated with Closet		
Classroom 200	Glue Dots associated with Blackboard		
Classroom 200	Expansion Seam Caulking		
Classroom 201	Transite associated with Fuse Box		
Classroom 201	Mastic associated with Floor Tile		
Classroom 201	Floor Tile VAT 12" x 12"		
Classroom 201	ACM Unit Ventilator		
Classroom 201	Floor Tile VAT 9" x 9"		
Classroom 201	Transite associated with Window Sill		
Classroom 201	Transite associated with Closet		
Classroom 201	Glue Dots associated with Blackboard		
Classroom 201	Expansion Seam Caulking		
Girl's Restroom across from Classroom 200	Transite associated with Window Sill		
Girl's Restroom across from Classroom 200	Expansion Seam Caulking		
Boy's Restroom across from Classroom 202	Transite associated with Window Sill		
Boy's Restroom across from Classroom 202	Expansion Seam Caulking		
Books B-2 Storage Room across from Classroom 202	Mastic associated with Floor Tile		
Books B-2 Storage Room across from Classroom 202	Floor Tile VAT 9" x 9"		
Books B-2 Storage Room across from Classroom 202	Expansion Seam Caulking		
Custodial Closet across from Classroom 200	Expansion Seam Caulking		
Classroom 202	Transite associated with Fuse Box		
Classroom 202	Mastic associated with Floor Tile		
Classroom 202	ACM Unit Ventilator		
Classroom 202	Floor Tile VAT 9" x 9"		
Classroom 202	Transite associated with Window Sill		
Classroom 202	Transite associated with Closet		
Classroom 202	Glue Dots associated with Blackboard		
Classroom 202	Expansion Seam Caulking		
Classroom 203	Transite associated with Fuse Box		
Classroom 203	Mastic associated with Floor Tile		
Classroom 203	Floor Tile VAT 12" x 12"		
Classroom 203	ACM Unit Ventilator		
Classroom 203	Floor Tile VAT 9" x 9"		

Stephen Decatur School: Asbestos Hazard Report

Classroom 203	Floor Tile VAT 9" x 9"		
Classroom 203	Transite associated with Window Sill		
Classroom 203	Transite associated with Closet		
Classroom 203	Glue Dots associated with Blackboard		
Classroom 203	Expansion Seam Caulking		
Classroom 204	Transite associated with Fuse Box		
Classroom 204	Mastic associated with Floor Tile		
Classroom 204	Floor Tile VAT 9" x 9"		
Classroom 204	Transite associated with Window Sill		
Classroom 204	Transite associated with Closet		
Classroom 204	Glue Dots associated with Blackboard		
Classroom 204	Expansion Seam Caulking		
Classroom 204	ACM Unit Ventilator		
Classroom 205	Transite associated with Fuse Box		
Classroom 205	Mastic associated with Floor Tile		
Classroom 205	Floor Tile VAT 9" x 9"		
Classroom 205	Floor Tile VAT 9" x 9"		
Classroom 205	Transite associated with Window Sill		
Classroom 205	Transite associated with Closet		
Classroom 205	Glue Dots associated with Blackboard		
Classroom 205	Expansion Seam Caulking		
Classroom 205	ACM Unit Ventilator		
Classroom 206	Transite associated with Fuse Box		
Classroom 206	Mastic associated with Floor Tile		
Classroom 206	Floor Tile VAT 12" x 12"		
Classroom 206	Floor Tile VAT 12" x 12"		
Classroom 206	Floor Tile VAT 9" x 9"		
Classroom 206	Transite associated with Window Sill		
Classroom 206	Transite associated with Closet		
Classroom 206	Glue Dots associated with Blackboard		
Classroom 206	Expansion Seam Caulking		
Classroom 206	ACM Unit Ventilator		
Women's Restroom across from Classroom 214	Transite associated with Stall, Restroom		
Women's Restroom across from Classroom 214	Expansion Seam Caulking		
Classroom 208	Transite associated with Fuse Box		
Classroom 208	Mastic associated with Floor Tile		
Classroom 208	ACM Unit Ventilator		
Classroom 208	Floor Tile VAT 9" x 9"		
Classroom 208	Transite associated with Window Sill		
Classroom 208	Transite associated with Closet		
Classroom 208	Glue Dots associated with Blackboard		
Classroom 208	Expansion Seam Caulking		
Classroom 210	Transite associated with Fuse Box		
Classroom 210	Mastic associated with Floor Tile		
Classroom 210	Floor Tile VAT 9" x 9"		
Classroom 210	Transite associated with Window Sill		
Classroom 210	Transite associated with Closet		
Classroom 210	Glue Dots associated with Blackboard		
Classroom 210	Expansion Seam Caulking		
Classroom 210	ACM Unit Ventilator		
Classroom 210	ACM Unit Ventilator		
Classroom 212	Transite associated with Fuse Box		
Classroom 212	Mastic associated with Floor Tile		
Classroom 212	Floor Tile VAT 9" x 9"		

Stephen Decatur School: Asbestos Hazard Report

Classroom 212	Transite associated with Window Sill		
Classroom 212	Transite associated with Closet		
Classroom 212	Glue Dots associated with Blackboard		
Classroom 212	Expansion Seam Caulking		
Classroom 212	ACM Unit Ventilator		
Room 214 Learning Support	Transite associated with Fuse Box		
Room 214 Learning Support	Floor Tile VAT 12" x 12"		
Room 214 Learning Support	Mastic associated with Floor Tile		
Room 214 Learning Support	ACM Unit Ventilator		
Room 214 Learning Support	Floor Tile VAT 9" x 9"		
Room 214 Learning Support	Transite associated with Window Sill		
Room 214 Learning Support	Transite associated with Closet		
Room 214 Learning Support	Glue Dots associated with Blackboard		
Room 214 Learning Support	Expansion Seam Caulking		
Classroom 216/218 Art	Transite associated with Fuse Box		
Classroom 216/218 Art	Mastic associated with Floor Tile		
Classroom 216/218 Art	ACM Unit Ventilator		
Classroom 216/218 Art	Floor Tile VAT 9" x 9"		
Classroom 216/218 Art	Transite associated with Window Sill		
Classroom 216/218 Art	Transite associated with Closet		
Classroom 216/218 Art	Glue Dots associated with Blackboard		
Classroom 216/218 Art	Expansion Seam Caulking		
Classroom 217 Science	Transite associated with Fuse Box		
Classroom 217 Science	Mastic associated with Floor Tile		
Classroom 217 Science	ACM Unit Ventilator		
Classroom 217 Science	Floor Tile VAT 12" x 12"		
Classroom 217 Science	Floor Tile VAT 12" x 12"		
Classroom 217 Science	Floor Tile VAT 12" x 12"		
Classroom 217 Science	Transite associated with Tabletop		
Classroom 217 Science	Transite associated with Window Sill		
Classroom 217 Science	Glue Dots associated with Blackboard		
Classroom 217 Science	Expansion Seam Caulking		
Classroom 217 Lab Prep	Mastic associated with Floor Tile		
Classroom 217 Lab Prep	Floor Tile VAT 12" x 12"		
Classroom 217 Lab Prep	Floor Tile VAT 12" x 12"		
Classroom 217 Lab Prep	Floor Tile VAT 12" x 12"		
Classroom 217 Lab Prep	Transite associated with Window Sill		
Classroom 219	Transite associated with Fuse Box		
Classroom 219	Mastic associated with Floor Tile		
Classroom 219	ACM Unit Ventilator		
Classroom 219	Floor Tile VAT 9" x 9"		
Classroom 219	Transite associated with Window Sill		
Classroom 219	Transite associated with Closet		
Classroom 219	Glue Dots associated with Blackboard		
Classroom 219	Expansion Seam Caulking		
Classroom 220 Music	Transite associated with Fuse Box		
Classroom 220 Music	Mastic associated with Floor Tile		
Classroom 220 Music	ACM Unit Ventilator		
Classroom 220 Music	Floor Tile VAT 9" x 9"		
Classroom 220 Music	Transite associated with Window Sill		
Classroom 220 Music	Transite associated with Closet		
Classroom 220 Music	Glue Dots associated with Blackboard		
Classroom 220 Music	Expansion Seam Caulking		
Gender Neutral Restroom across from Classroom 220	Expansion Seam Caulking		

Stephen Decatur School: Asbestos Hazard Report

Gender Neutral Restroom across from Classroom 220	Transite associated with Stall, Restroom		
Boy's Restroom across from Classroom 220	Transite associated with Window Sill		
Boy's Restroom across from Classroom 220	Expansion Seam Caulking		
Girl's Restroom near Classroom 220	Transite associated with Window Sill		
Girl's Restroom near Classroom 220	Expansion Seam Caulking		
Custodial Closet across from Classroom 220	Expansion Seam Caulking		
Hallway from Classroom 200 to Classroom 210	Floor Tile VAT 12" x 12"		
Hallway from Classroom 200 to Classroom 210	Mastic associated with Floor Tile		
Hallway from Classroom 200 to Classroom 210	Transite associated with Fire Extinguisher Sill		
Hallway from Classroom 200 to Classroom 210	Floor Tile VAT 12" x 12"		
Hallway from Classroom 200 to Classroom 210	Floor Tile VAT 9" x 9"		
Hallway from Classroom 200 to Classroom 210	Expansion Seam Caulking		
Hallway from Stairwell past Classroom 220 to Elevator and Classroom 212	Mastic associated with Floor Tile		
Hallway from Stairwell past Classroom 220 to Elevator and Classroom 212	Floor Tile VAT 12" x 12"		
Hallway from Stairwell past Classroom 220 to Elevator and Classroom 212	Transite associated with Fire Extinguisher Sill		
Hallway from Stairwell past Classroom 220 to Elevator and Classroom 212	Floor Tile VAT 9" x 9"		
Hallway from Stairwell past Classroom 220 to Elevator and Classroom 212	Floor Tile VAT 9" x 9"		
Hallway from Stairwell past Classroom 220 to Elevator and Classroom 212	Expansion Seam Caulking		
Stairwell #3 across from Classroom 200	Transite associated with Window Sill		
Stairwell #3 across from Classroom 200	Expansion Seam Caulking		
Stairwell #1 near Classroom 220	Expansion Seam Caulking		
Stairwell #2 across from Classroom 208	Expansion Seam Caulking		
Classroom 300	Transite associated with Fuse Box		
Classroom 300	Mastic associated with Floor Tile		
Classroom 300	ACM Unit Ventilator		
Classroom 300	Floor Tile VAT 9" x 9"		
Classroom 300	Transite associated with Window Sill		
Classroom 300	Transite associated with Closet		
Classroom 300	Glue Dots associated with Blackboard		
Classroom 300	Expansion Seam Caulking		
Classroom 301	Transite associated with Fuse Box		
Classroom 301	ACM Unit Ventilator		

Stephen Decatur School: Asbestos Hazard Report

Classroom 301	Mastic associated with Floor Tile		
Classroom 301	Floor Tile VAT 12" x 12"		
Classroom 301	Floor Tile VAT 9" x 9"		
Classroom 301	Floor Tile VAT 9" x 9"		
Classroom 301	Transite associated with Window Sill		
Classroom 301	Transite associated with Closet		
Classroom 301	Glue Dots associated with Blackboard		
Classroom 301	Expansion Seam Caulking		
Girl's Restroom across from Classroom 300	Transite associated with Window Sill		
Girl's Restroom across from Classroom 300	Expansion Seam Caulking		
Boy's Restroom across from Classroom 302	Transite associated with Window Sill		
Boy's Restroom across from Classroom 302	Expansion Seam Caulking		
Books B-3 Storage Room across from Classroom 302	Mastic associated with Floor Tile		
Books B-3 Storage Room across from Classroom 302	Floor Tile VAT 9" x 9"		
Books B-3 Storage Room across from Classroom 302	Expansion Seam Caulking		
Custodial Closet across from Classroom 300	Expansion Seam Caulking		
Classroom 302	Transite associated with Fuse Box		
Classroom 302	ACM Unit Ventilator		
Classroom 302	Mastic associated with Floor Tile		
Classroom 302	Floor Tile VAT 12" x 12"		
Classroom 302	Floor Tile VAT 9" x 9"		
Classroom 302	Transite associated with Window Sill		
Classroom 302	Transite associated with Closet		
Classroom 302	Glue Dots associated with Blackboard		
Classroom 302	Expansion Seam Caulking		
Classroom 303	Transite associated with Fuse Box		
Classroom 303	ACM Unit Ventilator		
Classroom 303	Mastic associated with Floor Tile		
Classroom 303	Floor Tile VAT 12" x 12"		
Classroom 303	Floor Tile VAT 9" x 9"		
Classroom 303	Floor Tile VAT 9" x 9"		
Classroom 303	Transite associated with Window Sill		
Classroom 303	Transite associated with Window Sill		
Classroom 303	Transite associated with Closet		
Classroom 303	Glue Dots associated with Blackboard		
Classroom 303	Expansion Seam Caulking		
Classroom 304	Transite associated with Fuse Box		
Classroom 304	ACM Unit Ventilator		
Classroom 304	Mastic associated with Floor Tile		
Classroom 304	Floor Tile VAT 9" x 9"		
Classroom 304	Transite associated with Window Sill		
Classroom 304	Transite associated with Closet		
Classroom 304	Glue Dots associated with Blackboard		
Classroom 304	Expansion Seam Caulking		
Classroom 305	Transite associated with Fuse Box		
Classroom 305	Floor Tile VAT 12" x 12"		
Classroom 305	Mastic associated with Floor Tile		
Classroom 305	Floor Tile VAT 9" x 9"		
Classroom 305	Transite associated with Window Sill		

Stephen Decatur School: Asbestos Hazard Report

Classroom 305	Transite associated with Closet		
Classroom 305	Glue Dots associated with Blackboard		
Classroom 305	Expansion Seam Caulking		
Classroom 305	ACM Unit Ventilator		
Classroom 306	Transite associated with Fuse Box		
Classroom 306	Mastic associated with Floor Tile		
Classroom 306	ACM Unit Ventilator		
Classroom 306	Floor Tile VAT 12" x 12"		
Classroom 306	Floor Tile VAT 9" x 9"		
Classroom 306	Transite associated with Window Sill		
Classroom 306	Transite associated with Closet		
Classroom 306	Expansion Seam Caulking		
Classroom 306	Expansion Seam Caulking		
Classroom 306	Glue Dots associated with Blackboard		
Women's Restroom across from Classroom 314	Transite associated with Stall, Restroom		
Women's Restroom across from Classroom 314	Expansion Seam Caulking		
Classroom 308	Transite associated with Fuse Box		
Classroom 308	Mastic associated with Floor Tile		
Classroom 308	ACM Unit Ventilator		
Classroom 308	Floor Tile VAT 12" x 12"		
Classroom 308	Floor Tile VAT 9" x 9"		
Classroom 308	Transite associated with Window Sill		
Classroom 308	Transite associated with Closet		
Classroom 308	Glue Dots associated with Blackboard		
Classroom 308	Expansion Seam Caulking		
Office 315 across from Classroom 314	Mastic associated with Floor Tile		
Office 315 across from Classroom 314	Floor Tile VAT 12" x 12"		
Office 315 across from Classroom 314	Floor Tile VAT 9" x 9"		
Office 315 across from Classroom 314	Transite associated with Window Sill		
Office 315 across from Classroom 314	Expansion Seam Caulking		
Classroom 310	Transite associated with Fuse Box		
Classroom 310	Mastic associated with Floor Tile		
Classroom 310	ACM Unit Ventilator		
Classroom 310	Glue Dots associated with Blackboard		
Classroom 310	Floor Tile VAT 9" x 9"		
Classroom 310	Transite associated with Window Sill		
Classroom 310	Transite associated with Closet		
Classroom 310	Expansion Seam Caulking		
Classroom 312	Transite associated with Fuse Box		
Classroom 312	Mastic associated with Floor Tile		
Classroom 312	ACM Unit Ventilator		
Classroom 312	Floor Tile VAT 9" x 9"		
Classroom 312	Transite associated with Window Sill		
Classroom 312	Transite associated with Closet		
Classroom 312	Glue Dots associated with Blackboard		
Classroom 312	Expansion Seam Caulking		
Classroom 314	Transite associated with Fuse Box		
Classroom 314	Mastic associated with Floor Tile		
Classroom 314	Floor Tile VAT 12" x 12"		
Classroom 314	Glue Dots associated with Blackboard		
Classroom 314	Floor Tile VAT 9" x 9"		
Classroom 314	Transite associated with Window Sill		
Classroom 314	Transite associated with Closet		
Classroom 314	Expansion Seam Caulking		

Stephen Decatur School: Asbestos Hazard Report

Classroom 314	ACM Unit Ventilator		
Computer Lab 316	Transite associated with Fuse Box		
Computer Lab 316	ACM Unit Ventilator		
Computer Lab 316	Mastic associated with Floor Tile		
Computer Lab 316	Expansion Seam Caulking		
Computer Lab 316	Floor Tile VAT 9" x 9"		
Computer Lab 316	Transite associated with Window Sill		
Computer Lab 316	Transite associated with Closet		
Computer Lab 316	Glue Dots associated with Blackboard		
Classroom 317	Transite associated with Fuse Box		
Classroom 317	Mastic associated with Floor Tile		
Classroom 317	Glue Dots associated with Blackboard		
Classroom 317	Floor Tile VAT 9" x 9"		
Classroom 317	Transite associated with Tabletop		
Classroom 317	Transite associated with Window Sill		
Classroom 317	Transite associated with Closet		
Classroom 317	Expansion Seam Caulking		
Classroom 317	ACM Unit Ventilator		
Classroom 318	Transite associated with Fuse Box		
Classroom 318	ACM Unit Ventilator		
Classroom 318	Mastic associated with Floor Tile		
Classroom 318	Floor Tile VAT 12" x 12"		
Classroom 318	Floor Tile VAT 9" x 9"	Damaged.	Removal of damaged material in Feb 2026.
Classroom 318	Transite associated with Window Sill		
Classroom 318	Transite associated with Closet		
Classroom 318	Glue Dots associated with Blackboard		
Classroom 318	Expansion Seam Caulking		
Classroom 319	Transite associated with Fuse Box		
Classroom 319	Mastic associated with Floor Tile		
Classroom 319	Floor Tile VAT 9" x 9"		
Classroom 319	Transite associated with Window Sill		
Classroom 319	Transite associated with Closet		
Classroom 319	Glue Dots associated with Blackboard		
Classroom 319	Expansion Seam Caulking		
Classroom 319	ACM Unit Ventilator		
Classroom 320	Transite associated with Fuse Box		
Classroom 320	Mastic associated with Floor Tile		
Classroom 320	Floor Tile VAT 12" x 12"		
Classroom 320	Floor Tile VAT 9" x 9"		
Classroom 320	Floor Tile VAT 9" x 9"		
Classroom 320	Transite associated with Window Sill		
Classroom 320	Transite associated with Closet		
Classroom 320	Glue Dots associated with Blackboard		
Classroom 320	Expansion Seam Caulking		
Classroom 320	ACM Unit Ventilator		
Gender Neutral/Mens Restroom across from Classroom 320	Expansion Seam Caulking		
Gender Neutral/Mens Restroom across from Classroom 320	Transite associated with Stall, Restroom		
Boy's Restroom across from Classroom 320	Transite associated with Window Sill		
Boy's Restroom across from Classroom 320	Expansion Seam Caulking		
Girl's Restroom near Classroom 320	Transite associated with Window Sill		
Girl's Restroom near Classroom 320	Expansion Seam Caulking		
Custodial Closet near Classroom 320	Expansion Seam Caulking		

Stephen Decatur School: Asbestos Hazard Report

Hallway from Classroom 300 to Classroom 310	Mastic associated with Floor Tile		
Hallway from Classroom 300 to Classroom 310	Floor Tile VAT 12" x 12"		
Hallway from Classroom 300 to Classroom 310	Transite associated with Fire Extinguisher Sill		
Hallway from Classroom 300 to Classroom 310	Floor Tile VAT 9" x 9"		
Hallway from Classroom 300 to Classroom 310	Expansion Seam Caulking		
Hallway from Stairwell #1 near Classroom 320 to Elevator and Classroom 312	Floor Tile VAT 12" x 12"		
Hallway from Stairwell #1 near Classroom 320 to Elevator and Classroom 312	Mastic associated with Floor Tile		
Hallway from Stairwell #1 near Classroom 320 to Elevator and Classroom 312	Transite associated with Fire Extinguisher Sill		
Hallway from Stairwell #1 near Classroom 320 to Elevator and Classroom 312	Floor Tile VAT 9" x 9"		
Hallway from Stairwell #1 near Classroom 320 to Elevator and Classroom 312	Expansion Seam Caulking		
Stairwell 3 across from Classroom 300	Transite associated with Window Sill		
Stairwell 3 across from Classroom 300	Expansion Seam Caulking		
Stairwell #1 near Classroom 320	Transite associated with Window Sill		
Stairwell #1 near Classroom 320	Expansion Seam Caulking		
Stairwell #2 across from Classroom 308	Expansion Seam Caulking		
Elevator Machine Room - entrance through S37-3	Transite associated with Electrical Panel		
Crawl Space accessible in Basement Boiler Room	Damp Proofing		
Exterior Facing Academy Road	Expansion Seam Caulking associated with Wall, Brick		
Exterior Facing Playground	Expansion Seam Caulking associated with Wall, Brick		
Exterior Facing Houses	Expansion Seam Caulking associated with Wall, Brick		
Exterior Facing Annex	Expansion Seam Caulking associated with Wall, Brick		
Boiler Room	Boiler Rope associated with Door, Boiler		
Boiler Room	Expansion Seam Caulking		
Restroom in Maintenance Staff Office	Expansion Seam Caulking		
Maintenance Staff Office	Expansion Seam Caulking		
Maintenance Supply and Equipment Storage Room in Cafeteria	Expansion Seam Caulking		
Maintenance Supply and Equipment Storage Room in Cafeteria	Expansion Seam Caulking		
Cafeteria	Transite associated with Fuse Box		
Cafeteria	ACM Unit Ventilator		
Cafeteria	Floor Tile VAT 12" x 12"		
Cafeteria	Expansion Seam Caulking		

Stephen Decatur School: Asbestos Hazard Report

Kitchen	Mastic associated with Floor Tile		
Kitchen	Floor Tile VAT 12" x 12"		
Kitchen	Floor Tile VAT 9" x 9"		
Kitchen	Floor Tile VAT 9" x 9"		
Kitchen	Expansion Seam Caulking		
Kitchen Office and Pantry	Mastic associated with Floor Tile		
Kitchen Office and Pantry	Expansion Seam Caulking		
Kitchen Office and Pantry	Floor Tile VAT 12" x 12"		
Kitchen Office and Pantry	Floor Tile VAT 9" x 9"		
Boy's Restroom near Cafeteria	Expansion Seam Caulking		
Gender Neutral Restroom across from Kitchen	Expansion Seam Caulking		
Gender Neutral Restroom across from Kitchen	Transite associated with Stall, Restroom		
Girl's Restroom near Kitchen	Expansion Seam Caulking		
Girl's Restroom in Gym	Expansion Seam Caulking		
Storage Room behind the Storage Room next to Boy's Restroom in Gym	Expansion Seam Caulking		
Storage Room next to Boy's Restroom in Gym	Expansion Seam Caulking		
Boy's Restroom in Gym	Expansion Seam Caulking		
Gym Office	Mastic associated with Floor Tile		
Gym Office	Expansion Seam Caulking		
Gym Office	Floor Tile VAT 9" x 9"		
Gym Office Restroom	Mastic associated with Floor Tile		
Gym Office Restroom	Expansion Seam Caulking		
Gym Office Restroom	Floor Tile VAT 9" x 9"		
Gym Office Restroom	Transite associated with Stall, Restroom		
Gymnasium	Transite associated with Fire Extinguisher Sill		
Gymnasium	Expansion Seam Caulking		
Storage Room in Gym next to Girl's Dressing Room	Mastic associated with Floor Tile		
Storage Room in Gym next to Girl's Dressing Room	Floor Tile VAT 9" x 9"		
Storage Room in Gym next to Girl's Dressing Room	Expansion Seam Caulking		
"Girl's Dressing" Room in Gym	Floor Tile VAT 12" x 12"		
"Girl's Dressing" Room in Gym	Mastic associated with Floor Tile		
"Girl's Dressing" Room in Gym	Expansion Seam Caulking		
Elevator	Mastic associated with Floor Tile		
Elevator	Floor Tile VAT 12" x 12"		
Hallway from Hall near Gym to Pantry	Mastic associated with Floor Tile		
Hallway from Hall near Gym to Pantry	Expansion Seam Caulking		
Hallway from Cafeteria to Gym	Mastic associated with Floor Tile		
Hallway from Cafeteria to Gym	Floor Tile VAT 12" x 12"		
Hallway from Cafeteria to Gym	Floor Tile VAT 12" x 12"		
Hallway from Cafeteria to Gym	Expansion Seam Caulking		
Hallway from Cafeteria to Boiler Room	Expansion Seam Caulking		
Back Stairwell in Boiler Room	Expansion Seam Caulking		
Stairwell in Cafeteria near Cage	Mastic associated with Floor Tile		
Stairwell in Cafeteria near Cage	Floor Tile VAT 12" x 12"		
Stairwell in Cafeteria near Cage	Expansion Seam Caulking		
Stairwell between Girl's Restroom and Gym	Mastic associated with Floor Tile		

Stephen Decatur School: Asbestos Hazard Report

Stairwell between Girl's Restroom and Gym	Floor Tile VAT 9" x 9"		
Stairwell between Girl's Restroom and Gym	Expansion Seam Caulking		
Library/IMC	Expansion Seam Caulking		
Hallway from Stairwell near Building Engineer's Office to IMC/Library	Floor Tile VAT 12" x 12"		
Hallway from Stairwell near Building Engineer's Office to IMC/Library	Expansion Seam Caulking		
Hallway from Stairwell near Building Engineer's Office to IMC/Library	Mastic associated with Floor Tile		
Classroom B1	Mastic associated with Floor Tile		
Classroom B1	Expansion Seam Caulking		
Classroom B1	Expansion Seam Caulking		
Classroom B1	Floor Tile VAT 12" x 12"		
Classroom B1	Floor Tile VAT 12" x 12"		
Classroom B1 Storage and Meter Room	Mastic associated with Floor Tile		
Classroom B1 Storage and Meter Room	Expansion Seam Caulking		
Classroom B1 Storage and Meter Room	Floor Tile VAT 12" x 12"		
Classroom B1 Restroom	Mastic associated with Floor Tile		
Classroom B1 Restroom	Expansion Seam Caulking		
Classroom B1 Restroom	Floor Tile VAT 12" x 12"		
Classroom B2	Mastic associated with Floor Tile		
Classroom B2	Expansion Seam Caulking		
Classroom B2	Floor Tile VAT 12" x 12"		
Classroom B2	Floor Tile VAT 12" x 12"		
Classroom B2 Closet	Mastic associated with Floor Tile		
Classroom B2 Closet	Expansion Seam Caulking		
Classroom B2 Closet	Floor Tile VAT 12" x 12"		
Classroom B2 Restroom	Mastic associated with Floor Tile		
Classroom B2 Restroom	Expansion Seam Caulking		
Classroom B2 Restroom	Floor Tile VAT 12" x 12"		
Classroom B3	Mastic associated with Floor Tile		
Classroom B3	Expansion Seam Caulking		
Classroom B3	Floor Tile VAT 12" x 12"		
Classroom B3	Floor Tile VAT 12" x 12"		
Classroom B3 Restroom	Mastic associated with Floor Tile		
Classroom B3 Restroom	Expansion Seam Caulking		
Classroom B3 Restroom	Floor Tile VAT 12" x 12"		
Classroom B3 Closet	Mastic associated with Floor Tile		
Classroom B3 Closet	Expansion Seam Caulking		
Classroom B3 Closet	Floor Tile VAT 12" x 12"		
Classroom B4	Mastic associated with Floor Tile		
Classroom B4	Expansion Seam Caulking		
Classroom B4	Floor Tile VAT 12" x 12"		
Classroom B4	Floor Tile VAT 12" x 12"		
Classroom B4 Restroom	Mastic associated with Floor Tile		
Classroom B4 Restroom	Expansion Seam Caulking		
Classroom B4 Restroom	Floor Tile VAT 12" x 12"		
Classroom B4 Closet	Mastic associated with Floor Tile		
Classroom B4 Closet	Expansion Seam Caulking		

Stephen Decatur School: Asbestos Hazard Report

Classroom B4 Closet	Floor Tile VAT 12" x 12"		
Hallway from Classroom B4 - B1	Mastic associated with Floor Tile		
Hallway from Classroom B4 - B1	Expansion Seam Caulking		
Hallway from Classroom B4 - B1	Floor Tile VAT 12" x 12"		
Hallway from Classroom B4 - B1	Floor Tile VAT 12" x 12"		
Exterior Facing Houses	Expansion Seam Caulking associated with Wall, Concrete		
Exterior Facing Academy Road	Expansion Seam Caulking associated with Wall, Concrete		
Exterior Facing Playground	Expansion Seam Caulking associated with Wall, Concrete		
Exterior Facing Field	Expansion Seam Caulking associated with Wall, Concrete		
Girl's Restroom	Thinset associated with Floor, Ceramic Tile		
Classroom A1	Glue Dots associated with Blackboard		
Boy's Restroom	Thinset associated with Floor, Ceramic Tile		
Classroom A2	Glue Dots associated with Blackboard		
Staff Restroom next to Boy's Restroom	Thinset associated with Floor, Ceramic Tile		
Classroom A3	Glue Dots associated with Blackboard		
Staff Restroom next to Teacher's Closet	Thinset associated with Floor, Ceramic Tile		
Classroom A4	Glue Dots associated with Blackboard		
Classroom A5	Glue Dots associated with Blackboard		
Classroom A6	Glue Dots associated with Blackboard		
Classroom A7	Glue Dots associated with Blackboard		
Classroom A7	Mastic associated with Floor Tile		
Classroom A7	Floor Tile VAT 12" x 12"		
Classroom A8	Glue Dots associated with Blackboard		
Classroom A9	Glue Dots associated with Blackboard		
Classroom A9	Mastic associated with Floor Tile		
Classroom A9	Floor Tile VAT 12" x 12"		
Classroom A10	Glue Dots associated with Blackboard		
Classroom A10	Mastic associated with Floor Tile		
Classroom A10	Floor Tile VAT 12" x 12"		
Hallway from near Classroom A8 to Exit Doors	Mastic associated with Floor Tile		
Hallway from near Classroom A8 to Exit Doors	Floor Tile VAT 12" x 12"		