

# Lewis Elkin Elementary School: Asbestos Hazard Report

The Philadelphia Regional Center for Children's Environmental Health has partnered with the Healthy Schools Initiative to analyze and report on public information regarding asbestos conditions in schools made available on the School District of Philadelphia's website.

This report is meant to communicate to parents, teachers, and staff the exposure risk at their school and help prioritize the removal of asbestos in high-risk exposure locations.

Our analysis is based on publicly available reports. We have not conducted inspections or verified the reports.

## Key Findings:

- 116 teacher / student occupied spaces have **asbestos containing material (ACM)**
- 22 spaces contained friable ACM
- ★ 0 spaces had damaged ACM

## Our Recommendations:

- The School District is required to regularly monitor the condition of their ACM by the EPA. As of the most recent report from July 2024, there is no damaged ACM in the school. We recommend frequent monitoring of all ACM, especially ceiling tile and sheetrock wall which if damaged is considered friable as listed in Table 1 of this report. Teachers, staff, and parents should report any damaged ACM to their principal immediately.



## What is asbestos?

**Asbestos is a fibrous material that is resistant to heat, water, and corrosion.**

See this link for a comprehensive list: <https://prcceh.upenn.edu/asbestos>

## Asbestos was used in materials in schools, including:

- Ceiling Tiles
- Floor Tiles
- Pipe Insulation
- Cement
- Paint and Caulk
- Soundproofing
- Fireproofing
- Plaster Materials

## What are the health effects of asbestos?

No immediate health impacts are expected from asbestos exposure in schools. However, breathing asbestos fibers in schools may increase the risk of developing cancer many years from now.

Children are very active, breathing more air while running and playing. Children take more breaths per minute than adults and are lower to the ground where asbestos fibers may settle. This puts them at an increased risk for asbestos exposure.

## How are damaged asbestos containing materials managed?

Asbestos can be removed. Sometimes damaged materials are managed in place by patching, encapsulating (using a specially formulated paint-like coating) or building an enclosure around damaged and/or accessible materials. All of these are forms of abatement.

The Environmental Protection Agency requires all remaining asbestos containing material to be inspected by the school district every six months. This is documented in an Asbestos Hazard Emergency Response Act Report (AHERA Report).

## Are all asbestos containing materials of equal risk?

Some asbestos containing materials like ceiling and floor tiles have asbestos fibers imbedded in other materials. As long as they are not broken or damaged the asbestos fibers are not released into the air.

Some asbestos containing materials like insulation on pipe remains fibrous and can easily be released in the air when damaged.

### Important Terms

*Get to know these terms to make the most out of this report.*

**Damaged Asbestos Containing Material (ACM)** can release asbestos fibers into the air.

**Friable Materials** can be reduced to a powder by applying hand pressure. **DO NOT TOUCH!**

**Non-Friable materials** are not easily damaged.

**Significantly damaged materials** are more than 10% damaged.

**Abated ACM** means repaired, removed, or reduced risk of exposure.

## Detailed Review for Lewis Elkin Elementary School

This school has 126 spaces with asbestos containing materials. 116 of them are in teacher / student occupied spaces. The School District last inspected ACM in July 2024 and published the AHERA report in September 2024. No damaged ACM were reported on this AHERA report.



We recommend that the school district continue to frequently monitor friable asbestos containing materials for damage. The only friable material found in the most recent report was ceiling tile and sheetrock wall in several areas throughout the school (see table 1). The little school house only had 1 ACM and it was nonfriable floor tile.

### Information Reviewed to Make this Report:

The 2024/25 AHERA report from the School District of Philadelphia was reviewed.

To see the most current information, scan these QR Codes. After scanning, search for your school.

### School Districts of Philadelphia Asbestos Reports:



AHERA Reports are documents generated from EPA required asbestos inspections



Report what you see!

Parents and teachers should report hazardous conditions in schools on the Healthy Schools app.

Scan here to download the app:



### Disclaimer:

This report analyzes custodial and mechanical spaces like boiler rooms **only** when ACM is significantly damaged (damage > 10%).

## Questions?

Find more resources on our website!

[prcceb.upenn.edu/asbestos](http://prcceb.upenn.edu/asbestos)

- Photo gallery of different types of damaged asbestos containing materials
- Guide to how we classify materials in schools
- Our analysis and reporting methodology
- What we do with the information in this report



Email us at [prcceb@penmedicine.upenn.edu](mailto:prcceb@penmedicine.upenn.edu) or call 215-573-9076

Table 1: Friable Asbestos Containing Materials Identified in Main Building

**NOTE: Friable materials can be reduced to a powder by applying hand pressure. *Do not touch it!* Damaged and significantly damaged friable materials readily release harmful asbestos fibers into the air.**

Location	Friable Asbestos Containing Material	Reported as Damaged or Significantly Damaged? (Blank = No)
Main Office	Sheetrock/Joint Compound Wall	
Office next to Main Office Storage Room	Ceiling Tile 2' x 2'	
Main Office Storage Room	Ceiling Tile 2' x 2'	
Main Office Conference Room	Ceiling Tile 2' x 2'	
Principal's Office Small Closet	Ceiling Tile 2' x 2'	
Office across from Principal's Office	Ceiling Tile 2' x 2'	
Classroom 102	Sheetrock Wall associated with Unit Ventilator	
Classroom 104	Sheetrock Wall associated with Unit Ventilator	
Classroom 105	Sheetrock Wall associated with Unit Ventilator	
Classroom 109	Sheetrock Wall associated with Unit Ventilator	
Main Office	Sheetrock/Joint Compound Wall	
COMHAR Waiting Area	Ceiling Tile 2' x 2'	
COMHAR Office Storage Room	Ceiling Tile 2' x 2'	
Counselor's Office 118	Ceiling Tile 2' x 2'	
Women's Lounge outside Restroom	Ceiling Tile 2' x 2'	
Mail Room	Ceiling Tile 2' x 2'	
Office adjacent to Mail Room	Ceiling Tile 2' x 2'	
Office next to Mail Room - Large Closet	Ceiling Tile 2' x 2'	
Office next to Mail Room - Closet on Main Office Side	Ceiling Tile 2' x 2'	

# Lewis Elkin Elementary School: Asbestos Hazard Report



Telecommunication Equipment Room	Ceiling Tile 2' x 2'	
Telecommunication Equipment Room	Sheetrock/Joint Compound Wall	
Main Office Hallway	Ceiling Tile 2' x 2'	
IMC Kitchen Office	Sheetrock/Joint Compound Wall	

**Table 2: Non-Friable Asbestos Containing Materials Identified in Main Building**

**NOTE: Significantly Damaged non-friable materials (damage ≥ 10% of the material) can release harmful asbestos fibers into the air.**

Location	Material Name	Reported as Damaged or Significantly Damaged?
Auditorium/Cafeteria	Mastic associated with Floor Tile	
Auditorium/Cafeteria	Floor Tile VAT 12" x 12"	
Auditorium/Cafeteria	Floor Tile VAT 12" x 12"	
Auditorium/Cafeteria	Transite associated with Fire Extinguisher Sill	
Auditorium/Cafeteria	Expansion Seam Caulking	
Auditorium Stage	Floor Tile VAT 12" x 12"	
Art Room	Expansion Seam Caulking associated with Wall, CMU	
Art Room	Floor Tile VAT 12" x 12"	
Art Room	Mastic	
Art Room	Sink Undercoat Mastic	
Art Room	Glue Dots associated with Blackboard	
Storage Room adjacent to Stairwell 2	Expansion Seam Caulking associated with Wall, CMU	
Crawlspace between Stairwell 2 and Classroom B02	Expansion Seam Caulking associated with Wall, CMU	
Classroom B02	Expansion Seam Caulking associated with Wall, CMU	
Classroom B02	Glue Dots associated with Blackboard	
Classroom B03	Expansion Seam Caulking associated with Wall, CMU	
Classroom B03	Glue Dots associated with Blackboard	
Classroom B03	Floor Tile VAT 12" x 12"	
Classroom B03 Closet adjacent to Hallway	Mastic associated with Floor Tile	
Classroom B03 Closet adjacent to Hallway	Expansion Seam Caulking	
Classroom B03 Closet adjacent to Hallway	Floor Tile VAT 12" x 12"	
Classroom B03 Closet adjacent to Classroom B02	Mastic associated with Floor Tile	
Classroom B03 Closet adjacent to Classroom B02	Expansion Seam Caulking	
Classroom B03 Closet adjacent to Classroom B02	Floor Tile VAT 12" x 12"	
Classroom B04	Floor Tile VAT 12" x 12"	
Classroom B04	Glue Dots associated with Blackboard	
Classroom B04	Mastic associated with Floor Tile	

# Lewis Elkin Elementary School: Asbestos Hazard Report

Boy's Restroom Elevator Mechanical Room	Expansion Seam Caulking	
Gymnasium	Mastic associated with Floor Tile	
Vestibule outside Girl's Locker Room	Expansion Seam Caulking	
Gym Storage Room	Expansion Seam Caulking associated with Wall, CMU	
Gym Office	Floor Tile VAT 12" x 12"	
Vestibule outside Boy's Locker Room	Expansion Seam Caulking	
Cafeteria Staff Locker Room	Floor Tile VAT 12" x 12"	
Kitchen	Expansion Seam Caulking associated with Wall, CMU	
Kitchen Serving Area	Expansion Seam Caulking	
Teacher Lounge	Floor Tile VAT 12" x 12"	
Teacher Lounge	Glue Dots associated with Wall, Wood	
Teacher Lounge	Expansion Seam Caulking associated with Wall, CMU	
Teacher Lounge	Floor Tile VAT 12" x 12"	
Teacher Lounge	Floor Tile VAT 12" x 12"	
Vestibule outside Building Engineer's Restroom	Floor Tile VAT 12" x 12"	
Electrical Room	Expansion Seam Caulking	
Electrical Room Behind BE Office	Expansion Seam Caulking	
Elevator	Floor Tile VAT 12" x 12"	
Hallway outside Art Room	Transite associated with Fire Extinguisher Sill	
Hallway outside Art Room	Floor Tile VAT 12" x 12"	
Hallway outside Classroom B03	Transite associated with Fire Extinguisher Sill	
Hallway outside Classroom B03	Floor Tile VAT 12" x 12"	
Hallway to Classroom B02	Transite associated with Fire Extinguisher Sill	
Hallway to Classroom B02	Floor Tile VAT 12" x 12"	
Hallway from Stairwell 4 to Cafeteria	Mastic associated with Floor Tile	
Hallway from Stairwell 4 to Cafeteria	Floor Tile VAT 12" x 12"	
Hallway from Stairwell 4 to Cafeteria	Floor Tile VAT 12" x 12"	
Hallway from Stairwell 4 to Cafeteria	Floor Tile VAT 12" x 12"	
Hallway from Stairwell 4 to Cafeteria	Transite associated with Fire Extinguisher Sill	
Hallway outside Elevator and Boy's Restroom	Floor Tile VAT 12" x 12"	
Hallway outside Building Engineer's Office	Mastic associated with Floor Tile	
Hallway outside Building Engineer's Office	Floor Tile VAT 12" x 12"	
Hallway outside Building Engineer's Office	Floor Tile VAT 12" x 12"	
Hallway from Building Engineer's Office to Loading Dock	Floor Tile VAT 12" x 12"	
Hallway from Building Engineer's Office to Loading Dock	Floor Tile VAT 12" x 12"	
Hallway from Building Engineer's Office to Loading Dock	Floor Tile VAT 12" x 12"	
Hallway outside Schoolyard Entrance	Mastic associated with Floor Tile	
Hallway outside Schoolyard Entrance	Floor Tile VAT 12" x 12"	
Hallway from Teacher's Lounge to Cafeteria	Floor Tile VAT 12" x 12"	

# Lewis Elkin Elementary School: Asbestos Hazard Report

Food Services Storeroom/Loading Dock next to Boys Shower	Expansion Seam Caulking associated with Wall, CMU	
Hallway to Gym	Transite associated with Fire Extinguisher Sill	
Hallway to Gym	Floor Tile VAT 12" x 12"	
Crawlspace adjacent to Art Room	Expansion Seam Caulking associated with Wall, CMU	
Stairwell 2	Floor Tile VAT 12" x 12"	
Stairwell 1	Floor Tile VAT 12" x 12"	
Stairwell 3	Floor Tile VAT 12" x 12"	
Stairwell 4	Floor Tile VAT 12" x 12"	
Stairwell 4	Transite associated with Fire Extinguisher Sill	
Stairs to back of Stage	Expansion Seam Caulking	
Stairs to back of Stage	Floor Tile VAT 12" x 12"	
Office next to Main Office Storage Room	Expansion Seam Caulking	
Main Office Storage Room	Mastic associated with Floor Tile	
Main Office Storage Room	Floor Tile VAT 12" x 12"	
Main Office Conference Room	Glue Dots associated with Blackboard	
Main Office Conference Room	Floor Tile VAT 12" x 12"	
Principal's Office	Expansion Seam Caulking	
Principal's Office	Floor Tile VAT 12" x 12"	
Principal's Office Small Closet	Floor Tile VAT 12" x 12"	
Office across from Principal's Office	Expansion Seam Caulking	
Office across from Principal's Office	Floor Tile VAT 12" x 12"	
Vice-Principal's Office	Expansion Seam Caulking	
Vice-Principal's Office	Mastic associated with Floor Tile	
Vice-Principal's Office	Floor Tile VAT 12" x 12"	
Vice-Principal's Office	Floor Tile VAT 12" x 12"	
Principal's Office Large Closet	Floor Tile VAT 12" x 12"	
Classroom 102	Mastic associated with Floor Tile	
Classroom 102	Glue Dots associated with Blackboard	
Classroom 102	Floor Tile VAT 12" x 12"	
Classroom 102	Floor Tile VAT 12" x 12"	
Classroom 102	Floor Tile VAT 12" x 12"	
Classroom 102	Expansion Seam Caulking	
Classroom 102 Restroom	Expansion Seam Caulking	
Classrooms 102 and 103 Staff Restroom	Expansion Seam Caulking	
Classroom 103	Glue Dots associated with Blackboard	
Classroom 103	Floor Tile VAT 12" x 12"	
Classroom 103	Expansion Seam Caulking	
Classroom 101	Glue Dots associated with Blackboard	
Classroom 101	Floor Tile VAT 12" x 12"	
Classroom 101	Expansion Seam Caulking	
Classroom 103 Restroom	Expansion Seam Caulking	
Mechanical Closet Between Classrooms 104 and 105	Expansion Seam Caulking	
Classroom 104 Closet	Expansion Seam Caulking	

# Lewis Elkin Elementary School: Asbestos Hazard Report

Classrooms 104 and 105 Staff Restroom	Expansion Seam Caulking	
Classroom 104	Floor Tile VAT 12" x 12"	
Classroom 104	Floor Tile VAT 12" x 12"	
Classroom 104	Glue Dots associated with Blackboard	
Classroom 104	Floor Tile VAT 12" x 12"	
Classroom 104 Restroom	Expansion Seam Caulking	
Classroom 105	Glue Dots associated with Blackboard	
Classroom 105	Floor Tile VAT 12" x 12"	
Classroom 105	Floor Tile VAT 12" x 12"	
Classroom 105	Floor Tile VAT 12" x 12"	
Classroom 105	Expansion Seam Caulking	
Classroom 105 Restroom	Expansion Seam Caulking	
Classroom 106	Glue Dots associated with Blackboard	
Classroom 106	Expansion Seam Caulking	
Classroom 108	Glue Dots associated with Blackboard	
Classroom 108	Floor Tile VAT 12" x 12"	
Classroom 108	Floor Tile VAT 12" x 12"	
Classroom 108	Expansion Seam Caulking	
Classroom 107	Mastic associated with Floor Tile	
Classroom 107	Glue Dots associated with Blackboard	
Classroom 107	Expansion Seam Caulking	
Classroom 107 Closet	Expansion Seam Caulking	
Classroom 107 Restroom	Expansion Seam Caulking	
Classroom 110	Glue Dots associated with Blackboard	
Classroom 110	Floor Tile VAT 12" x 12"	
Classroom 110	Floor Tile VAT 12" x 12"	
Classroom 110	Expansion Seam Caulking	
Classroom 110 Restroom	Expansion Seam Caulking	
Classroom 109	Glue Dots associated with Blackboard	
Classroom 109	Floor Tile VAT 12" x 12"	
Classroom 109	Expansion Seam Caulking	
COMHAR Waiting Area	Expansion Seam Caulking	
COMHAR Waiting Area	Floor Tile VAT 12" x 12"	
Classroom 111	Glue Dots associated with Blackboard	
Classroom 111	Floor Tile VAT 12" x 12"	
Classroom 111	Expansion Seam Caulking	
COMHAR Office Restroom	Expansion Seam Caulking	
Closet in 211A	Expansion Seam Caulking	
COMHAR Office Storage Room	Expansion Seam Caulking	
COMHAR Office Storage Room	Floor Tile VAT 12" x 12"	
COMHAR Office Storage Room	Floor Tile VAT 12" x 12"	
Comhar classroom	Floor Tile VAT 12" x 12"	
Comhar classroom	Floor Tile VAT 12" x 12"	
COMHAR Office	Floor Tile VAT 12" x 12"	
COMHAR Office	Expansion Seam Caulking	



# Lewis Elkin Elementary School: Asbestos Hazard Report

COMHAR Exam Room	Floor Tile VAT 12" x 12"	
Storage Room behind Elevator	Expansion Seam Caulking	
Classroom 114	Glue Dots associated with Blackboard	
Classroom 114	Floor Tile VAT 12" x 12"	
Classroom 114	Expansion Seam Caulking	
Large Conference Room	Sink Undercoat Mastic	
Large Conference Room	Glue Dots associated with Blackboard	
Large Conference Room	Floor Tile VAT 12" x 12"	
Large Conference Room	Floor Tile VAT 12" x 12"	
Classroom 113	Glue Dots associated with Blackboard	
Classroom 113	Floor Tile VAT 12" x 12"	
Classroom 113	Expansion Seam Caulking	
Storeroom across from Girl's Restroom	Expansion Seam Caulking	
Boy's Restroom	Expansion Seam Caulking	
Classroom 112	Glue Dots associated with Blackboard	
Classroom 112	Floor Tile VAT 12" x 12"	
Classroom 112	Floor Tile VAT 12" x 12"	
Classroom 112	Expansion Seam Caulking	
Custodial Closet adjacent to Elevator	Expansion Seam Caulking	
Girl's Restroom	Expansion Seam Caulking	
Counselor's Office 118	Floor Tile VAT 12" x 12"	
Counselor's Office 118	Expansion Seam Caulking	
Reflection Room Vestibule	Floor Tile VAT 12" x 12"	
Health Room	Floor Tile VAT 12" x 12"	
Health Room	Expansion Seam Caulking	
Reflection Room	Sink Undercoat Mastic	
Reflection Room	Floor Tile VAT 12" x 12"	
Reflection Room	Expansion Seam Caulking	
Counselor's Office 119	Floor Tile VAT 12" x 12"	
Counselor's Office 119	Expansion Seam Caulking	
School Police Office	Expansion Seam Caulking	
School Police Office	Floor Tile VAT 12" x 12"	
Women's Lounge outside Restroom	Floor Tile VAT 12" x 12"	
Women's Lounge outside Restroom	Expansion Seam Caulking	
Gender Neutral Restroom	Expansion Seam Caulking	
Women's Restroom	Expansion Seam Caulking	
Mail Room	Floor Tile VAT 12" x 12"	
Mail Room	Floor Tile VAT 12" x 12"	
Mail Room	Floor Tile VAT 12" x 12"	
Office adjacent to Mail Room	Expansion Seam Caulking	
Office adjacent to Mail Room	Floor Tile VAT 12" x 12"	
Office next to Mail Room - Large Closet	Expansion Seam Caulking	
Office next to Mail Room - Large Closet	Floor Tile VAT 12" x 12"	
Office next to Mail Room - Closet on Main Office Side	Expansion Seam Caulking	

# Lewis Elkin Elementary School: Asbestos Hazard Report

Office next to Mail Room - Closet on Main Office Side	Floor Tile VAT 12" x 12"	
Office adjacent to Nurse's Office	Expansion Seam Caulking	
Office adjacent to Nurse's Office	Glue Dots associated with Blackboard	
Office adjacent to Nurse's Office	Floor Tile VAT 12" x 12"	
Telecommunication Equipment Room	Floor Tile VAT 12" x 12"	
Main Lobby	Floor Tile VAT 12" x 12"	
Main Lobby	Floor Tile VAT 12" x 12"	
Main Lobby	Expansion Seam Caulking	
Hallway outside Stairwell 1	Mastic associated with Floor Tile	
Hallway outside Stairwell 1	Floor Tile VAT 12" x 12"	
Hallway outside Stairwell 1	Floor Tile VAT 12" x 12"	
Hallway outside Stairwell 1	Floor Tile VAT 12" x 12"	
Hallway outside Stairwell 1	Expansion Seam Caulking	
Hallway from 2nd Floor Women's Restroom to Elevator	Mastic associated with Floor Tile	
Hallway from 2nd Floor Women's Restroom to Elevator	Floor Tile VAT 12" x 12"	
Hallway from 2nd Floor Women's Restroom to Elevator	Floor Tile VAT 12" x 12"	
Hallway from 2nd Floor Women's Restroom to Elevator	Floor Tile VAT 12" x 12"	
Hallway from 2nd Floor Women's Restroom to Elevator	Expansion Seam Caulking	
Hallway outside Offices 118-120	Floor Tile VAT 12" x 12"	
Hallway outside Offices 118-120	Floor Tile VAT 12" x 12"	
Hallway outside Offices 118-120	Expansion Seam Caulking	
Hallway outside Classrooms 101-102	Expansion Seam Caulking	
Hallway outside Classrooms 101-102	Floor Tile VAT 12" x 12"	
Hallway outside Classrooms 101-102	Floor Tile VAT 12" x 12"	
Hallway outside Classrooms 101-102	Floor Tile VAT 12" x 12"	
Hallway outside Classrooms 101-102	Transite associated with Fire Extinguisher Sill	
Hallway from Elevator to Stairwell 2	Floor Tile VAT 12" x 12"	
Hallway from Elevator to Stairwell 2	Floor Tile VAT 12" x 12"	
Hallway from Elevator to Stairwell 2	Floor Tile VAT 12" x 12"	
Hallway from Elevator to Stairwell 2	Transite associated with Fire Extinguisher Sill	
Stairwell 3 Hallway	Mastic associated with Floor Tile	
Stairwell 3 Hallway	Floor Tile VAT 12" x 12"	
Stairwell 3 Hallway	Floor Tile VAT 12" x 12"	
Stairwell 3 Hallway	Transite associated with Fire Extinguisher Sill	
Stairwell 3 Hallway	Expansion Seam Caulking	
Hallway outside Classroom 116 and Office 117	Mastic associated with Floor Tile	
Hallway outside Classroom 116 and Office 117	Floor Tile VAT 12" x 12"	
Hallway outside Classroom 116 and Office 117	Expansion Seam Caulking	
Main Office Hallway	Expansion Seam Caulking	
Main Office Hallway	Floor Tile VAT 12" x 12"	

# Lewis Elkin Elementary School: Asbestos Hazard Report

Book Closet across from Classroom 107	Expansion Seam Caulking	
Stairwell 2	Expansion Seam Caulking	
Stairwell 2 Hallway	Mastic associated with Floor Tile	
Stairwell 2 Hallway	Floor Tile VAT 12" x 12"	
Stairwell 2 Hallway	Transite associated with Fire Extinguisher Sill	
Stairwell 1	Expansion Seam Caulking	
Stairwell 3	Expansion Seam Caulking	
Stairwell 4	Expansion Seam Caulking	
Stairwell 4 Hallway	Floor Tile VAT 12" x 12"	
Stairwell 4 Hallway	Mastic associated with Floor Tile	
Stairwell 4 Hallway	Transite associated with Fire Extinguisher Sill	
Stairwell 4 Hallway	Expansion Seam Caulking	
Classroom 201	Sink Undercoat Mastic	
Classroom 201	Glue Dots associated with Blackboard	
Classroom 201	Floor Tile VAT 12" x 12"	
Classroom 201	Floor Tile VAT 12" x 12"	
Classroom 201	Expansion Seam Caulking	
Classroom 204	Sink Undercoat Mastic	
Classroom 204	Glue Dots associated with Blackboard	
Classroom 204	Floor Tile VAT 12" x 12"	
Classroom 204	Expansion Seam Caulking	
Classroom 204A	Glue Dots associated with Blackboard	
Classroom 204A	Floor Tile VAT 12" x 12"	
Classroom 204A	Expansion Seam Caulking	
Classroom 203	Mastic associated with Floor Tile	
Classroom 203	Glue Dots associated with Blackboard	
Classroom 203	Floor Tile VAT 12" x 12"	
Classroom 203	Expansion Seam Caulking	
Classroom 207A	Mastic associated with Floor Tile	
Classroom 207A	Expansion Seam Caulking	
Classroom 207A	Glue Dots associated with Blackboard	
Classroom 207A	Floor Tile VAT 12" x 12"	
Classroom 202	Sink Undercoat Mastic	
Classroom 202	Glue Dots associated with Blackboard	
Classroom 202	Floor Tile VAT 12" x 12"	
Classroom 202	Expansion Seam Caulking	
Classroom 206	Mastic associated with Floor Tile	
Classroom 206	Sink Undercoat Mastic	
Classroom 206	Glue Dots associated with Blackboard	
Classroom 206	Floor Tile VAT 12" x 12"	
Classroom 206	Floor Tile VAT 12" x 12"	
Classroom 206	Expansion Seam Caulking	
Classroom 207	Sink Undercoat Mastic	
Classroom 207	Glue Dots associated with Blackboard	
Classroom 207	Floor Tile VAT 12" x 12"	

# Lewis Elkin Elementary School: Asbestos Hazard Report

Classroom 208	Mastic associated with Floor Tile	
Classroom 208	Sink Undercoat Mastic	
Classroom 208	Glue Dots associated with Blackboard	
Classroom 208	Floor Tile VAT 12" x 12"	
Classroom 208	Floor Tile VAT 12" x 12"	
Classroom 208	Expansion Seam Caulking	
Classroom 211A	Floor Tile VAT 12" x 12"	
Classroom 211A	Glue Dots associated with Blackboard	
Classroom 211A	Floor Tile VAT 12" x 12"	
Classroom 211A	Expansion Seam Caulking	
Classroom 205	Mastic associated with Floor Tile	
Classroom 205	Sink Undercoat Mastic	
Classroom 205	Glue Dots associated with Blackboard	
Classroom 205	Floor Tile VAT 12" x 12"	
Classroom 205	Floor Tile VAT 12" x 12"	
Classroom 205	Floor Tile VAT 12" x 12"	
Classroom 205	Expansion Seam Caulking	
Classroom 209	Mastic associated with Floor Tile	
Classroom 209	Sink Undercoat Mastic	
Classroom 209	Glue Dots associated with Blackboard	
Classroom 209	Floor Tile VAT 12" x 12"	
Classroom 209	Expansion Seam Caulking	
Storage Room across from Classroom 209	Mastic associated with Floor Tile	
Classroom 212	Glue Dots associated with Blackboard	
Classroom 212	Floor Tile VAT 12" x 12"	
Classroom 212	Floor Tile VAT 12" x 12"	
Classroom 212	Expansion Seam Caulking	
Storage Room behind Elevator	Expansion Seam Caulking	
Classroom 211	Sink Undercoat Mastic	
Classroom 211	Glue Dots associated with Blackboard	
Classroom 211	Floor Tile VAT 12" x 12"	
Classroom 211	Floor Tile VAT 12" x 12"	
Classroom 211	Floor Tile VAT 12" x 12"	
Classroom 211	Expansion Seam Caulking	
Classroom 215A	Glue Dots associated with Blackboard	
Classroom 215A	Floor Tile VAT 12" x 12"	
Classroom 215A	Floor Tile VAT 12" x 12"	
Classroom 215A	Expansion Seam Caulking	
Classroom 210	Sink Undercoat Mastic	
Classroom 210	Glue Dots associated with Blackboard	
Classroom 210	Floor Tile VAT 12" x 12"	
Classroom 210	Expansion Seam Caulking	
Classroom 217 Closet	Expansion Seam Caulking	
Classroom 218	Sink Undercoat Mastic	
Classroom 218	Glue Dots associated with Blackboard	

# Lewis Elkin Elementary School: Asbestos Hazard Report

Classroom 218	Floor Tile VAT 12" x 12"	
Classroom 218	Floor Tile VAT 12" x 12"	
Classroom 218	Expansion Seam Caulking	
Storage Room adjacent to Classroom 218	Expansion Seam Caulking	
Speech Pathologist Office, Former Men's Lounge	Floor Tile VAT 12" x 12"	
Speech Pathologist Office, Former Men's Lounge	Expansion Seam Caulking	
Speech Pathologist Office, Former Men's Lounge	Floor Tile VAT 12" x 12"	
Classroom 217	Transite associated with Sink	
Classroom 217	Mastic associated with Floor Tile	
Classroom 217	Floor Tile VAT 12" x 12"	
Classroom 217	Glue Dots associated with Blackboard	
Classroom 217	Floor Tile VAT 12" x 12"	
Classroom 217	Expansion Seam Caulking	
Boy's Restroom	Expansion Seam Caulking	
Classroom 213	Glue Dots associated with Blackboard	
Classroom 213	Floor Tile VAT 12" x 12"	
Classroom 213	Expansion Seam Caulking	
Custodial Closet adjacent to Elevator	Expansion Seam Caulking	
Girl's Restroom	Expansion Seam Caulking	
Women's Lounge outside Restroom	Floor Tile VAT 12" x 12"	
IMC Kitchen	Mastic associated with Floor Tile	
IMC Kitchen	Sink Undercoat Mastic	
IMC Kitchen	Floor Tile VAT 12" x 12"	
IMC Kitchen	Expansion Seam Caulking	
IMC Kitchen Office	Floor Tile VAT 12" x 12"	
IMC Storage Room	Mastic associated with Floor Tile	
IMC Storage Room	Sink Undercoat Mastic	
IMC Storage Room	Expansion Seam Caulking	
IMC Copy Room	Floor Tile VAT 12" x 12"	
Hallway outside Classrooms 217 and 218	Transite associated with Fire Extinguisher Sill	
Hallway outside Classrooms 217 and 218	Floor Tile VAT 12" x 12"	
Hallway outside Classrooms 217 and 218	Floor Tile VAT 12" x 12"	
Hallway outside Classrooms 209, 212, and 213	Mastic associated with Floor Tile	
Hallway outside Classrooms 209, 212, and 213	Floor Tile VAT 12" x 12"	
Hallway outside Classrooms 209, 212, and 213	Floor Tile VAT 12" x 12"	
Hallway outside Classrooms 209, 212, and 213	Floor Tile VAT 12" x 12"	
Hallway outside Classrooms 209, 212, and 213	Floor Tile VAT 12" x 12"	
Hallway outside Classrooms 209, 212, and 213	Transite associated with Fire Extinguisher Sill	

# Lewis Elkin Elementary School: Asbestos Hazard Report

Stairwell 3 Hallway	Floor Tile VAT 12" x 12"	
Stairwell 3 Hallway	Transite associated with Fire Extinguisher Sill	
Stairwell 4 Hallway	Mastic associated with Floor Tile	
Stairwell 4 Hallway	Floor Tile VAT 12" x 12"	
Stairwell 4 Hallway	Floor Tile VAT 12" x 12"	
Stairwell 4 Hallway	Floor Tile VAT 12" x 12"	
Stairwell 4 Hallway	Transite associated with Fire Extinguisher Sill	
Stairwell 2 Hallway	Expansion Seam Caulking	
Stairwell 2 Hallway	Floor Tile VAT 12" x 12"	
Stairwell 2 Hallway	Mastic associated with Floor Tile	
Stairwell 2 Hallway	Floor Tile VAT 12" x 12"	
Stairwell 2 Hallway	Transite associated with Fire Extinguisher Sill	
Lobby outside Stairwell 2 and 3 and IMC	Floor Tile VAT 12" x 12"	
Lobby outside Stairwell 2 and 3 and IMC	Expansion Seam Caulking	
IMC	Floor Tile VAT 12" x 12"	
IMC	Expansion Seam Caulking	
IMC	Floor Tile VAT 12" x 12"	
IMC	Floor Tile VAT 12" x 12"	
IMC	Transite associated with Fire Extinguisher Sill	
Classroom 216	Sink Undercoat Mastic	
Classroom 216	Glue Dots associated with Blackboard	
Classroom 216	Floor Tile VAT 12" x 12"	
Classroom 216	Floor Tile VAT 12" x 12"	
Classroom 216	Expansion Seam Caulking	
Classroom 215	Mastic associated with Floor Tile	
Classroom 215	Sink Undercoat Mastic	
Classroom 215	Glue Dots associated with Blackboard	
Classroom 215	Expansion Seam Caulking	
Classroom 214	Sink Undercoat Mastic	
Classroom 214	Floor Tile VAT 12" x 12"	
Classroom 214	Floor Tile VAT 12" x 12"	
Classroom 214	Expansion Seam Caulking	
Stairwell 2	Expansion Seam Caulking	
Stairwell 1	Expansion Seam Caulking	
Stairwell 3	Expansion Seam Caulking	
Stairwell 4	Expansion Seam Caulking	
Exterior of Building	Mortar	

Table 3: Non Friable Asbestos Containing Materials Identified in the Little School House

NOTE: Significantly Damaged non-friable materials (damage  $\geq$  10% of the material) can release harmful asbestos fibers into the air.

Location	Friable Asbestos Containing Material	Reported as Damaged or Significantly Damaged? (Blank = No)
Classroom 1	Floor Tile VAT 12" x 12"	