

Hill-Freedman World Academy at Leeds: Asbestos Hazard Report

The Philadelphia Regional Center for Children's Environmental Health has partnered with the Healthy Schools Initiative to analyze and report on public information regarding asbestos conditions in schools made available on the School District of Philadelphia's website.

This report is meant to communicate to parents, teachers, and staff the exposure risk at their school and help prioritize the removal of asbestos in high-risk exposure locations.

Our analysis is based on publicly available reports. We have not conducted inspections or verified the reports.

Key Findings:

- 152 teacher / student occupied spaces have asbestos containing material (ACM)
- 39 spaces had damaged ACM
- 147 spaces contained friable ACM
- **Most damaged** materials have **not** yet been scheduled to be abated

Our Recommendations:

- The School District scheduled the abatement for two sections of damaged floor tiles identified during their latest inspection in Jan 2025. The School District did not abate damaged friable asbestos containing pipe insulation in several areas around the school (see Table 1). We recommend this material to be abated immediately.
- The School District is required to regularly monitor the condition of their ACM by the EPA. We recommend the complete removal of friable ACM instead of encapsulation for materials that have been repeatedly damaged (See Table 1).



What is asbestos?

Asbestos is a fibrous material that is resistant to heat, water, and corrosion.

See this link for a comprehensive list: <https://prcceh.upenn.edu/asbestos>

Asbestos was used in materials in schools, including:

- Ceiling Tiles
- Floor Tiles
- Pipe Insulation
- Cement
- Paint and Caulk
- Soundproofing
- Fireproofing
- Plaster Materials

What are the health effects of asbestos?

No immediate health impacts are expected from asbestos exposure in schools. However, breathing asbestos fibers in schools may increase the risk of developing cancer many years from now.

Children are very active, breathing more air while running and playing. Children take more breaths per minute than adults and are lower to the ground where asbestos fibers may settle. This puts them at an increased risk for asbestos exposure.

Are all asbestos containing materials of equal risk?

Some asbestos containing materials like ceiling and floor tiles have asbestos fibers imbedded in other materials. As long as they are not broken or damaged the asbestos fibers are not released into the air.

Some asbestos containing materials like insulation on pipe remains fibrous and can easily be released in the air when damaged.

How are damaged asbestos containing materials managed?

Asbestos can be removed. Sometimes damaged materials are managed in place by patching, encapsulating (using a specially formulated paint-like coating) or building an enclosure around damaged and/or accessible materials. All of these are forms of abatement.

The Environmental Protection Agency requires all remaining asbestos containing material to be inspected by the school district every six months. This is documented in an Asbestos Hazard Emergency Response Act Report (AHERA Report).

Important Terms

Get to know these terms to make the most out of this report.

Damaged Asbestos Containing Material (ACM) can release asbestos fibers into the air.

Friable Materials can be reduced to a powder by applying hand pressure. **DO NOT TOUCH!**

Non-Friable materials are not easily damaged.

Significantly damaged materials are more than 10% damaged.

Abated ACM means repaired, removed, or reduced risk of exposure.

Detailed Review for Thomas K. Finletter School

This school has 195 spaces with asbestos containing materials. 152 of them are in teacher / student occupied spaces. The School District last inspected ACM in Jan 2025 and published the AHERA report in Feb 2025. Since then, the School District scheduled the abatement of two sections of damaged asbestos containing floor tiles identified during this inspection.



We recommend that the school district immediately abate the damaged asbestos containing pipe insulation as shown in Table 1. We recommend that the School District completely remove friable ACM that have been repeatedly damaged in the past as listed in Table 1. Abatement was scheduled for the two floor tile sections in Dec 2024, however the website does not confirm that the abatement was completed. A list of all the ACM in the school and their damage/abatement schedule can be found in the tables at the end of this report.

Information Reviewed to Make this Report:

The 2024/25 AHERA report from the School District of Philadelphia, and asbestos abatement notifications from the Air Management Services Online Portal.

Not included in this report are planned repairs to damaged asbestos materials that have not been uploaded to the Air Management Services website or any updated after April 25, 2025. To see the most current information, scan these QR Codes. After scanning, search for your school.

School Districts of Philadelphia Asbestos Reports:



AHERA Reports are documents generated from EPA required asbestos inspections

Office of the Controller Asbestos Project:



Asbestos abatement notification forms



Report what you see!

Parents and teachers should report hazardous conditions in schools on the Healthy Schools app.

Scan here to
download the app:



Disclaimer:

This report analyzes custodial and mechanical spaces like boiler rooms **only** when ACM is significantly damaged (damage > 10%).

Questions?

Find more resources on our website!

prcceh.upenn.edu/asbestos

- Photo gallery of different types of damaged asbestos containing materials
- Guide to how we classify materials in schools
- Our analysis and reporting methodology
- What we do with the information in this report



Email us at prcceh@pennteamicine.upenn.edu or call 215-573-9076

Table 1: Friable Asbestos Containing Materials Identified

NOTE: Friable materials can be reduced to a powder by applying hand pressure.
Do not touch it! Damaged and significantly damaged friable materials readily release harmful asbestos fibers into the air.

| Location | Friable Asbestos Containing Material | Reported as Damaged or Significantly Damaged? (Blank = No) | Abatement scheduled since the inspection? (Blank = No) |
|--|--|--|--|
| Classroom 108 | Pipe Insulation 2-6 inch | | |
| Classroom 108 | Pipe Fitting Insulation | | |
| Classroom 110 | Pipe Insulation 2-6 inch | | |
| Classroom 110 | Pipe Fitting Insulation | | |
| Classroom 111 | Pipe Insulation 2-6 inch | | |
| Classroom 111 | Pipe Fitting Insulation | | |
| Classroom 112 | Pipe Insulation 2-6 inch | | |
| Classroom 112 | Pipe Fitting Insulation | | |
| Office 113 across from Main Office | Pipe Insulation 2-6 inch | | |
| Office 113 across from Main Office | Pipe Fitting Insulation | | |
| IMC Library 115 | Pipe Insulation 2-6 inch | | |
| IMC Library 115 | Pipe Fitting Insulation | | |
| Classroom 117 adjacent to IMC | Pipe Fitting Insulation | | |
| Classroom 117 adjacent to IMC | Pipe Insulation 2-6 inch associated with Cabinet, Built-in | | |
| Boy's Restroom across from Classroom 120 | Pipe Insulation 2-6 inch | | |
| Boy's Restroom across from Classroom 120 | Pipe Fitting Insulation | | |
| Custodial Closet across from Classroom 120 | Pipe Insulation 2-6 inch | | |
| Custodial Closet across from Classroom 120 | Pipe Fitting Insulation | | |
| Classroom 120 | Pipe Insulation 2-6 inch | | |
| Classroom 120 | Pipe Fitting Insulation | | |
| Classroom 122 | Pipe Insulation 2-6 inch | | |
| Classroom 122 | Pipe Fitting Insulation | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|---|---|----------|--|
| Classroom 121 | Pipe Insulation 2-6 inch | | |
| Classroom 121 | Pipe Fitting Insulation | | |
| Classroom 119 | Pipe Insulation 2-6 inch | | |
| Classroom 119 | Pipe Fitting Insulation | | |
| Office 123 | Pipe Insulation 2-6 inch | Damaged. | |
| Office 123 | Pipe Fitting Insulation | | |
| Classroom 124 | Pipe Insulation 2-6 inch | | |
| Classroom 124 | Pipe Fitting Insulation | | |
| Classroom 126 | Pipe Insulation 2-6 inch | | |
| Classroom 126 | Pipe Fitting Insulation | | |
| Independent Living Center 125 | Pipe Insulation 2-6 inch | | |
| Independent Living Center 125 | Pipe Fitting Insulation | | |
| Independent Living Center 125 Large Closet | Pipe Insulation 2-6 inch | | |
| Independent Living Center 125 Large Closet | Pipe Fitting Insulation | | |
| Pipe Chase in Independent Living Center 125 Large Closet | Pipe Fitting Insulation | | |
| Pipe Chase in Independent Living Center 125 Large Closet | Pipe Insulation 2-6 inch | | |
| Kitchen Classroom in Independent Living Center 125 | Pipe Insulation 2-6 inch | | |
| Kitchen Classroom in Independent Living Center 125 | Pipe Fitting Insulation | | |
| Classroom 128 | Pipe Insulation 2-6 inch | | |
| Classroom 128 | Pipe Fitting Insulation | | |
| Teacher's Lounge Room 127 | Pipe Insulation 2-6 inch | | |
| Teacher's Lounge Room 127 | Pipe Fitting Insulation | | |
| Girl's Restroom next to Teacher's Lounge 127 | Pipe Insulation 2-6 inch | | |
| Girl's Restroom next to Teacher's Lounge 127 | Pipe Fitting Insulation | | |
| Classroom 133 | Heat Shield Insulation associated with Radiator | | |
| Classroom 133 | Pipe Insulation 2-6 inch | | |
| Classroom 133 | Pipe Fitting Insulation | | |
| Classroom 134 | Heat Shield Insulation associated with Radiator | | |
| Classroom 134 | Pipe Insulation 2-6 inch | | |
| Classroom 134 | Pipe Fitting Insulation | | |
| Classroom 132 | Pipe Insulation 2-6 inch | | |
| Classroom 132 | Pipe Fitting Insulation | | |
| Classroom 129 | Heat Shield Insulation associated with Radiator | | |
| Classroom 131 | Pipe Insulation 2-6 inch | | |
| Classroom 131 | Pipe Fitting Insulation | | |
| Boy's Restroom next to Stairwell #6 | Pipe Insulation >6 inches | | |
| Boy's Restroom next to Stairwell #6 | Pipe Insulation 2-6 inch | | |
| Boy's Restroom next to Stairwell #6 | Pipe Fitting Insulation | | |
| Storage Room 139 next to Boys Restroom | Pipe Fitting Insulation | | |
| Storage Room 139 next to Boys Restroom | Pipe Insulation 2-6 inch | | |
| Foyer outside Boy's Restroom next to Stairwell #6 | Pipe Insulation 2-6 inch | | |
| Foyer outside Boy's Restroom next to Stairwell #6 | Pipe Fitting Insulation | | |
| Girl's Restroom next to Stairwell #5 | Pipe Insulation 2-6 inch | | |
| Girl's Restroom next to Stairwell #5 | Pipe Fitting Insulation | | |
| Girl's Restroom across from Main Office | Pipe Insulation 2-6 inch | | |
| Girl's Restroom across from Main Office | Pipe Fitting Insulation | | |
| Mechanical Closet next to Girl's Restroom across from Main Office | Pipe Insulation 2-6 inch | | |
| Mechanical Closet next to Girl's Restroom across from Main Office | Pipe Fitting Insulation | | |
| Mechanical Closet 1-B in Hallway next to Counselor's Suite and Boy's Restroom | Pipe Insulation 2-6 inch | | |
| Mechanical Closet 1-B in Hallway next to Counselor's Suite and Boy's Restroom | Pipe Fitting Insulation | | |
| Closet in Electrical Room for Stage Controls | Pipe Insulation 2-6 inch | | |
| Storage Room on Stage Right | Pipe Insulation 2-6 inch | | |
| Storage Room on Stage Right | Pipe Fitting Insulation | | |
| Auditorium | Textured Plaster Ceiling | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|--|---|---|--|
| Custodial Closet in Hallway outside Music Technology Room 102 | Pipe Fitting Insulation | | |
| Custodial Closet in Hallway outside Music Technology Room 102 | Pipe Insulation 2-6 inch | | |
| Stage | Pipe Fitting Insulation | | |
| Stage | Pipe Insulation 2-6 inch | | |
| Stage | Textured Plaster Ceiling | | |
| Vice Principals Office in Main Office | Pipe Insulation 2-6 inch | | |
| Vice Principals Office in Main Office | Pipe Fitting Insulation | | |
| Main Office 114 | Pipe Insulation 2-6 inch | | |
| Main Office 114 | Pipe Fitting Insulation | | |
| Main Office 114 | Pipe Insulation 2-6 inch | | |
| Storage Room in Main Office 114 at entrance | Pipe Insulation 2-6 inch | | |
| Principal's Office | Pipe Insulation 2-6 inch | | |
| Principal's Office | Pipe Fitting Insulation | | |
| Principal's Office Restroom | Pipe Insulation 2-6 inch | | |
| Principal's Office Restroom | Pipe Fitting Insulation | | |
| Custodial Closet 140 in Hallway near Classroom 136 | Pipe Fitting Insulation | | |
| Custodial Closet 140 in Hallway near Classroom 136 | Pipe Insulation 2-6 inch | | |
| Custodial Closet 140 in Hallway near Classroom 136 | Pipe Insulation >6 inches | | |
| Conference Room 116 next to Principal's Office | Pipe Insulation 2-6 inch | | |
| Conference Room 116 next to Principal's Office | Pipe Fitting Insulation | | |
| Conference Room 116 next to Principal's Office | Pipe Insulation 2-6 inch | | |
| Office 116C inside Mail Room 116A | Pipe Fitting Insulation | | |
| Office 116C inside Mail Room 116A | Pipe Insulation 2-6 inch | | |
| Staff Lounge 118 across from Classroom 117 | Pipe Insulation 2-6 inch | Damaged. Previously reported damaged in Dec 2023 and July 2024. | |
| Staff Lounge 118 across from Classroom 117 | Pipe Fitting Insulation | | |
| Hallway that connects to Music Practice Rooms | Metal Pan Ceiling Tile 1' x 1' | | |
| Hallway from Counselors Suite 105 to Classroom 112 | Pipe Insulation 2-6 inch | | |
| Hallway from Counselors Suite 105 to Classroom 112 | Pipe Fitting Insulation | | |
| Hallway in front of Classrooms 104-Music Technology Room 102 | Pipe Insulation 2-6 inch | | |
| Hallway in front of Classrooms 104-Music Technology Room 102 | Pipe Fitting Insulation | | |
| Hallway from Teachers Lounge 127 to Main Office | Pipe Insulation 2-6 inch | | |
| Hallway from Teachers Lounge 127 to Main Office | Pipe Fitting Insulation | | |
| Hallway between Stairwell #5 and Stairwell #6 | Pipe Insulation 2-6 inch | | |
| Hallway between Stairwell #5 and Stairwell #6 | Pipe Fitting Insulation | | |
| Entire Hallway from area outside Classroom 130 to Stairwell #7 adjacent to Classroom 129 | Heat Shield Insulation associated with Radiator | | |
| Entire Hallway from area outside Classroom 130 to Stairwell #7 adjacent to Classroom 129 | Pipe Insulation >6 inches | | |
| Entire Hallway from area outside Classroom 130 to Stairwell #7 adjacent to Classroom 129 | Pipe Insulation 2-6 inch | | |
| Entire Hallway from area outside Classroom 130 to Stairwell #7 adjacent to Classroom 129 | Pipe Fitting Insulation | | |
| Main Entrance Foyer next to Auditorium | Heat Shield Insulation associated with Radiator | | |
| Stairwell #1 by Classrooms 112 | Heat Shield Insulation associated with Radiator | | |
| Stairwell #1 by Classrooms 112 | Pipe Insulation 2-6 inch | | |
| Stairwell #1 by Classrooms 112 | Pipe Fitting Insulation | | |
| Stairwell #5 across from Elevator | Pipe Insulation 2-6 inch | | |
| Stairwell #5 across from Elevator | Pipe Fitting Insulation | | |
| Stairwell #6 next to Elevator | Pipe Insulation 2-6 inch | | |
| Stairwell #6 next to Elevator | Pipe Fitting Insulation | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|--|---|--|--|
| Stairwell next to Classroom 130 to the Gym | Heat Shield Insulation associated with Radiator | | |
| Stairwell next to Classroom 130 to the Gym | Pipe Insulation 2-6 inch | | |
| Stairwell next to Classroom 130 to the Gym | Pipe Fitting Insulation | | |
| Stairwell #7 by Classroom 129 | Pipe Insulation 2-6 inch | | |
| Classroom 202 Storage | Pipe Insulation 2-6 inch | | |
| Classroom 202 Storage | Pipe Fitting Insulation | | |
| Laboratory Storage Room in between Classroom 209 & 207 | Pipe Packing Insulation associated with Unit Ventilator, Interior | | |
| Male Staff Restroom | Pipe Insulation 2-6 inch | | |
| Custodial Closet across from Classroom 224 | Paint associated with Ductwork, Exterior | | |
| Classroom 229 Large Closet Pipe Chase | Pipe Fitting Insulation | | |
| Classroom 229 Large Closet Pipe Chase | Pipe Insulation 2-6 inch | | |
| Girl's Gym 233 | Paint associated with Ductwork, Exterior | | |
| Gym Teacher's Office 234A | Pipe Insulation 2-6 inch | | |
| Gym Teacher's Office 234A | Pipe Fitting Insulation | | |
| Gym Teachers Office 234A Closet next to Restroom | Paint associated with Ductwork, Exterior | | |
| Gym Teachers Office 234A Closet next to Restroom | Pipe Insulation >6 inches | Significantly damaged. Previously reported as damaged in Dec 2023. | |
| Gym Teachers Office 234A Closet next to Restroom | Pipe Insulation 2-6 inch | | |
| Gym Teachers Office 234A Closet next to Restroom | Pipe Fitting Insulation | | |
| Gym Teachers Office 324A Closet along back wall | Paint associated with Ductwork, Exterior | | |
| Gym Teachers Office 324A Closet along back wall | Pipe Insulation 2-6 inch | | |
| Girls Gym 233 Storage Closet 234B | Paint associated with Ductwork, Exterior | | |
| Girls Gym 233 Storage Closet 234B | Pipe Insulation 2-6 inch | | |
| Girls Gym 233 Storage Closet 234B | Pipe Fitting Insulation | | |
| Boy's Gym 234 | Paint associated with Ductwork, Exterior | | |
| Gym Teachers Office 233A Closet along back wall | Pipe Fitting Insulation | | |
| Gym Teachers Office 233A Closet along back wall | Pipe Insulation 2-6 inch | | |
| Gym Teachers Office 233A Closet next to Restroom | Pipe Insulation 2-6 inch | | |
| Boys Gym Equipment Closet 233B | Pipe Fitting Insulation | | |
| Boys Gym Equipment Closet 233B | Pipe Insulation 2-6 inch | | |
| Girl's Restroom across Classroom 216 | Pipe Insulation 2-6 inch | | |
| Girl's Restroom across Classroom 216 | Pipe Fitting Insulation | | |
| Mechanical Closet across the Hall from Classroom 216 and next to Girl's Restroom | Paint associated with Ductwork, Exterior | | |
| Mechanical Closet across the Hall from Classroom 216 and next to Girl's Restroom | Pipe Insulation 2-6 inch | | |
| Mechanical Closet across the Hall from Classroom 216 and next to Girl's Restroom | Pipe Fitting Insulation | Damaged. | |
| Boy's Restroom across from Room 200 | Pipe Insulation 2-6 inch | | |
| Mechanical Closet next to Boy's Restroom | Pipe Fitting Insulation | | |
| Mechanical Closet next to Boy's Restroom | Pipe Insulation 2-6 inch | | |
| Boys' Restroom next to Classroom 223 | Pipe Insulation 2-6 inch | | |
| Hallway from Main Hallway to the Classroom 202 | Pipe Insulation 2-6 inch | | |
| Hallway from Main Hallway to the Classroom 202 | Pipe Fitting Insulation | | |
| Hallway between Classroom 216 and Room 200 | Pipe Insulation 2-6 inch | | |
| Hallway between Classroom 216 and Room 200 | Pipe Fitting Insulation | | |
| Hallway from Room 200 to Classroom 212 | Pipe Fitting Insulation | | |
| Hallway from Room 200 to Classroom 212 | Pipe Insulation 2-6 inch | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|---|---|---|--|
| Stairwell #2 across from the Classroom 202 | Heat Shield Insulation associated with Radiator | | |
| Stairwell #1 next to Classroom 212 | Heat Shield Insulation associated with Radiator | | |
| Stairwell #4 next to Classroom 224 | Heat Shield Insulation associated with Radiator | | |
| Stairwell #5 across from Elevator | Heat Shield Insulation associated with Radiator | | |
| Stairwell within the Boys Gymnasium 234 | Pipe Fitting Insulation | | |
| Stairwell within the Boys Gymnasium 234 | Pipe Insulation 2-6 inch | | |
| Stairwell within the Girls Gymnasium 233 | Heat Shield Insulation associated with Radiator | | |
| Stairwell within the Girls Gymnasium 233 | Pipe Fitting Insulation | | |
| Stairwell within the Girls Gymnasium 233 | Pipe Insulation 2-6 inch | | |
| Fan Room above the Gymnasiums | Pipe Insulation >6 inches | | |
| Fan Room above the Gymnasiums | Pipe Insulation 2-6 inch | | |
| Fan Room above the Gymnasiums | Pipe Fitting Insulation | | |
| Auditorium Attic | Textured Plaster Floor | | |
| Stairwell leading down into Basement from Stairwell #4 | Pipe Insulation 2-6 inch | | |
| Small Electrical Room with Crawlspace access (accessed from Stairwell#4 near Mens Restroom) | Pipe Insulation 2-6 inch | | |
| Small Electrical Room with Crawlspace access (accessed from Stairwell#4 near Mens Restroom) | Pipe Fitting Insulation | | |
| Main Crawl Space | Pipe Insulation 2-6 inch | | |
| Room B5 | Pipe Insulation 2-6 inch | Damaged. Previously reported as damaged in Dec 2023 and July 2024. | |
| Room B5 | Pipe Fitting Insulation | Damaged. Previously reported as damaged in July 2024. | |
| Conference Room B3 | Pipe Packing Insulation associated with Unit Ventilator, Interior | | |
| Conference Room B3 | Pipe Insulation 2-6 inch | | |
| Conference Room B3 | Pipe Fitting Insulation | | |
| Office with a Restroom inside Facilities Area Management Office | Pipe Insulation 2-6 inch | | |
| Office with a Restroom inside Facilities Area Management Office | Pipe Fitting Insulation | | |
| Men's Restroom across from Room 5 | Pipe Insulation 2-6 inch | | |
| Men's Restroom across from Room 5 | Pipe Fitting Insulation | Significantly damaged. Previously reported as significantly damaged in July 2024. | |
| Facilities Area Management Office next to Conference Room B3 | Pipe Insulation 2-6 inch | | |
| Facilities Area Management Office next to Conference Room B3 | Pipe Fitting Insulation | | |
| Large Far Left Office in Office Suite 5 | Pipe Insulation 2-6 inch | | |
| Large Far Left Office in Office Suite 5 | Pipe Fitting Insulation | | |
| Right Office in Office Suite 5 | Pipe Insulation 2-6 inch | | |
| Office 8 Break Room (window side) | Pipe Fitting Insulation | | |
| Office 8 Break Room (window side) | Pipe Insulation 2-6 inch | | |
| Conference Room Behind Mail/IT Room | Pipe Insulation 2-6 inch | | |
| Conference Room Behind Mail/IT Room | Pipe Fitting Insulation | | |
| Classroom 9 Storage Closet to the Window | Pipe Insulation 2-6 inch | | |
| Classroom 9 Storage Closet to the Window | Pipe Fitting Insulation | Significantly damaged. | |
| Mechanic's Locker Closet adjacent to BE Office | Pipe Insulation 2-6 inch | | |
| Small Hallway next to Music Classroom 1 that leads to exit door to exterior | Pipe Insulation 2-6 inch | | |
| Small Hallway next to Music Classroom 1 that leads to exit door to exterior | Pipe Fitting Insulation | | |
| Music Room 1 | Pipe Fitting Insulation | | |
| Music Room 1 | Pipe Insulation 2-6 inch | | |
| Music Room 2 | Pipe Fitting Insulation | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|---|---------------------------|--|--|
| Music Room 2 | Pipe Insulation 2-6 inch | | |
| Music Room 3 | Pipe Insulation 2-6 inch | | |
| Music Room 3 | Pipe Fitting Insulation | | |
| Music Room 5 | Pipe Fitting Insulation | | |
| Music Room 5 | Pipe Insulation 2-6 inch | | |
| Music Storage Room 4 | Pipe Insulation 2-6 inch | | |
| Kitchen Storage Area next to Walk In Refrigerator | Cork Pipe Insulation | Significantly damaged. | |
| Classroom 1 | Pipe Insulation 2-6 inch | | |
| Classroom 1 | Pipe Fitting Insulation | | |
| Assistant Superintendent's Office across from Room 9 | Pipe Fitting Insulation | | |
| Assistant Superintendent's Office across from Room 9 | Pipe Insulation 2-6 inch | | |
| Assistant Superintendent's Office across from Room 9 | Pipe Insulation 2-6 inch | | |
| Assistant Superintendent's Office Restroom | Pipe Insulation 2-6 inch | | |
| Main Cubicle Area in Office 8 | Pipe Fitting Insulation | | |
| Main Cubicle Area in Office 8 | Pipe Insulation 2-6 inch | | |
| Main Cubicle Area in Office 8 | Pipe Fitting Insulation | | |
| Main Cubicle Area in Office 8 | Pipe Insulation 2-6 inch | | |
| Leeds Supply Closet next to Custodial Closet | Pipe Insulation >6 inches | | |
| Leeds Supply Closet next to Custodial Closet | Pipe Insulation 2-6 inch | | |
| Leeds Supply Closet next to Custodial Closet | Pipe Fitting Insulation | | |
| Hallway from Stairwell #5 to Building Engineer's Office | Pipe Insulation 2-6 inch | | |
| Hallway from Stairwell #5 to Building Engineer's Office | Pipe Fitting Insulation | | |
| Custodial Closet next to Stairwell #5 | Pipe Insulation >6 inches | | |
| Custodial Closet next to Stairwell #5 | Pipe Insulation 2-6 inch | | |
| Supply Closet to right of Stairwell #6 | Pipe Insulation 2-6 inch | | |
| Supply Closet to right of Stairwell #6 | Pipe Fitting Insulation | | |
| Exhaust Fan Room inside Supply Closet to right of Stairwell #6 | Pipe Insulation 2-6 inch | | |
| Exhaust Fan Room inside Supply Closet to right of Stairwell #6 | Pipe Fitting Insulation | | |
| Boiler Room Upper and Lower Levels | Tank Insulation | | |
| Mechanical Room underneath Room 017 (Rear Storage Room in Building Engineer's Area) | Pipe Insulation 2-6 inch | | |
| Mechanical Room underneath Room 017 (Rear Storage Room in Building Engineer's Area) | Pipe Fitting Insulation | Damaged. Previously reported as damaged in July 2024. | |
| Rear Storage Room in Building Engineer's Area | Pipe Insulation 2-6 inch | | |
| Rear Storage Room in Building Engineer's Area | Pipe Fitting Insulation | Significantly damaged. Previously reported as damaged in Dec 2023. | |
| Men's Lounge in BE Area | Pipe Insulation 2-6 inch | | |
| Men's Lounge in BE Area | Pipe Fitting Insulation | | |
| Restroom in Men's Lounge in BE Area | Pipe Insulation 2-6 inch | | |
| Restroom in Men's Lounge in BE Area | Pipe Fitting Insulation | | |
| Women's Lounge in BE Area | Pipe Insulation 2-6 inch | | |
| Women's Lounge in BE Area | Pipe Fitting Insulation | | |
| Restroom in Women's Lounge in BE Area | Pipe Insulation 2-6 inch | | |
| Restroom in Women's Lounge in BE Area | Pipe Fitting Insulation | | |
| Building Engineer's (BE) Office | Pipe Insulation 2-6 inch | | |
| Building Engineer's (BE) Office | Pipe Fitting Insulation | | |
| Building Engineer's Office Closet | Pipe Fitting Insulation | | |
| Building Engineer's Office Closet | Pipe Insulation 2-6 inch | | |
| Building Engineer's Office Restroom | Pipe Fitting Insulation | | |
| Building Engineer's Office Restroom | Pipe Insulation 2-6 inch | | |
| Custodial Storage across from Women's Lounge in BE Area | Pipe Insulation >6 inches | | |
| Custodial Storage across from Women's Lounge in BE Area | Pipe Insulation 2-6 inch | | |
| Custodial Storage across from Women's Lounge in BE Area | Pipe Fitting Insulation | | |
| Women's Restroom next to Assistant Superintendent's Office | Pipe Insulation 2-6 inch | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|--|--------------------------------|---|--|
| Women's Restroom next to Assistant Superintendent's Office | Pipe Fitting Insulation | | |
| Girls' Restroom near Cafeteria Entrance | Pipe Insulation 2-6 inch | | |
| Girls' Restroom near Cafeteria Entrance | Pipe Fitting Insulation | | |
| Pipe Chase to Right of Girls' Restroom near Cafeteria Entrance | Pipe Insulation 2-6 inch | | |
| Pipe Chase to Right of Girls' Restroom near Cafeteria Entrance | Pipe Fitting Insulation | | |
| Boy's Restroom at Cafeteria Entrance | Pipe Insulation 2-6 inch | | |
| Boy's Restroom at Cafeteria Entrance | Pipe Fitting Insulation | | |
| Former Serving Area And Faculty Lunch Room (to the Far Right of Kitchen) | Metal Pan Ceiling Tile 1' x 1' | | |
| Former Serving Area And Faculty Lunch Room (to the Far Right of Kitchen) | Pipe Insulation 2-6 inch | | |
| Former Serving Area And Faculty Lunch Room (to the Far Right of Kitchen) | Pipe Fitting Insulation | | |
| Custodial Closet at Entrance to Cafeteria | Pipe Insulation 2-6 inch | | |
| Custodial Closet at Entrance to Cafeteria | Pipe Fitting Insulation | | |
| Closet in Cafeteria adjacent to Stairwell #1 | Pipe Insulation 2-6 inch | | |
| Kitchen Office | Pipe Insulation 2-6 inch | | |
| Kitchen Office | Pipe Fitting Insulation | | |
| Entire Kitchen Area | Pipe Insulation 2-6 inch | | |
| Entire Kitchen Area | Pipe Fitting Insulation | | |
| Book Storage Suite - Far Left Office | Pipe Fitting Insulation | | |
| Book Storage Suite - Far Left Office | Pipe Insulation 2-6 inch | Damaged. Previously reported as damaged in July 2024. | |
| Book Storage Suite - Middle Room | Pipe Fitting Insulation | | |
| Book Storage Suite - Middle Room | Pipe Insulation 2-6 inch | Damaged. Previously reported as damaged in July 2024. | |
| Classroom 003 | Pipe Insulation 2-6 inch | | |
| Classroom 003 | Pipe Fitting Insulation | | |
| Open Storage Area in Cafeteria adjacent to Stairwell #1 | Pipe Insulation 2-6 inch | | |
| Open Storage Area in Cafeteria adjacent to Stairwell #1 | Pipe Fitting Insulation | | |
| Cafeteria | Metal Pan Ceiling Tile 1' x 1' | | |
| Cafeteria | Pipe Insulation 2-6 inch | Damaged. Previously reported as damaged in March 2019 and Dec 2023. | |
| Cafeteria | Pipe Fitting Insulation | Damaged. | |
| Music Room Suite Open Area | Pipe Insulation 2-6 inch | | |
| Music Room Suite Open Area | Pipe Fitting Insulation | | |
| Incinerator Room Upstairs & Downstairs | Pipe Insulation 2-6 inch | | |
| Incinerator Room Upstairs & Downstairs | Pipe Fitting Insulation | | |
| Teacher's Lounge 36 across from Girls Restroom | Pipe Insulation 2-6 inch | | |
| Teacher's Lounge 36 across from Girls Restroom | Pipe Fitting Insulation | | |
| Teacher's Lounge 36 Foyer outside Mens Restroom | Pipe Fitting Insulation | | |
| Teacher's Lounge 36 Foyer outside Mens Restroom | Pipe Insulation 2-6 inch | | |
| Teacher's Lounge 36 Mens Restroom | Pipe Fitting Insulation | | |
| Teacher's Lounge 36 Mens Restroom | Pipe Insulation 2-6 inch | | |
| Teacher's Lounge 36 Womens Restroom | Pipe Insulation 2-6 inch | | |
| Teacher's Lounge 36 Womens Restroom | Pipe Fitting Insulation | | |
| Storage Room/Mechanical Room down Hallway from Music Classroom 1 | Pipe Fitting Insulation | | |
| Storage Room/Mechanical Room down Hallway from Music Classroom 1 | Pipe Insulation 2-6 inch | | |
| Kitchen Dry Storage Area | Pipe Insulation 2-6 inch | | |
| Kitchen Dry Storage Area | Pipe Fitting Insulation | | |
| Classroom 005 | Pipe Insulation 2-6 inch | Damaged. Previously reported as damaged in Dec 2023 and July 2024. | |
| Classroom 005 | Pipe Fitting Insulation | | |

Hill-Freeman World Academy at Leeds: Asbestos Hazard Report

| | | | |
|---|---|--|--|
| Middle Office in Office Suite 5 | Pipe Insulation 2-6 inch | | |
| Middle Office in Office Suite 5 | Pipe Fitting Insulation | | |
| Computer Lab Room 6 | Pipe Insulation 2-6 inch | | |
| Computer Lab Room 6 | Pipe Fitting Insulation | | |
| Room 7 | Pipe Insulation 2-6 inch | | |
| Room 7 | Pipe Fitting Insulation | | |
| Office within Room 7 | Pipe Insulation 2-6 inch | | |
| Office within Room 7 | Pipe Fitting Insulation | | |
| Classroom 9 | Pipe Insulation 2-6 inch | | |
| Classroom 9 | Pipe Fitting Insulation | | |
| Hallway from Classroom 9 through double doors to Girls Restroom | Pipe Fitting Insulation | | |
| Hallway from Classroom 9 through double doors to Girls Restroom | Pipe Insulation 2-6 inch | | |
| Hallway outside Room B5 to Conference Room B3 | Pipe Insulation 2-6 inch | | |
| Hallway outside Room B5 to Conference Room B3 | Pipe Fitting Insulation | | |
| Stairwell #1 at rear of Cafeteria | Heat Shield Insulation associated with Radiator | | |
| Stairwell #1 at rear of Cafeteria | Pipe Insulation 2-6 inch | | |
| Stairwell #1 at rear of Cafeteria | Pipe Fitting Insulation | | |
| Stairwell #2 outside Music Suite | Pipe Insulation 2-6 inch | | |
| Stairwell #2 outside Music Suite | Pipe Fitting Insulation | | |
| Stairwell #3 near the Cafeteria Entrance between Boy's and Girl's Restrooms | Heat Shield Insulation associated with Radiator | | |
| Stairwell #4 near Mens Restroom | Heat Shield Insulation associated with Radiator | | |
| Stairwell #5 outside the Entrance to the Building Engineer's Suite | Pipe Insulation 2-6 inch | | |
| Stairwell #5 outside the Entrance to the Building Engineer's Suite | Pipe Fitting Insulation | | |
| Stairwell #6 next to Elevator | Pipe Insulation 2-6 inch | | |
| Stairwell #6 next to Elevator | Pipe Fitting Insulation | | |

Table 2: Non-Friable Asbestos Containing Materials Identified

NOTE: Significantly Damaged non-friable materials (damage \geq 10% of the material) can release harmful asbestos fibers into the air.

| Location | Material Name | Reported as Damaged or Significantly Damaged? | Abatement scheduled since the inspection? |
|----------------------|--|---|---|
| Classroom 108 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 108 | Glue Dots associated with Blackboard | | |
| Classroom 108 | Floor Tile VAT 9" x 9" | | |
| Classroom 110 | ACM Unit Ventilator | | |
| Classroom 110 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 110 | Glue Dots associated with Blackboard | | |
| Classroom 110 | Floor Tile VAT 9" x 9" | | |
| Classroom 110 Closet | Expansion Seam Caulking | | |
| Classroom 110 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 111 | Floor Tile VAT 12" x 12" | | |
| Classroom 111 | ACM Unit Ventilator | | |
| Classroom 111 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 111 | Glue Dots associated with Blackboard | | |
| Classroom 111 | Floor Tile VAT 9" x 9" | | |
| Classroom 111 Closet | Expansion Seam Caulking | | |
| Classroom 111 Closet | Floor Tile VAT 9" x 9" | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|--|---|--|--------------------------------|
| Classroom 112 | Floor Tile VAT 12" x 12" | | |
| Classroom 112 | ACM Unit Ventilator | | |
| Classroom 112 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 112 | Glue Dots associated with Blackboard | | |
| Classroom 112 | Floor Tile VAT 9" x 9" | | |
| Office 113 across from Main Office | Expansion Seam Caulking | | |
| Office 113 across from Main Office | Floor Tile VAT 12" x 12" | | |
| Office 113 across from Main Office | Floor Tile VAT 9" x 9" | | |
| IMC Library 115 | Expansion Seam Caulking | | |
| IMC Library 115 | Floor Tile VAT 9" x 9" associated with Foul Air Shaft | | |
| IMC Library 115 | Floor Tile VAT 12" x 12" | | |
| IMC Library 115 | ACM Unit Ventilator | | |
| IMC Library 115 | Transite associated with Unit Ventilator, Interior | | |
| IMC Library 115 | Floor Tile VAT 9" x 9" | | |
| Classroom 117 adjacent to IMC | Floor Tile VAT 12" x 12" | | |
| Classroom 117 adjacent to IMC | Expansion Seam Caulking | | |
| Classroom 117 adjacent to IMC | ACM Unit Ventilator | | |
| Classroom 117 adjacent to IMC | Glue Dots associated with Blackboard | | |
| Classroom 117 adjacent to IMC | Transite associated with Unit Ventilator, Interior | | |
| Classroom 117 adjacent to IMC | Mastic associated with Floor Tile | | |
| Classroom 117 adjacent to IMC | Floor Tile VAT 9" x 9" | | |
| Boy's Restroom across from Classroom 120 | Expansion Seam Caulking | Damaged. Previously reported as damaged in Jan 2013 and Oct 2024. | Scheduled removal in Dec 2024. |
| Classroom 117 Closet | Expansion Seam Caulking | | |
| Classroom 117 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 120 | Floor Tile VAT 12" x 12" | | |
| Classroom 120 | ACM Unit Ventilator | | |
| Classroom 120 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 120 | Glue Dots associated with Blackboard | | |
| Classroom 120 | Floor Tile VAT 9" x 9" | | |
| Classroom 120 Closet | Expansion Seam Caulking | Damaged. Previously reported as damaged in Jan 2013, Dec 2023, and Oct 2024. | Scheduled removal in Dec 2024. |
| Classroom 120 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 122 | Expansion Seam Caulking | | |
| Classroom 122 | ACM Unit Ventilator | | |
| Classroom 122 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 122 | Glue Dots associated with Blackboard | | |
| Classroom 122 | Floor Tile VAT 9" x 9" | | |
| Classroom 122 Closet | Expansion Seam Caulking | | |
| Classroom 122 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 121 | Expansion Seam Caulking | | |
| Classroom 121 | Floor Tile VAT 12" x 12" | | |
| Classroom 121 | ACM Unit Ventilator | | |
| Classroom 121 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 121 | Glue Dots associated with Blackboard | | |
| Classroom 121 | Floor Tile VAT 9" x 9" | | |
| Classroom 119 | Expansion Seam Caulking | | |
| Classroom 119 | Floor Tile VAT 12" x 12" | | |
| Classroom 119 | ACM Unit Ventilator | | |
| Classroom 119 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 119 | Floor Tile VAT 9" x 9" | | |
| Classroom 121 Closet | Expansion Seam Caulking | | |
| Classroom 121 Closet | Floor Tile VAT 9" x 9" | | |
| Office 123 | Floor Tile VAT 12" x 12" | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|--|---|------------------------|--|
| Office 123 | Transite associated with Unit Ventilator, Interior | | |
| Office 123 | ACM Unit Ventilator | | |
| Classroom 124 | Expansion Seam Caulking | | |
| Classroom 124 | Floor Tile VAT 9" x 9" associated with Foul Air Shaft | | |
| Classroom 124 | ACM Unit Ventilator | | |
| Classroom 124 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 124 | Glue Dots associated with Blackboard | | |
| Classroom 124 | Floor Tile VAT 9" x 9" | | |
| Classroom 124 Closet | Expansion Seam Caulking | | |
| Classroom 124 Closet | Floor Tile VAT 9" x 9" | Significantly damaged. | |
| Classroom 126 | Expansion Seam Caulking | | |
| Classroom 126 | Floor Tile VAT 9" x 9" associated with Foul Air Shaft | | |
| Classroom 126 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 126 | ACM Unit Ventilator | | |
| Classroom 126 | Glue Dots associated with Blackboard | | |
| Classroom 126 | Floor Tile VAT 12" x 12" | | |
| Classroom 126 Closet | Expansion Seam Caulking | | |
| Classroom 126 Closet | Floor Tile VAT 9" x 9" | Significantly damaged. | |
| Independent Living Center 125 | ACM Unit Ventilator | | |
| Independent Living Center 125 | Transite associated with Unit Ventilator, Interior | | |
| Independent Living Center 125 | Glue Dots associated with Blackboard | | |
| Independent Living Center 125 | Floor Tile VAT 9" x 9" | | |
| Independent Living Center 125 Small Closet by Entry Door | Expansion Seam Caulking | | |
| Independent Living Center 125 Small Closet by Entry Door | Floor Tile VAT 9" x 9" | Significantly damaged. | |
| Independent Living Center 125 Large Closet | Expansion Seam Caulking | | |
| Independent Living Center 125 Large Closet | Floor Tile VAT 12" x 12" | Significantly damaged. | |
| Kitchen Classroom in Independent Living Center 125 | Floor Tile VAT 12" x 12" | | |
| Kitchen Classroom in Independent Living Center 125 | Glue Dots associated with Blackboard | | |
| Kitchen Classroom in Independent Living Center 125 | Transite associated with Unit Ventilator, Interior | | |
| Kitchen Classroom in Independent Living Center 125 | ACM Unit Ventilator | | |
| Kitchen Classroom in Independent Living Center 125 | Floor Tile VAT 9" x 9" | | |
| Classroom 128 | Expansion Seam Caulking | | |
| Classroom 128 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 128 | Floor Tile VAT 9" x 9" associated with Foul Air Shaft | | |
| Classroom 128 | ACM Unit Ventilator | | |
| Classroom 128 | Glue Dots associated with Blackboard | | |
| Classroom 128 | Floor Tile VAT 9" x 9" | | |
| Classroom 128 Closet | Expansion Seam Caulking | Damaged. | |
| Classroom 128 Closet | Floor Tile VAT 9" x 9" | | |
| Teacher's Lounge Room 127 | Floor Tile VAT 12" x 12" | | |
| Teacher's Lounge Room 127 | Glue Dots associated with Blackboard | | |
| Teacher's Lounge Room 127 | Floor Tile VAT 9" x 9" | | |
| Girl's Restroom next to Teacher's Lounge 127 | Transite associated with Stall, Restroom | | |
| Classroom 133 | Glue Dots associated with Blackboard | | |
| Classroom 133 | Floor Tile VAT 12" x 12" | | |
| Classroom 133 Closet | Floor Tile VAT 12" x 12" | | |
| Classroom 133 Closet | Expansion Seam Caulking | | |
| Classroom 134 | Glue Dots associated with Blackboard | | |
| Classroom 134 | Floor Tile VAT 12" x 12" | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|--|--|------------------------|--|
| Classroom 134 Closet | Expansion Seam Caulking | | |
| Classroom 134 Closet | Floor Tile VAT 9" x 9" | | |
| Restroom in Classroom 134 | Floor Tile VAT 12" x 12" | | |
| Classroom 130 | Floor Tile VAT 12" x 12" | | |
| Classroom 132 | Floor Tile VAT 12" x 12" | | |
| Classroom 136 | Floor Tile VAT 12" x 12" | | |
| Classroom 135 | Expansion Seam Caulking | | |
| Classroom 135 | Floor Tile VAT 12" x 12" | Significantly damaged. | |
| Classroom 129 | Floor Tile VAT 12" x 12" | | |
| Classroom 131 | Floor Tile VAT 12" x 12" | | |
| Girl's Restroom across from Main Office | Transite associated with Stall, Restroom | | |
| Storage Closet 1-D across from Girls Restroom | Expansion Seam Caulking | | |
| Storage Closet 1-D across from Girls Restroom | Floor Tile VAT 9" x 9" | Significantly damaged. | |
| Stage Prop Storage Closet | Floor Tile VAT 9" x 9" | Damaged. | |
| Electrical Room for Stage Controls | Transite | | |
| Electrical Room for Stage Controls | Floor Tile VAT 9" x 9" | | |
| Closet in Electrical Room for Stage Controls | Transite associated with Fuse Box | | |
| Closet in Electrical Room for Stage Controls | Floor Tile VAT 9" x 9" | | |
| Auditorium | Transite associated with Radiator | | |
| Auditorium | Floor Tile VAT 12" x 12" | | |
| Auditorium | Floor Tile VAT 9" x 9" | | |
| Storage Closet at the Side of Auditorium across from Classroom 104 | Floor Tile VAT 9" x 9" | | |
| Custodial Closet in Hallway outside Music Technology Room 102 | Transite associated with Unit Ventilator, Interior | | |
| Custodial Closet in Hallway outside Music Technology Room 102 | ACM Unit Ventilator | | |
| Stage | Floor Tile VAT 9" x 9" | | |
| Stage | Floor Tile VAT 9" x 9" | | |
| Vice Principals Office in Main Office | Floor Tile VAT 12" x 12" | | |
| Former Restroom Storage in Vice Principals Office | Floor Tile VAT 9" x 9" | | |
| Large Storage in Vice Principals Office By Main Office | Floor Tile VAT 9" x 9" | | |
| Main Office 114 | Expansion Seam Caulking | | |
| Main Office 114 | Glue Dots associated with Blackboard | | |
| Main Office 114 | Transite associated with Unit Ventilator, Interior | | |
| Main Office 114 | ACM Unit Ventilator | | |
| Main Office 114 | Floor Tile VAT 12" x 12" | | |
| Storage Room in Main Office 114 at entrance | Floor Tile VAT 9" x 9" | | |
| Main Office Server Room outside Principals Office | Expansion Seam Caulking | | |
| Main Office Server Room outside Principals Office | Floor Tile VAT 9" x 9" | | |
| Principal's Office Restroom | Floor Tile VAT 12" x 12" | | |
| Principal's Office Storage Closet To The Right Of Principal Bathroom | Floor Tile VAT 9" x 9" | | |
| Conference Room 116 next to Principal's Office | Floor Tile VAT 12" x 12" | | |
| Mail Room 116A | Floor Tile VAT 12" x 12" | | |
| Closet in Conference Room next to Principal's Office | Floor Tile VAT 12" x 12" | | |
| Staff Lounge 118 across from Classroom 117 | Expansion Seam Caulking | | |
| Staff Lounge 118 across from Classroom 117 | Floor Tile VAT 12" x 12" | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|---|--|----------|--|
| Staff Lounge 118 across from Classroom 117 | Floor Tile VAT 9" x 9" | | |
| Womens Restroom in Staff Lounge across Classroom 117 | Floor Tile VAT 12" x 12" | | |
| Mens Restroom in Staff Lounge across Classroom 117 | Floor Tile VAT 12" x 12" | | |
| Mens Restroom in Staff Lounge across Classroom 117 | Floor Tile VAT 9" x 9" | | |
| Hallway leading from Music Classroom 100 to the Music Technology Room 102 | Floor Tile VAT 12" x 12" | Damaged. | |
| Hallway leading from Music Classroom 100 to the Music Technology Room 102 | ACM Unit Ventilator | | |
| Hallway leading from Music Classroom 100 to the Music Technology Room 102 | Transite associated with Unit Ventilator, Interior | | |
| Hallway leading from Music Classroom 100 to the Music Technology Room 102 | Floor Tile VAT 9" x 9" | | |
| Hallway that connects to Music Practice Rooms | Floor Tile VAT 12" x 12" | | |
| Hallway that connects to Music Practice Rooms | Floor Tile VAT 9" x 9" | | |
| Hallway from Counselors Suite 105 to Classroom 112 | Floor Tile VAT 12" x 12" | | |
| Hallway from Counselors Suite 105 to Classroom 112 | ACM Unit Ventilator | | |
| Hallway from Counselors Suite 105 to Classroom 112 | Transite associated with Unit Ventilator, Interior | | |
| Hallway from Counselors Suite 105 to Classroom 112 | Floor Tile VAT 9" x 9" | | |
| Hallway at Main Entrance at the Auditorium | Floor Tile VAT 12" x 12" | | |
| Hallway at Main Entrance at the Auditorium | ACM Unit Ventilator | | |
| Hallway at Main Entrance at the Auditorium | Transite associated with Unit Ventilator, Interior | | |
| Hallway at Main Entrance at the Auditorium | Floor Tile VAT 9" x 9" | | |
| Foyer in the Nurse's Suite 109 | Floor Tile VAT 12" x 12" | | |
| Foyer in the Nurse's Suite 109 | Floor Tile VAT 9" x 9" | | |
| Hallway in front of Classrooms 104-Music Technology Room 102 | Floor Tile VAT 12" x 12" | | |
| Hallway in front of Classrooms 104-Music Technology Room 102 | Transite associated with Unit Ventilator, Interior | | |
| Hallway in front of Classrooms 104-Music Technology Room 102 | ACM Unit Ventilator | | |
| Hallway in front of Classrooms 104-Music Technology Room 102 | Floor Tile VAT 9" x 9" | | |
| Hallway from Teachers Lounge 127 to Main Office | Electrical Wire Wrap associated with Unit Ventilator, Interior | | |
| Hallway from Teachers Lounge 127 to Main Office | Floor Tile VAT 12" x 12" | | |
| Hallway from Teachers Lounge 127 to Main Office | ACM Unit Ventilator | | |
| Hallway from Teachers Lounge 127 to Main Office | Transite associated with Unit Ventilator, Interior | | |
| Hallway from Teachers Lounge 127 to Main Office | Floor Tile VAT 9" x 9" | | |
| Hallway between Stairwell #5 and Stairwell #6 | Floor Tile VAT 9" x 9" | | |
| Hallway between Stairwell #5 and Stairwell #6 | Floor Tile VAT 12" x 12" | Damaged. | |
| Hallway between Stairwell #5 and Stairwell #6 | ACM Unit Ventilator | | |
| Hallway between Stairwell #5 and Stairwell #6 | Transite associated with Unit Ventilator, Interior | | |
| Hallway from Custodial Closet 140 to Classroom 135 | Floor Tile VAT 12" x 12" | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|--|--|----------|--|
| Hallway from Custodial Closet 140 to Classroom 135 | Floor Tile VAT 9" x 9" | | |
| Entire Hallway from area outside Classroom 130 to Stairwell #7 adjacent to Classroom 129 | Floor Tile VAT 12" x 12" | | |
| Stairwell #9 outside of Music Classroom 100 | ACM Unit Ventilator | | |
| Stairwell #9 outside of Music Classroom 100 | Transite associated with Unit Ventilator, Interior | | |
| Teacher's Lounge 200 | Expansion Seam Caulking | | |
| Teacher's Lounge 200 | Floor Tile VAT 12" x 12" | | |
| Teacher's Lounge 200 | Floor Tile VAT 9" x 9" | | |
| Classroom 202 Storage | Floor Tile VAT 12" x 12" | Damaged. | |
| Classroom 202 Storage | Floor Tile VAT 12" x 12" | | |
| Classroom 202 Storage | Floor Tile VAT 9" x 9" | | |
| Classroom 202 | Floor Tile VAT 12" x 12" | | |
| Classroom 202 | ACM Unit Ventilator | | |
| Classroom 202 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 202 | Glue Dots associated with Blackboard | | |
| Classroom 202 | Floor Tile VAT 9" x 9" | | |
| Closet across from Classroom 202 | Expansion Seam Caulking | | |
| Closet across from Classroom 202 | Floor Tile VAT 12" x 12" | | |
| Female Staff Restroom | Expansion Seam Caulking | | |
| Female Staff Restroom | Floor Tile VAT 12" x 12" | | |
| Laboratory Storage Room in between Classroom 209 & 207 | Transite associated with Unit Ventilator, Interior | | |
| Laboratory Storage Room in between Classroom 209 & 207 | ACM Unit Ventilator | | |
| Male Staff Restroom | Expansion Seam Caulking | | |
| Male Staff Restroom | Floor Tile VAT 12" x 12" | | |
| Male Staff Restroom | Floor Tile VAT 12" x 12" | | |
| Classroom 204 | Floor Tile VAT 12" x 12" | | |
| Classroom 204 | ACM Unit Ventilator | | |
| Classroom 204 | Glue Dots associated with Blackboard | | |
| Classroom 204 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 204 | Mastic associated with Floor Tile | | |
| Classroom 204 | Floor Tile VAT 9" x 9" | | |
| Classroom 204 Closet | Expansion Seam Caulking | | |
| Classroom 204 Closet | Floor Tile VAT 9" x 9" | | |
| Science Classroom 207 | Expansion Seam Caulking | | |
| Science Classroom 207 | ACM Unit Ventilator | | |
| Science Classroom 207 | Transite associated with Unit Ventilator, Interior | | |
| Science Classroom 207 | Floor Tile VAT 12" x 12" | | |
| Science Classroom 207 Closet | Expansion Seam Caulking | | |
| Science Classroom 207 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 208 | Floor Tile VAT 12" x 12" | | |
| Classroom 208 | ACM Unit Ventilator | | |
| Classroom 208 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 208 Closet | Expansion Seam Caulking | | |
| Classroom 208 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 206 | Expansion Seam Caulking | | |
| Classroom 206 | ACM Unit Ventilator | | |
| Classroom 206 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 206 | Floor Tile VAT 9" x 9" | | |
| Room 205 | Floor Tile VAT 9" x 9" | | |
| Room 205 | Expansion Seam Caulking | | |
| Room 205 | Floor Tile VAT 12" x 12" | | |
| Room 205 | ACM Unit Ventilator | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|------------------------------|--|---|--|
| Room 205 | Transite associated with Unit Ventilator, Interior | | |
| Room 205 Closet | Expansion Seam Caulking | | |
| Room 205 Closet | Floor Tile VAT 12" x 12" | | |
| Science Classroom 209 | Leveling Compound associated with Floor Tile | | |
| Science Classroom 209 | ACM Unit Ventilator | | |
| Science Classroom 209 | Transite associated with Unit Ventilator, Interior | | |
| Science Classroom 207 | Floor Tile VAT 12" x 12" | | |
| Science Classroom 207 Closet | Expansion Seam Caulking | | |
| Science Classroom 207 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 208 | Floor Tile VAT 12" x 12" | | |
| Classroom 208 | ACM Unit Ventilator | | |
| Classroom 208 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 208 Closet | Expansion Seam Caulking | | |
| Classroom 208 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 206 | Expansion Seam Caulking | | |
| Classroom 206 | ACM Unit Ventilator | | |
| Classroom 206 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 206 | Floor Tile VAT 9" x 9" | | |
| Room 205 | Floor Tile VAT 9" x 9" | | |
| Room 205 | Expansion Seam Caulking | | |
| Room 205 | Floor Tile VAT 12" x 12" | | |
| Room 205 | ACM Unit Ventilator | | |
| Room 205 | Transite associated with Unit Ventilator, Interior | | |
| Room 205 Closet | Expansion Seam Caulking | | |
| Room 205 Closet | Floor Tile VAT 12" x 12" | | |
| Science Classroom 209 | Leveling Compound associated with Floor Tile | | |
| Science Classroom 209 | ACM Unit Ventilator | | |
| Science Classroom 209 | Transite associated with Unit Ventilator, Interior | | |
| Science Classroom 209 Closet | Expansion Seam Caulking | | |
| Science Classroom 209 Closet | Floor Tile VAT 12" x 12" | | |
| Classroom 212 | Floor Tile VAT 12" x 12" | | |
| Classroom 212 | ACM Unit Ventilator | | |
| Classroom 212 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 212 | Floor Tile VAT 9" x 9" | Significantly damaged. | |
| Classroom 212 Closet | Expansion Seam Caulking | | |
| Classroom 212 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 210 Closet | Expansion Seam Caulking | Significantly damaged. | |
| Classroom 210 Closet | Floor Tile VAT 12" x 12" | Damaged. | |
| Classroom 210 | Floor Tile VAT 12" x 12" | | |
| Classroom 210 | ACM Unit Ventilator | | |
| Classroom 210 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 210 | Floor Tile VAT 9" x 9" | | |
| Classroom 218 | Floor Tile VAT 12" x 12" | Damaged. Previously reported as damaged in Jan 2013, Dec 2023, and July 2024. | |
| Classroom 218 | Mastic associated with Floor Tile | | |
| Classroom 218 | Expansion Seam Caulking | | |
| Classroom 218 | ACM Unit Ventilator | | |
| Classroom 218 | Glue Dots associated with Blackboard | | |
| Classroom 218 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 216 | Floor Tile VAT 12" x 12" | | |
| Classroom 216 | Glue Dots associated with Blackboard | | |
| Classroom 216 | Transite associated with Unit Ventilator, Interior | Significantly damaged. | |
| Classroom 216 | ACM Unit Ventilator | | |
| Classroom 216 | Floor Tile VAT 9" x 9" | | |
| Classroom 218 Closet | Floor Tile VAT 12" x 12" | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|----------------------|--|--|--|
| Classroom 218 Closet | Expansion Seam Caulking | | |
| Classroom 216 Closet | Floor Tile VAT 12" x 12" | | |
| Classroom 216 Closet | Floor Tile VAT 12" x 12" | | |
| Classroom 216 Closet | Expansion Seam Caulking | | |
| Classroom 220 | Floor Tile VAT 12" x 12" | | |
| Classroom 220 | ACM Unit Ventilator | | |
| Classroom 220 | Glue Dots associated with Blackboard | | |
| Classroom 220 | Expansion Seam Caulking | | |
| Classroom 220 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 220 | Floor Tile VAT 9" x 9" | | |
| Classroom 222 | Expansion Seam Caulking | | |
| Classroom 222 | Glue Dots associated with Blackboard | | |
| Classroom 222 | ACM Unit Ventilator | | |
| Classroom 222 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 222 | Mastic associated with Floor Tile | | |
| Classroom 222 | Floor Tile VAT 12" x 12" associated with Cabinet, Built-in | | |
| Classroom 222 | Floor Tile VAT 9" x 9" | | |
| Classroom 222 Closet | Expansion Seam Caulking | | |
| Classroom 222 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 219 | ACM Unit Ventilator | | |
| Classroom 219 | Glue Dots associated with Blackboard | | |
| Classroom 219 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 219 | Floor Tile VAT 9" x 9" | | |
| Classroom 219 Closet | Expansion Seam Caulking | | |
| Classroom 219 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 221 | Expansion Seam Caulking | | |
| Classroom 221 | Floor Tile VAT 12" x 12" | | |
| Classroom 221 | ACM Unit Ventilator | | |
| Classroom 221 | Glue Dots associated with Blackboard | | |
| Classroom 221 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 221 | Floor Tile VAT 9" x 9" | | |
| Classroom 224 | Floor Tile VAT 12" x 12" | Damaged. Previously reported as damaged in Dec 2023. | |
| Classroom 224 | ACM Unit Ventilator | | |
| Classroom 224 | Glue Dots associated with Blackboard | | |
| Classroom 224 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 224 | Floor Tile VAT 9" x 9" | | |
| Classroom 224 Closet | Expansion Seam Caulking | | |
| Classroom 224 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 223 | Floor Tile VAT 12" x 12" | | |
| Classroom 223 | Mastic associated with Floor Tile | | |
| Classroom 223 | Expansion Seam Caulking | | |
| Classroom 223 | ACM Unit Ventilator | | |
| Classroom 223 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 223 | Glue Dots associated with Blackboard | | |
| Classroom 223 | Floor Tile VAT 9" x 9" | | |
| Classroom 223 Closet | Floor Tile VAT 12" x 12" | | |
| Classroom 223 Closet | Expansion Seam Caulking | | |
| Classroom 226 | Expansion Seam Caulking | | |
| Classroom 226 | Floor Tile VAT 9" x 9" associated with Cabinet, Built-in | Damaged. Previously reported as damaged in Dec 2023. | |
| Classroom 226 | ACM Unit Ventilator | | |
| Classroom 226 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 226 | Glue Dots associated with Blackboard | | |
| Classroom 226 | Floor Tile VAT 9" x 9" | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|--|--|--|--|
| Classroom 226 Closet | Expansion Seam Caulking | | |
| Classroom 226 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 228 | Expansion Seam Caulking | | |
| Classroom 228 | Floor Tile VAT 9" x 9" associated with Cabinet, Built-in | | |
| Classroom 228 | Floor Tile VAT 12" x 12" | | |
| Classroom 228 | ACM Unit Ventilator | | |
| Classroom 228 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 228 | Glue Dots associated with Blackboard | | |
| Classroom 228 | Floor Tile VAT 9" x 9" | | |
| Classroom 228 Closet | Expansion Seam Caulking | | |
| Classroom 228 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 225 | Expansion Seam Caulking | | |
| Classroom 225 | Floor Tile VAT 12" x 12" | | |
| Classroom 225 | ACM Unit Ventilator | | |
| Classroom 225 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 225 | Glue Dots associated with Blackboard | | |
| Classroom 225 | Floor Tile VAT 9" x 9" | | |
| Classroom 225 Closet | Expansion Seam Caulking | | |
| Classroom 225 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 230 | Expansion Seam Caulking | | |
| Classroom 230 | Floor Tile VAT 12" x 12" | | |
| Classroom 230 | ACM Unit Ventilator | | |
| Classroom 230 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 230 | Glue Dots associated with Blackboard | Significantly damaged. | |
| Classroom 230 | Floor Tile VAT 9" x 9" | | |
| Classroom 230 Closet | Expansion Seam Caulking | | |
| Classroom 230 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 232 | Expansion Seam Caulking | | |
| Classroom 232 | ACM Unit Ventilator | | |
| Classroom 232 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 232 | Glue Dots associated with Blackboard | | |
| Classroom 232 | Floor Tile VAT 9" x 9" | | |
| Classroom 232 Closet | Expansion Seam Caulking | | |
| Classroom 232 Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 229 | Transite associated with Electrical Panel | | |
| Classroom 229 | Expansion Seam Caulking | | |
| Classroom 229 | Floor Tile VAT 12" x 12" | | |
| Classroom 229 | ACM Unit Ventilator | | |
| Classroom 229 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 229 | Glue Dots associated with Blackboard | | |
| Classroom 229 | Floor Tile VAT 9" x 9" | | |
| Classroom 229 Small Closet | Expansion Seam Caulking | | |
| Classroom 229 Small Closet | Floor Tile VAT 9" x 9" | | |
| Classroom 229 Large Closet | Floor Tile VAT 12" x 12" | | |
| Classroom 229 Large Closet | Expansion Seam Caulking | | |
| Classroom 229 Large Closet | Floor Tile VAT 9" x 9" | | |
| Girl's Gym 233 | Glue Dots associated with Blackboard | | |
| Gym Teacher's Office 234A | Glue Dots associated with Blackboard | | |
| Gym Teacher's Office 234A | Floor Tile VAT 9" x 9" | | |
| Gym Teachers Office 234A Restroom | Floor Tile VAT 12" x 12" | Damaged. Previously reported as damaged in Dec 2023. | |
| Gym Teachers Office 234A Restroom | Floor Tile VAT 12" x 12" | | |
| Gym Teachers Office 234A Closet next to Restroom | Floor Tile VAT 9" x 9" | | |
| Gym Teachers Office 324A Closet along back wall | Floor Tile VAT 12" x 12" | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|---|--|------------------------|--|
| Gym Teachers Office 324A Closet along back wall | Mastic associated with Floor Tile | | |
| Girls Gym 233 Storage Closet 234B | Floor Tile VAT 9" x 9" | Significantly damaged. | |
| Boy's Gym 234 | Glue Dots associated with Blackboard | | |
| Boy's Gym 234 | Floor Tile VAT 9" x 9" | | |
| Gym Teachers Office 233A | Floor Tile VAT 9" x 9" | | |
| Gym Teachers Office 233A | Floor Tile VAT 12" x 12" | | |
| Gym Teachers Office 233A Closet along back wall | Floor Tile VAT 9" x 9" | | |
| Gym Teachers Office 233A Closet next to Restroom | Floor Tile VAT 9" x 9" | | |
| Gym Teacher's Office 233A Restroom | Floor Tile VAT 9" x 9" | | |
| Gym Teacher's Office 233A Restroom | Floor Tile VAT 12" x 12" | | |
| Classroom 227 | ACM Unit Ventilator | | |
| Classroom 227 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 227 | Glue Dots associated with Blackboard | | |
| Classroom 227 | Floor Tile VAT 12" x 12" | | |
| Counselor's Office 231 | Floor Tile VAT 12" x 12" | | |
| Counselor's Office 231 | Glue Dots associated with Blackboard | | |
| Counselor's Office 231 | Floor Tile VAT 9" x 9" | | |
| Girl's Restroom across from Classroom 232 | Transite associated with Stall, Restroom | | |
| Roster Office 215 | Expansion Seam Caulking | | |
| Roster Office 215 | Floor Tile VAT 12" x 12" | | |
| Roster Office 215 | Floor Tile VAT 12" x 12" | | |
| Roster Office 215 | Floor Tile VAT 9" x 9" | | |
| Restroom in Roster Office 215 | Expansion Seam Caulking | | |
| Restroom in Roster Office 215 | Floor Tile VAT 12" x 12" | | |
| Girl's Restroom across Classroom 216 | Transite associated with Stall, Restroom | | |
| Boy's Restroom across from Room 200 | Expansion Seam Caulking | | |
| Boys' Restroom next to Classroom 223 | Expansion Seam Caulking | | |
| Foyer outside Classroom 202 | Floor Tile VAT 12" x 12" | | |
| Foyer outside Classroom 202 | Floor Tile VAT 9" x 9" | | |
| Foyer outside Staff Restrooms | Expansion Seam Caulking | | |
| Foyer outside Staff Restrooms | Glue Dots associated with Blackboard | | |
| Foyer outside Staff Restrooms | Floor Tile VAT 12" x 12" | | |
| Hallway from Counselors Office 231 to Classroom 216 | Mastic associated with Floor Tile | | |
| Hallway from Counselors Office 231 to Classroom 216 | Floor Tile VAT 9" x 9" | | |
| Hallway from Counselors Office 231 to Classroom 216 | ACM Unit Ventilator | | |
| Hallway from Counselors Office 231 to Classroom 216 | Transite associated with Unit Ventilator, Interior | | |
| Hallway from Main Hallway to the Classroom 202 | ACM Unit Ventilator | | |
| Hallway from Main Hallway to the Classroom 202 | Transite associated with Unit Ventilator, Interior | | |
| Hallway from Main Hallway to the Classroom 202 | Floor Tile VAT 12" x 12" | | |
| Hallway between Classroom 216 and Room 200 | Floor Tile VAT 12" x 12" | | |
| Hallway between Classroom 216 and Room 200 | Floor Tile VAT 9" x 9" | | |
| Hallway between Classroom 216 and Room 200 | ACM Unit Ventilator | | |
| Hallway between Classroom 216 and Room 200 | Transite associated with Unit Ventilator, Interior | | |
| Hallway outside Gymnasium Entrances | Floor Tile VAT 9" x 9" | | |
| Hallway outside Gymnasium Entrances | Floor Tile VAT 12" x 12" | | |
| Hallway outside Gymnasium Entrances | Transite associated with Unit Ventilator, Interior | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|---|--|--|--|
| Hallway outside Gymnasium Entrances | ACM Unit Ventilator | | |
| Hallway from Room 200 to Classroom 212 | Floor Tile VAT 12" x 12" | | |
| Hallway from Room 200 to Classroom 212 | ACM Unit Ventilator | | |
| Hallway from Room 200 to Classroom 212 | Transite associated with Unit Ventilator, Interior | | |
| Hallway from Room 200 to Classroom 212 | Floor Tile VAT 12" x 12" | | |
| Fan Room above the Gymnasiums | Transite associated with Electrical Panel | | |
| Fan Room above the Gymnasiums | Caulk associated with Fan Unit, Exterior | | |
| Fan Room above the Gymnasiums | Caulk associated with Fan Unit, Interior | | |
| Fan Room above the Gymnasiums | Expansion Seam Caulking associated with Wall, CMU | | |
| Fan Penthouse above Auditorium | Caulk associated with Fan Unit, Interior | | |
| Auditorium Attic | Damp Proofing | | |
| Auditorium Attic | Electrical Wire Wrap associated with Stage Light | | |
| Small Electrical Room with Crawlspace access (accessed from Stairwell#4 near Mens Restroom) | Fire Doors | | |
| Large Electrical Room (accessed from Stairwell#4 near Mens Restroom) | Fire Doors | | |
| Room B5 | Transite associated with Unit Ventilator, Interior | | |
| Room B5 | ACM Unit Ventilator | | |
| Room B5 | Glue Dots associated with Blackboard | | |
| Room B5 | Floor Tile VAT 12" x 12" | | |
| Restroom inside Facilities Management Office | Floor Tile VAT 12" x 12" | | |
| Storage in Facilities Area Management Office next to Conference B3 | Floor Tile VAT 9" x 9" | | |
| Conference Room B3 | Transite associated with Unit Ventilator, Interior | | |
| Conference Room B3 | ACM Unit Ventilator | | |
| Conference Room B3 | Floor Tile VAT 12" x 12" | | |
| Men's Restroom across from Room 5 | Transite associated with Stall, Restroom | | |
| Large Far Left Office in Office Suite 5 | Mastic associated with Floor Tile | | |
| Large Far Left Office in Office Suite 5 | Transite associated with Unit Ventilator, Interior | | |
| Large Far Left Office in Office Suite 5 | ACM Unit Ventilator | | |
| Large Far Left Office in Office Suite 5 | Floor Tile VAT 12" x 12" associated with Cabinet, Built-in | | |
| Large Far Left Office in Office Suite 5 | Glue Dots associated with Blackboard | | |
| Large Far Left Office in Office Suite 5 | Floor Tile VAT 12" x 12" | | |
| Storage Room in Large Far Left Office in Office Suite 5 | Mastic associated with Floor Tile | | |
| Storage Room in Large Far Left Office in Office Suite 5 | Expansion Seam Caulking | | |
| Storage Room in Large Far Left Office in Office Suite 5 | Floor Tile VAT 12" x 12" | | |
| Right Office in Office Suite 5 | Mastic associated with Floor Tile | | |
| Right Office in Office Suite 5 | ACM Unit Ventilator | | |
| Right Office in Office Suite 5 | Transite associated with Unit Ventilator, Interior | | |
| Right Office in Office Suite 5 | Floor Tile VAT 12" x 12" associated with Cabinet, Built-in | | |
| Right Office in Office Suite 5 | Glue Dots associated with Blackboard | | |
| Right Office in Office Suite 5 | Floor Tile VAT 12" x 12" | | |
| Closet in Right Office in Office Suite 5 | Mastic associated with Floor Tile | | |
| Closet in Right Office in Office Suite 5 | Expansion Seam Caulking | | |
| Closet in Right Office in Office Suite 5 | Floor Tile VAT 12" x 12" | | |
| Office 8 Break Room (window side) | Mastic associated with Floor Tile | | |
| Office 8 Break Room (window side) | Floor Tile VAT 12" x 12" | | |
| Conference Room Behind Mail/IT Room | ACM Unit Ventilator | | |
| Conference Room Behind Mail/IT Room | Transite associated with Unit Ventilator, Interior | | |
| Conference Room Behind Mail/IT Room | Glue Dots associated with Blackboard | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|---|--|--|--|
| Conference Room Behind Mail/IT Room Closet by Window | Floor Tile VAT 12" x 12" | | |
| Conference Room Behind Mail/IT Room Closet by Window | Floor Tile VAT 12" x 12" | | |
| Classroom 9 Storage Closet to the Window | Floor Tile VAT 9" x 9" | | |
| Classroom 9 Storage Closet to the Window | Floor Tile VAT 12" x 12" | | |
| Classroom 9 Storage Closet to the Window | Floor Tile VAT 12" x 12" | | |
| Classroom 9 Storage Closet Hallway Side | Mastic associated with Floor Tile | | |
| Classroom 9 Storage Closet Hallway Side | Floor Tile VAT 9" x 9" | | |
| Kitchen Womens Restroom | Transite associated with Stall, Restroom | | |
| Small Hallway next to Music Classroom 1 that leads to exit door to exterior | Floor Tile VAT 9" x 9" | | |
| Music Room 1 | Floor Tile VAT 12" x 12" | | |
| Music Room 1 | Mastic associated with Cove Base | | |
| Music Room 1 | Floor Tile VAT 9" x 9" | | |
| Music Room 2 | Mastic associated with Cove Base | | |
| Music Room 2 | Glue Dots associated with Blackboard | | |
| Music Room 2 | Floor Tile VAT 9" x 9" | | |
| Music Room 3 | Floor Tile VAT 12" x 12" | | |
| Music Room 3 | Glue Dots associated with Blackboard | | |
| Music Room 3 | Floor Tile VAT 9" x 9" | | |
| Music Room 3 | Mastic associated with Cove Base | | |
| Music Room 5 | Mastic associated with Cove Base | | |
| Music Room 5 | Glue Dots associated with Blackboard | | |
| Music Room 5 | Floor Tile VAT 12" x 12" | | |
| Music Room 5 | Floor Tile VAT 12" x 12" | | |
| Pump Room in Music Room 5 | Floor Tile VAT 12" x 12" | | |
| Music Storage Room 4 | Glue Dots associated with Blackboard | | |
| Music Storage Room 4 | Floor Tile VAT 9" x 9" | | |
| Storage across from Stairwell #3 | Floor Tile VAT 9" x 9" | | |
| Classroom 1 | ACM Unit Ventilator | | |
| Classroom 1 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 1 | Floor Tile VAT 12" x 12" associated with Cabinet, Built-in | | |
| Classroom 1 | Expansion Seam Caulking | | |
| Classroom 1 | Glue Dots associated with Blackboard | | |
| Classroom 1 | Floor Tile VAT 12" x 12" | | |
| Classroom 1 | Floor Tile VAT 12" x 12" | | |
| Assistant Superintendent's Office across from Room 9 | Mastic associated with Floor Tile | | |
| Assistant Superintendent's Office across from Room 9 | ACM Unit Ventilator | | |
| Assistant Superintendent's Office across from Room 9 | Transite associated with Unit Ventilator, Interior | | |
| Assistant Superintendent's Office across from Room 9 | Floor Tile VAT 12" x 12" | | |
| Assistant Superintendent's Office Restroom | Mastic associated with Floor Tile | | |
| Assistant Superintendent's Office Restroom | Floor Tile VAT 12" x 12" | | |
| Main Cubicle Area in Office 8 | Mastic associated with Floor Tile | | |
| Main Cubicle Area in Office 8 | ACM Unit Ventilator | | |
| Main Cubicle Area in Office 8 | Transite associated with Unit Ventilator, Interior | | |
| Main Cubicle Area in Office 8 | Sink Undercoat Mastic | | |
| Main Cubicle Area in Office 8 | Glue Dots associated with Blackboard | | |
| Main Cubicle Area in Office 8 | Floor Tile VAT 12" x 12" | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|--|--|--|--|
| Assistant Superintendent's Office Closet | Mastic associated with Floor Tile | | |
| Assistant Superintendent's Office Closet | Floor Tile VAT 12" x 12" | | |
| Middle Closet in Office 8 | Mastic associated with Floor Tile | | |
| Middle Closet in Office 8 | Floor Tile VAT 9" x 9" | | |
| Closet in Office 8 closest to Hallway | Mastic associated with Floor Tile | | |
| Closet in Office 8 closest to Hallway | Floor Tile VAT 9" x 9" | | |
| Leeds Supply Closet next to Custodial Closet | Glue Dots associated with Blackboard | | |
| Leeds Supply Closet next to Custodial Closet | Transite associated with Unit Ventilator, Interior | | |
| Leeds Supply Closet next to Custodial Closet | ACM Unit Ventilator | | |
| Leeds Supply Closet next to Custodial Closet | Floor Tile VAT 9" x 9" | | |
| Supply Closet to right of Stairwell #6 | Floor Tile VAT 12" x 12" | | |
| Supply Closet to right of Stairwell #6 | Floor Tile VAT 9" x 9" | | |
| Boiler Room Upper and Lower Levels | Boilers | | |
| Restroom in Men's Lounge in BE Area | Transite associated with Stall, Restroom | | |
| Restroom in Women's Lounge in BE Area | Transite associated with Stall, Restroom | | |
| Classroom 1 Closet | Floor Tile VAT 12" x 12" | | |
| Classroom 1 Closet | Floor Tile VAT 12" x 12" | | |
| Building Engineer's (BE) Office | Glue Dots associated with Blackboard | | |
| Building Engineer's Office Restroom | Transite associated with Stall, Restroom | | |
| Custodial Storage across from Women's Lounge in BE Area | Floor Tile VAT 9" x 9" | | |
| Storage 22 adjacent Women's Restroom | Floor Tile VAT 12" x 12" | | |
| Elevator Machine Room | Floor Tile VAT 12" x 12" | | |
| Women's Restroom next to Assistant Superintendent's Office | Floor Tile VAT 12" x 12" | | |
| Girls' Restroom near Cafeteria Entrance | Transite associated with Stall, Restroom | | |
| Boy's Restroom at Cafeteria Entrance | Expansion Seam Caulking | | |
| Former Serving Area And Faculty Lunch Room (to the Far Right of Kitchen) | Floor Tile VAT 12" x 12" | | |
| Former Serving Area And Faculty Lunch Room (to the Far Right of Kitchen) | ACM Unit Ventilator | | |
| Former Serving Area And Faculty Lunch Room (to the Far Right of Kitchen) | Transite associated with Unit Ventilator, Interior | | |
| Former Serving Area And Faculty Lunch Room (to the Far Right of Kitchen) | Floor Tile VAT 9" x 9" | | |
| Closet in Cafeteria adjacent to Stairwell #1 | Floor Tile VAT 12" x 12" | | |
| Closet at the Cafeteria Entrance | Floor Tile VAT 12" x 12" | | |
| Book Storage Suite - Far Left Office | Transite associated with Unit Ventilator, Interior | | |
| Book Storage Suite - Far Left Office | ACM Unit Ventilator | | |
| Book Storage Suite - Far Left Office | Floor Tile VAT 12" x 12" associated with Cabinet, Built-in | | |
| Book Storage Suite - Far Left Office | Floor Tile VAT 12" x 12" | | |
| Book Storage Suite - Middle Room | Floor Tile VAT 12" x 12" associated with Cabinet, Built-in | | |
| Book Storage Suite - Middle Room | Transite associated with Unit Ventilator, Interior | | |
| Book Storage Suite - Middle Room | ACM Unit Ventilator | | |
| Book Storage Suite - Middle Room | Floor Tile VAT 12" x 12" | | |
| Book Storage Suite - Far Right Room | Floor Tile VAT 12" x 12" | | |
| Classroom 003 | Floor Tile VAT 12" x 12" associated with Cabinet, Built-in | | |
| Classroom 003 | ACM Unit Ventilator | | |
| Classroom 003 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 003 | Floor Tile VAT 12" x 12" | | |
| Classroom 003 | Floor Tile VAT 12" x 12" | | |
| Classroom 003 | Glue Dots associated with Blackboard | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|---|--|--|--|
| Cafeteria | Glue Dots associated with Blackboard | | |
| Cafeteria | Mastic associated with Floor Tile | | |
| Music Room Suite Open Area | Floor Tile VAT 12" x 12" | | |
| Music Room Suite Open Area | Floor Tile VAT 9" x 9" | | |
| Incinerator Room Upstairs & Downstairs | Fire Brick associated with Incinerator | | |
| Incinerator Room Upstairs & Downstairs | Fire Doors | | |
| Teacher's Lounge 36 across from Girls Restroom | Floor Tile VAT 12" x 12" | | |
| Teacher's Lounge 36 across from Girls Restroom | Glue Dots associated with Blackboard | | |
| Teacher's Lounge 36 Foyer outside Mens Restroom | Floor Tile VAT 12" x 12" | | |
| Teacher's Lounge 36 Mens Restroom | Floor Tile VAT 12" x 12" | | |
| Teacher's Lounge 36 Mens Restroom | Floor Tile VAT 12" x 12" | | |
| Teacher's Lounge 36 Mens Restroom | Transite associated with Stall, Restroom | | |
| Teacher's Lounge 36 Foyer outside Womens Restroom | Floor Tile VAT 12" x 12" | | |
| Teacher's Lounge 36 Womens Restroom | Floor Tile VAT 12" x 12" | | |
| Teacher's Lounge 36 Womens Restroom | Floor Tile VAT 12" x 12" | | |
| Teacher's Lounge 36 Womens Restroom | Transite associated with Stall, Restroom | | |
| Classroom 003 Closet | Floor Tile VAT 12" x 12" | | |
| Classroom 003 Closet | Floor Tile VAT 12" x 12" | | |
| Room B4 | Floor Tile VAT 12" x 12" | | |
| Classroom 005 | ACM Unit Ventilator | | |
| Classroom 005 | Floor Tile VAT 9" x 9" associated with Foul Air Shaft | | |
| Classroom 005 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 005 | Floor Tile VAT 12" x 12" | | |
| Classroom 005 Closet | Floor Tile VAT 12" x 12" | | |
| Middle Office in Office Suite 5 | Mastic associated with Floor Tile | | |
| Middle Office in Office Suite 5 | Floor Tile VAT 12" x 12" associated with Cabinet, Built-in | | |
| Middle Office in Office Suite 5 | Floor Tile VAT 12" x 12" | | |
| Computer Lab Room 6 | Mastic associated with Floor Tile | | |
| Computer Lab Room 6 | Floor Tile VAT 12" x 12" | | |
| Computer Lab Room 6 | ACM Unit Ventilator | | |
| Computer Lab Room 6 | Transite associated with Unit Ventilator, Interior | | |
| Computer Lab Room 6 | Floor Tile VAT 12" x 12" associated with Cabinet, Built-in | | |
| Computer Lab Room 6 | Floor Tile VAT 12" x 12" | | |
| Computer Lab Room 6 | Glue Dots associated with Blackboard | | |
| Computer Lab Room 6 Closet | Expansion Seam Caulking | | |
| Computer Lab Room 6 Closet | Floor Tile VAT 9" x 9" | | |
| Room 7 | Mastic associated with Floor Tile | | |
| Room 7 | ACM Unit Ventilator | | |
| Room 7 | Transite associated with Unit Ventilator, Interior | | |
| Room 7 | Floor Tile VAT 12" x 12" associated with Cabinet, Built-in | | |
| Mail/IT Room across from Office 8 | Mastic associated with Floor Tile | | |
| Mail/IT Room across from Office 8 | Floor Tile VAT 12" x 12" | | |
| Mail/IT Room across from Office 8 | Floor Tile VAT 12" x 12" | | |
| Mail/IT Room across from Office 8 | Floor Tile VAT 9" x 9" | | |
| Office within Room 7 | Transite associated with Electrical Panel | | |
| Office within Room 7 | Glue Dots associated with Blackboard | | |
| Room 7 Storage in Middle of Room | Mastic associated with Floor Tile | | |
| Room 7 Storage in Middle of Room | Floor Tile VAT 9" x 9" | | |

Hill-Freeman World Academy at Leeds:

Asbestos Hazard Report

| | | | |
|--|--|--|--|
| Classroom 9 | Mastic associated with Floor Tile | | |
| Classroom 9 | ACM Unit Ventilator | | |
| Classroom 9 | Transite associated with Unit Ventilator, Interior | | |
| Classroom 9 | Floor Tile VAT 12" x 12" associated with Cabinet, Built-in | | |
| Classroom 9 | Glue Dots associated with Blackboard | | |
| Classroom 9 | Floor Tile VAT 9" x 9" associated with Foul Air Shaft | | |
| Classroom 9 | Floor Tile VAT 12" x 12" | | |
| Classroom 9 Closet next to Entrance Door | Floor Tile VAT 9" x 9" | | |
| Hallway from Cafeteria to Music Suite | Floor Tile VAT 12" x 12" | | |
| Hallway from Cafeteria to Music Suite | Floor Tile VAT 9" x 9" | | |
| Hallway in Book Storage Suite (across Classroom 003) | Floor Tile VAT 12" x 12" | | |
| Hallway in Book Storage Suite (across Classroom 003) | Glue Dots associated with Blackboard | | |
| Hallway in Book Storage Suite (across Classroom 003) | Floor Tile VAT 12" x 12" | | |
| Closet in Hallway in Book Storage Suite | Floor Tile VAT 12" x 12" | | |
| Hallway at Incinerator Room from the Girl's Restroom to the Boy's Restroom | Transite associated with Unit Ventilator, Interior | | |
| Hallway at Incinerator Room from the Girl's Restroom to the Boy's Restroom | ACM Unit Ventilator | | |
| Hallway at Incinerator Room from the Girl's Restroom to the Boy's Restroom | Floor Tile VAT 12" x 12" | | |
| Hallway at Incinerator Room from the Girl's Restroom to the Boy's Restroom | Floor Tile VAT 9" x 9" | | |
| Hallway from Classroom 9 through double doors to Girls Restroom | Floor Tile VAT 9" x 9" | | |
| Hallway from Classroom 9 through double doors to Girls Restroom | Transite associated with Unit Ventilator, Interior | | |
| Hallway from Classroom 9 through double doors to Girls Restroom | ACM Unit Ventilator | | |
| Hallway outside Office Suite 5 | Mastic associated with Floor Tile | | |
| Hallway outside Office Suite 5 | Glue Dots associated with Blackboard | | |
| Hallway outside Office Suite 5 | Floor Tile VAT 12" x 12" | | |
| Hallway outside Room B5 to Conference Room B3 | Mastic associated with Floor Tile | | |
| Hallway outside Room B5 to Conference Room B3 | Floor Tile VAT 12" x 12" | | |
| Hallway adjacent Elevator to Stairs 5 & 6 | Floor Tile VAT 12" x 12" | | |
| Hallway adjacent Elevator to Stairs 5 & 6 | Transite associated with Unit Ventilator, Interior | | |
| Hallway adjacent Elevator to Stairs 5 & 6 | ACM Unit Ventilator | | |
| Hallway adjacent Elevator to Stairs 5 & 6 | Floor Tile VAT 9" x 9" | | |
| Stairwell #2 outside Music Suite | ACM Unit Ventilator | | |
| Stairwell #2 outside Music Suite | Transite associated with Unit Ventilator, Interior | | |