

# Henry W. Lawton School: Asbestos Hazard Report

The Philadelphia Regional Center for Children's Environmental Health has partnered with the Healthy Schools Initiative to analyze and report on public information regarding asbestos conditions in schools made available on the School District of Philadelphia's website.

This report is meant to communicate to parents, teachers, and staff the exposure risk at their school and help prioritize the removal of asbestos in high-risk exposure locations.

Our analysis is based on publicly available reports. We have not conducted inspections or verified the reports.

## Key Findings:

- 82 teacher / student occupied spaces have asbestos containing material (ACM)
- 3 spaces had damaged ACM
- 61 spaces contained friable ACM
- **All damaged** materials were scheduled to be abated

## Our Recommendations:

- The School District scheduled the abatement for all four damaged friable ACM identified during their latest inspection in Jul 2025.
- The School District is required to regularly monitor the condition of its ACM by the EPA. We recommend the complete removal of friable ACM instead of encapsulation for materials that have been repeatedly damaged, such as the paint in classroom 206 (See Table 1).



A Program of:





## What is asbestos?

**Asbestos is a fibrous material that is resistant to heat, water, and corrosion.**

See this link for a comprehensive list: <https://prcceh.upenn.edu/asbestos>

## What are the health effects of asbestos?

No immediate health impacts are expected from asbestos exposure in schools. However, breathing asbestos fibers in schools may increase the risk of developing cancer many years from now.

Children are very active, breathing more air while running and playing. Children take more breaths per minute than adults and are lower to the ground where asbestos fibers may settle. This puts them at an increased risk for asbestos exposure.

## How are damaged asbestos containing materials managed?

Asbestos can be removed. Sometimes damaged materials are managed in place by patching, encapsulating (using a specially formulated paint-like coating) or building an enclosure around damaged and/or accessible materials. All of these are forms of abatement.

The Environmental Protection Agency requires all remaining asbestos containing material to be inspected by the school district every six months. This is documented in an Asbestos Hazard Emergency Response Act Report (AHERA Report).

## Asbestos was used in materials in schools, including:

- Ceiling Tiles
- Floor Tiles
- Pipe Insulation
- Cement
- Paint and Caulk
- Soundproofing
- Fireproofing
- Plaster Materials

## Are all asbestos containing materials of equal risk?

Some asbestos containing materials like ceiling and floor tiles have asbestos fibers imbedded in other materials. As long as they are not broken or damaged the asbestos fibers are not released into the air.

Some asbestos containing materials like insulation on pipe remains fibrous and can easily be released in the air when damaged.

### Important Terms

*Get to know these terms to make the most out of this report.*

**Damaged Asbestos Containing Material (ACM)** can release asbestos fibers into the air.

**Friable Materials** can be reduced to a powder by applying hand pressure. **DO NOT TOUCH!**

**Non-Friable materials** are not easily damaged.

**Significantly damaged materials** are more than 10% damaged.

**Abated ACM** means repaired, removed, or reduced risk of exposure.

## Detailed Review for Henry W. Lawton School

This school has 90 spaces with asbestos containing materials. 82 of them are in teacher / student occupied spaces. The School District last inspected ACM in Jul 2025 and published the AHERA report in Aug 2025. Since then, the School District scheduled the abatement of all 4 damaged asbestos containing materials identified during this inspection. All damaged materials identified were friable ACM (see Table 1).

We recommend that the School District completely remove friable ACM that has been repeatedly damaged in the past, such as the paint in Classroom 206, as listed in Table 1. A list of all the ACM in the school and their damage/abatement schedule can be found in the tables at the end of this report. The Air Management Services website does not confirm that the abatement scheduled in 2025 in response to the Aug 2025 AHERA report was completed.



### Information Reviewed to Make this Report:

The 2025/26 AHERA report from the School District of Philadelphia, and asbestos abatement notifications from the Air Management Services Online Portal.

**Not included** in this report are planned repairs to damaged asbestos materials that have not been uploaded to the Air Management Services website or any updated after December 12, 2025. To see the most current information, scan these QR Codes. After scanning, search for your school.

#### School Districts of Philadelphia Asbestos Reports:



AHERA Reports are documents generated from EPA required asbestos inspections

#### Office of the Controller Asbestos Project:



Asbestos abatement notification forms



Report what you see!

Parents and teachers should report hazardous conditions in schools on the Healthy Schools app.

Scan here to download the app:



### Disclaimer:

This report analyzes custodial and mechanical spaces like boiler rooms **only** when ACM is significantly damaged (damage > 10%).

## Questions?

Find more resources on our website!

[prcch.upenn.edu/asbestos](http://prcch.upenn.edu/asbestos)

- Photo gallery of different types of damaged asbestos containing materials
- Guide to how we classify materials in schools
- Our analysis and reporting methodology
- What we do with the information in this report



Email us at [prcch@pennmedicine.upenn.edu](mailto:prcch@pennmedicine.upenn.edu) or call 215-573-9076

Table 1: Friable Asbestos Containing Materials Identified

NOTE: Friable materials can be reduced to a powder by applying hand pressure.

***Do not touch it!*** Damaged and significantly damaged friable materials readily release harmful asbestos fibers into the air.

Location	Material Name	Reported as Damaged or Significantly Damaged? (Blank = No)	Abatement scheduled since the inspection? (Blank = No)
Classroom 101 Restroom	Paint associated with Ceiling, Concrete		
Classroom 101 Closet	Paint associated with Ceiling, Concrete		
Classroom 101 Closet	Paint associated with Wall, CMU		
Classroom 101 Closet	Paint associated with Ceiling, Concrete		
Classroom 102	Paint associated with Wall, CMU		
Classroom 102	Paint associated with Ceiling, Concrete		
Classroom 102 Closet Closer To Hall	Paint associated with Ceiling, Concrete		
Classroom 102 Closet Closer To Hall	Paint associated with Wall, CMU		
Classroom 102 Closet Closest To Playground Exit	Paint associated with Ceiling, Concrete		
Classroom 102 Closet Closest To Playground Exit	Paint associated with Wall, CMU		
Nurse's Suite Waiting Area	Paint associated with Ceiling, Concrete		
Nurse's Suite Waiting Area	Paint associated with Wall, CMU		

# Henry W. Lawton School: Asbestos Hazard Report

Nurse's Suite Office	Paint associated with Ceiling, Concrete	Damaged.	Encapsulation scheduled for Aug-Nov 2025.
Nurse's Suite Office	Paint associated with Wall, CMU	Damaged.	Encapsulation scheduled for Aug-Nov 2025.
Nurse's Suite Treatment Room	Paint associated with Ceiling, Concrete		
Nurse's Suite Treatment Room	Paint associated with Wall, CMU		
Nurse's Suite Closet	Paint associated with Ceiling, Concrete		
Nurse's Suite Closet	Paint associated with Wall, CMU		
Nurse's Suite Restroom	Paint associated with Ceiling, Concrete		
Classroom 104	Paint associated with Wall, CMU		
Classroom 104	Paint associated with Ceiling, Concrete		
Classroom 104 Restroom	Paint associated with Wall, CMU		
Classroom 104 Restroom	Paint associated with Ceiling, Concrete		
Classroom 104 Closet	Paint associated with Wall, CMU		
Classroom 104 Closet	Paint associated with Ceiling, Concrete		
Main Office	Paint associated with Ceiling, Concrete		
Principal's Office	Paint associated with Ceiling, Concrete		
Principal's Office	Paint associated with Wall, CMU		
School Counselor Office	Paint associated with Ceiling, Concrete		
School Counselor Office	Paint associated with Wall, CMU		
Main Office Kitchenette	Paint associated with Wall, CMU		
Main Office Server Room	Paint associated with Ceiling, Concrete		
Main Office Server Room	Paint associated with Wall, CMU		
Principal's Closet	Paint associated with Ceiling, Concrete		
Principal's Closet	Paint associated with Wall, CMU		
Principal's Restroom	Paint associated with Wall, CMU		
Storage Room accross from Main Office	Paint associated with Ceiling, Concrete		
Storage Room accross from Main Office	Paint associated with Wall, CMU		
Custodial Room	Paint associated with Wall, CMU		
Classroom 103	Paint associated with Wall, CMU		
Classroom 103	Paint associated with Ceiling, Concrete		
Girl's Restroom	Paint associated with Wall, CMU		
Girl's Restroom	Paint associated with Ceiling, Concrete		
Gender Neutral Restroom	Paint associated with Ceiling, Concrete		
Gender Neutral Restroom	Paint associated with Wall, CMU		
Classroom 105	Paint associated with Wall, CMU		
Classroom 105	Paint associated with Ceiling, Concrete		
Boy's Restroom	Paint associated with Wall, CMU		
Boy's Restroom	Paint associated with Ceiling, Concrete		
Staff Restroom	Paint associated with Wall, CMU		
Staff Restroom	Paint associated with Ceiling, Concrete		
Classroom 107	Paint associated with Ceiling, Concrete		

# Henry W. Lawton School: Asbestos Hazard Report

Kitchen Staff Locker	Paint associated with Wall, CMU		
Building Engineer's Office	Paint associated with Ceiling, Concrete		
Staff Locker Room	Paint associated with Wall, CMU		
Staff Locker Room	Paint associated with Ceiling, Concrete		
Building Engineer's Restroom	Paint associated with Ceiling, Concrete		
Building Engineer's Restroom	Paint associated with Wall, CMU		
Staff Restroom	Paint associated with Ceiling, Concrete		
Staff Restroom	Paint associated with Wall, CMU		
Building Engineer's Hallway/Storage Area	Paint associated with Ceiling, Concrete		
Mechanical Room	Paint associated with Wall, CMU		
Electrical Room in Storage Room across from Main Office	Paint associated with Ceiling, Concrete		
Electrical Room in Storage Room across from Main Office	Paint associated with Wall, CMU		
Classroom 109	Paint associated with Wall, CMU		
Classroom 109	Paint associated with Ceiling, Concrete		
Classroom 106	Paint associated with Ceiling, Concrete		
Cafetorium	Paint associated with Ceiling, Concrete		
Stage	Paint associated with Ceiling, Concrete		
Stage	Paint associated with Wall, CMU		
Cafetorium Fan Room	Paint associated with Wall, CMU		
Kitchen Office	Paint associated with Wall, CMU		
Kitchen Storage	Paint associated with Wall, CMU		
Kitchen Staff Locker Restroom	Paint associated with Wall, CMU		
Kitchen Food Storage	Paint associated with Wall, CMU		
Gymnasium	Paint associated with Wall, CMU		
Gym Storage	Paint associated with Wall, CMU		
Coach's Office	Paint associated with Ceiling, Concrete		
Coach's Office	Paint associated with Wall, CMU		
Coach's Restroom	Paint associated with Ceiling, Concrete		
Coach's Restroom	Paint associated with Wall, CMU		
Girl's Locker Room (inactive)	Paint associated with Wall, CMU		
Girl's Locker Room (inactive)	Paint associated with Ceiling, Concrete		
Boy's Locker Room	Paint associated with Wall, CMU		
Boy's Locker Room	Paint associated with Ceiling, Concrete		
Closet adjacent to Gymnasium	Paint associated with Wall, CMU		
Teacher's Lunch Room	Paint associated with Wall, CMU		
Teacher's Lunch Room	Paint associated with Ceiling, Concrete		
Hallway from Cafetorium to Gymnasium	Paint associated with Ceiling, Concrete		
Hallway from Cafetorium to Gymnasium	Paint associated with Wall, CMU		
Hallway from Classrooms 101 to 113	Paint associated with Ceiling, Concrete		

# Henry W. Lawton School: Asbestos Hazard Report

Hallway between Main Office and Classroom 109	Paint associated with Ceiling, Concrete		
Hallway between Main Office and Classroom 109	Paint associated with Wall, CMU		
Small Hallway adjacent Cafetorium	Paint associated with Ceiling, Concrete		
Small Hallway adjacent Cafetorium	Paint associated with Wall, CMU		
Hallway from Offices 103 to 105	Paint associated with Ceiling, Concrete		
Hallway from Offices 103 to 105	Paint associated with Wall, CMU		
Stairwell C adjacent to Classroom 106	Paint associated with Wall, CMU		
Stairwell adjacent to Classroom 109	Paint associated with Wall, CMU		
Stairwell A adjacent to Classroom 101	Paint associated with Wall, CMU		
Classroom 201	Paint associated with Ceiling, Concrete		
Classroom 201	Paint associated with Wall, CMU		
Classroom 202	Paint associated with Wall, CMU		
Classroom 202	Paint associated with Ceiling, Concrete		
Classroom 203	Paint associated with Wall, CMU		
Classroom 203	Paint associated with Ceiling, Concrete		
Classroom 204	Paint associated with Ceiling, Concrete		
Classroom 205	Paint associated with Wall, CMU		
Classroom 205	Paint associated with Ceiling, Concrete		
Classroom 206	Paint associated with Wall, CMU	Damaged. Previously reported damaged in Feb 2025 and Jul 2024.	Encapsulation scheduled for Aug-Nov 2025. Previously encapsulated Apr 2025 and Feb 2025.
Classroom 206	Paint associated with Ceiling, Concrete		
Science Lab	Paint associated with Wall, CMU		
Classroom 208	Paint associated with Wall, CMU		
Classroom 208	Paint associated with Ceiling, Concrete		
Closet 210	Paint associated with Wall, CMU		
Closet 210	Paint associated with Ceiling, Concrete		
Electrical Room	Paint associated with Wall, CMU		
Electrical Room	Paint associated with Ceiling, Concrete		
Art Lab	Paint associated with Wall, CMU		
Girl's Restroom	Paint associated with Wall, CMU		
Girl's Restroom	Paint associated with Ceiling, Concrete		
Staff Restroom adjacent to Girl's Restroom	Paint associated with Ceiling, Concrete		

# Henry W. Lawton School: Asbestos Hazard Report

Office 212	Paint associated with Ceiling, Concrete		
Office 212	Paint associated with Wall, CMU		
IMC (Library)	Paint associated with Wall, CMU		
IMC (Library)	Paint associated with Ceiling, Concrete		
IMC (Library) Office	Paint associated with Wall, CMU	Damaged.	Encapsulation scheduled for Aug-Nov 2025.
Classroom 214	Paint associated with Ceiling, Concrete		
Classroom 216	Paint associated with Ceiling, Concrete		
Boy's Restroom	Paint associated with Wall, CMU		
Boy's Restroom	Paint associated with Ceiling, Concrete		
Staff Restroom adjacent to Boy's Restroom	Paint associated with Wall, CMU		
Staff Restroom adjacent to Boy's Restroom	Paint associated with Ceiling, Concrete		
Hallway from IMC to Classroom 216	Paint associated with Wall, CMU		
Hallway from IMC to Classroom 216	Paint associated with Ceiling, Concrete		
Hallway from Classrooms 201 to 215	Paint associated with Wall, CMU		
Hallway from Classrooms 201 to 215	Paint associated with Ceiling, Concrete		
Stairwell C adjacent to Classroom 216	Paint associated with Wall, CMU		
Stairwell C adjacent to Classroom 216	Paint associated with Ceiling, Concrete		
Stairwell B adjacent to Computer Lab	Paint associated with Wall, CMU		
Stairwell B adjacent to Computer Lab	Paint associated with Ceiling, Concrete		
Stairwell A adjacent to Classroom 201	Paint associated with Wall, CMU		
Stairwell A adjacent to Classroom 201	Paint associated with Ceiling, Concrete		

Table 2: Non-Friable Asbestos Containing Materials Identified

NOTE: Significantly Damaged non-friable materials (damage  $\geq$  10% of the material) can release harmful asbestos fibers into the air.

Location	Material Name	Reported as Damaged or Significantly Damaged? (Blank = No)	Abatement scheduled since the inspection? (Blank = No)
Classroom 101	Mastic associated with Floor Tile		

# Henry W. Lawton School: Asbestos Hazard Report

Classroom 101	Expansion Seam Caulking		
Classroom 101	Floor Tile VAT 12" x 12"		
Classroom 101 Restroom	Expansion Seam Caulking		
Classroom 101 Closet	Mastic associated with Floor Tile		
Classroom 101 Closet	Expansion Seam Caulking		
Classroom 101 Closet	Floor Tile VAT 12" x 12"		
Classroom 101 Closet	Mastic associated with Floor Tile		
Classroom 101 Closet	Expansion Seam Caulking		
Classroom 101 Closet	Floor Tile VAT 12" x 12"		
Classroom 102	Mastic associated with Floor Tile		
Classroom 102	Floor Tile VAT 12" x 12"		
Classroom 102	Expansion Seam Caulking		
Classroom 102 Restroom	Expansion Seam Caulking		
Classroom 102 Closet Closer To Hall	Mastic associated with Floor Tile		
Classroom 102 Closet Closer To Hall	Floor Tile VAT 12" x 12"		
Classroom 102 Closet Closer To Hall	Expansion Seam Caulking		
Classroom 102 Closet Closest To Playground Exit	Mastic associated with Floor Tile		
Classroom 102 Closet Closest To Playground Exit	Floor Tile VAT 12" x 12"		
Classroom 102 Closet Closest To Playground Exit	Expansion Seam Caulking		
Nurse's Suite Waiting Area	Mastic associated with Floor Tile		
Nurse's Suite Waiting Area	Expansion Seam Caulking		
Nurse's Suite Waiting Area	Floor Tile VAT 12" x 12"		
Nurse's Suite Office	Mastic associated with Floor Tile		
Nurse's Suite Office	Expansion Seam Caulking		
Nurse's Suite Office	Floor Tile VAT 12" x 12"		
Nurse's Suite Treatment Room	Mastic associated with Floor Tile		
Nurse's Suite Treatment Room	Expansion Seam Caulking		
Nurse's Suite Treatment Room	Floor Tile VAT 12" x 12"		
Nurse's Suite Closet	Mastic associated with Floor Tile		
Nurse's Suite Closet	Floor Tile VAT 12" x 12"		
Nurse's Suite Closet	Expansion Seam Caulking		
Nurse's Suite Restroom	Expansion Seam Caulking		
Classroom 104	Mastic associated with Floor Tile		
Classroom 104	Floor Tile VAT 12" x 12"		
Classroom 104	Expansion Seam Caulking		
Classroom 104	Sink Undercoat Mastic		
Classroom 104 Restroom	Expansion Seam Caulking		
Classroom 104 Closet	Mastic associated with Floor Tile		
Classroom 104 Closet	Floor Tile VAT 12" x 12"		
Classroom 104 Closet	Expansion Seam Caulking		

# Henry W. Lawton School: Asbestos Hazard Report

Main Office	Mastic associated with Floor Tile		
Main Office	Floor Tile VAT 12" x 12"		
Main Office	Expansion Seam Caulking		
Principal's Office	Mastic associated with Floor Tile		
Principal's Office	Expansion Seam Caulking		
Principal's Office	Floor Tile VAT 12" x 12"		
School Counselor Office	Expansion Seam Caulking		
Main Office Kitchenette	Mastic associated with Floor Tile		
Main Office Kitchenette	Expansion Seam Caulking		
Main Office Kitchenette	Sink Undercoat Mastic		
Main Office Kitchenette	Floor Tile VAT 12" x 12"		
Main Office Server Room	Expansion Seam Caulking		
Main Office Server Room	Floor Tile VAT 12" x 12"		
Principal's Closet	Mastic associated with Floor Tile		
Principal's Closet	Expansion Seam Caulking		
Principal's Closet	Floor Tile VAT 12" x 12"		
Principal's Restroom	Expansion Seam Caulking		
Storage Room accross from Main Office	Mastic associated with Floor Tile		
Storage Room accross from Main Office	Expansion Seam Caulking		
Storage Room accross from Main Office	Floor Tile VAT 12" x 12"		
Elevator Machinery Room	Expansion Seam Caulking		
Custodial Room	Expansion Seam Caulking		
Classroom 103	Mastic associated with Floor Tile		
Classroom 103	Floor Tile VAT 12" x 12"		
Classroom 103	Expansion Seam Caulking		
Girl's Restroom	Expansion Seam Caulking		
Gender Neutral Restroom	Expansion Seam Caulking		
Classroom 105	Mastic associated with Floor Tile		
Classroom 105	Floor Tile VAT 12" x 12"		
Classroom 105	Expansion Seam Caulking		
Boy's Restroom	Expansion Seam Caulking		
Staff Restroom	Expansion Seam Caulking		
Classroom 107	Mastic associated with Floor Tile		
Classroom 107	Floor Tile VAT 12" x 12"		
Classroom 107	Expansion Seam Caulking		
Kitchen Staff Locker	Expansion Seam Caulking		
Building Engineer's Office	Mastic associated with Floor Tile		
Building Engineer's Office	Floor Tile VAT 12" x 12"		
Building Engineer's Office	Expansion Seam Caulking		
Staff Locker Room	Floor Tile VAT 12" x 12"		
Staff Locker Room	Mastic associated with Floor Tile		
Staff Locker Room	Expansion Seam Caulking		
Building Engineer's Restroom	Expansion Seam Caulking		

# Henry W. Lawton School: Asbestos Hazard Report

Staff Restroom	Expansion Seam Caulking		
Building Engineer's Hallway/Storage Area	Expansion Seam Caulking		
Mechanical Room	Expansion Seam Caulking		
Electrical Room in Storage Room across from Main Office	Mastic associated with Floor Tile		
Electrical Room in Storage Room across from Main Office	Floor Tile VAT 12" x 12"		
Electrical Room in Storage Room across from Main Office	Expansion Seam Caulking		
Classroom 109	Mastic associated with Floor Tile		
Classroom 109	Floor Tile VAT 12" x 12"		
Classroom 109	Expansion Seam Caulking		
Classroom 106	Mastic associated with Floor Tile		
Classroom 106	Transite associated with Tabletop		
Classroom 106	Transite associated with Glassware Drying Rack		
Classroom 106	Expansion Seam Caulking		
Classroom 106	Floor Tile VAT 12" x 12"		
Cafetorium	Expansion Seam Caulking		
Stage	Mastic associated with Floor Tile		
Stage	Expansion Seam Caulking		
Stage	Floor Tile VAT 12" x 12"		
Cafetorium Fan Room	Expansion Seam Caulking		
Kitchen	Expansion Seam Caulking		
Kitchen Office	Mastic associated with Floor Tile		
Kitchen Office	Floor Tile VAT 12" x 12"		
Kitchen Storage	Mastic associated with Floor Tile		
Kitchen Storage	Floor Tile VAT 12" x 12"		
Kitchen Storage	Expansion Seam Caulking		
Kitchen Staff Locker Restroom	Expansion Seam Caulking		
Gymnasium	Expansion Seam Caulking		
Gymnasium	Mastic associated with Floor Tile		
Gymnasium	Floor Tile VAT 12" x 12"		
Gym Storage	Expansion Seam Caulking		
Coach's Office	Mastic associated with Floor Tile		
Coach's Office	Expansion Seam Caulking		
Coach's Office	Floor Tile VAT 12" x 12"		
Coach's Restroom	Expansion Seam Caulking		
Girl's Locker Room (inactive)	Expansion Seam Caulking		
Boy's Locker Room	Expansion Seam Caulking		
Closet adjacent to Gymnasium	Expansion Seam Caulking		
Teacher's Lunch Room	Mastic associated with Floor Tile		
Teacher's Lunch Room	Expansion Seam Caulking		
Teacher's Lunch Room	Floor Tile VAT 12" x 12"		

# Henry W. Lawton School: Asbestos Hazard Report

Hallway from Cafetorium to Gymnasium	Mastic associated with Floor Tile		
Hallway from Cafetorium to Gymnasium	Expansion Seam Caulking		
Hallway from Cafetorium to Gymnasium	Floor Tile VAT 12" x 12"		
Hallway from Classrooms 101 to 113	Mastic associated with Floor Tile		
Hallway from Classrooms 101 to 113	Expansion Seam Caulking		
Hallway from Classrooms 101 to 113	Floor Tile VAT 12" x 12"		
Hallway between Main Office and Classroom 109	Mastic associated with Floor Tile		
Hallway between Main Office and Classroom 109	Expansion Seam Caulking		
Hallway between Main Office and Classroom 109	Floor Tile VAT 12" x 12"		
Small Hallway adjacent Cafetorium	Mastic associated with Floor Tile		
Small Hallway adjacent Cafetorium	Expansion Seam Caulking		
Small Hallway adjacent Cafetorium	Floor Tile VAT 12" x 12"		
Hallway from Offices 103 to 105	Mastic associated with Floor Tile		
Hallway from Offices 103 to 105	Expansion Seam Caulking		
Hallway from Offices 103 to 105	Floor Tile VAT 12" x 12"		
Stairwell C adjacent to Classroom 106	Expansion Seam Caulking		
Stairwell adjacent to Classroom 109	Expansion Seam Caulking		
Stairwell A adjacent to Classroom 101	Expansion Seam Caulking		
Classroom 201	Glue Dots associated with Blackboard		
Classroom 201	Expansion Seam Caulking		
Classroom 201	Sink Undercoat Mastic		
Classroom 202	Expansion Seam Caulking		
Classroom 202	Sink Undercoat Mastic		
Classroom 203	Partition Room Dividers		
Classroom 203	Expansion Seam Caulking		
Classroom 203	Sink Undercoat Mastic		
Classroom 204	Mastic associated with Floor Tile		
Classroom 204	Expansion Seam Caulking		
Classroom 204	Sink Undercoat Mastic		

# Henry W. Lawton School: Asbestos Hazard Report

Classroom 204	Floor Tile VAT 12" x 12"		
Classroom 205	Mastic associated with Floor Tile		
Classroom 205	Glue Dots associated with Blackboard		
Classroom 205	Expansion Seam Caulking		
Classroom 205	Sink Undercoat Mastic		
Classroom 205	Floor Tile VAT 12" x 12"		
Classroom 206	Expansion Seam Caulking		
Classroom 206	Sink Undercoat Mastic		
Science Lab	Expansion Seam Caulking		
Classroom 208	Expansion Seam Caulking		
Classroom 208	Sink Undercoat Mastic		
Closet 210	Mastic associated with Floor Tile		
Closet 210	Expansion Seam Caulking		
Closet 210	Floor Tile VAT 12" x 12"		
Electrical Room	Expansion Seam Caulking		
Art Lab	Mastic associated with Floor Tile		
Art Lab	Expansion Seam Caulking		
Art Lab	Floor Tile VAT 12" x 12"		
Girl's Restroom	Expansion Seam Caulking		
Staff Restroom adjacent to Girl's Restroom	Expansion Seam Caulking		
Computer Lab	Expansion Seam Caulking		
Office 212	Mastic associated with Floor Tile		
Office 212	Expansion Seam Caulking		
IMC (Library)	Expansion Seam Caulking		
IMC (Library) Closet	Mastic associated with Floor Tile		
IMC (Library) Closet	Expansion Seam Caulking		
IMC (Library) Closet	Floor Tile VAT 12" x 12"		
IMC (Library) Office	Expansion Seam Caulking		
Classroom 214	Mastic associated with Floor Tile		
Classroom 214	Sink Undercoat Mastic		
Classroom 214	Glue Dots associated with Blackboard		
Classroom 214	Expansion Seam Caulking		
Classroom 214	Floor Tile VAT 12" x 12"		
Classroom 216	Mastic associated with Floor Tile		
Classroom 216	Glue Dots associated with Blackboard		
Classroom 216	Expansion Seam Caulking		
Classroom 216	Floor Tile VAT 12" x 12"		
Boy's Restroom	Expansion Seam Caulking		
Staff Restroom adjacent to Boy's Restroom	Expansion Seam Caulking		
Hallway from IMC to Classroom 216	Mastic associated with Floor Tile		
Hallway from IMC to Classroom 216	Expansion Seam Caulking		

# Henry W. Lawton School: Asbestos Hazard Report

Hallway from IMC to Classroom 216	Floor Tile VAT 12" x 12"		
Hallway from Classrooms 201 to 215	Mastic associated with Floor Tile		
Hallway from Classrooms 201 to 215	Expansion Seam Caulking		
Hallway from Classrooms 201 to 215	Floor Tile VAT 12" x 12"		
Stairwell C adjacent to Classroom 216	Expansion Seam Caulking		
Stairwell B adjacent to Computer Lab	Expansion Seam Caulking		
Stairwell A adjacent to Classroom 201	Expansion Seam Caulking		
Table Storage	Mastic associated with Floor Tile		
Table Storage	Floor Tile VAT 12" x 12"		
Boy's Restroom	Mastic associated with Floor Tile		
Boy's Restroom	Floor Tile VAT 12" x 12"		
Classroom 108	Mastic associated with Floor Tile		
Classroom 108	Floor Tile VAT 12" x 12"		
Classroom 110	Mastic associated with Floor Tile		
Classroom 110	Floor Tile VAT 12" x 12"		
Classroom 111	Floor Tile VAT 12" x 12"		
Classroom 112	Mastic associated with Floor Tile		
Classroom 112	Floor Tile VAT 12" x 12"		
Classroom 113	Mastic associated with Floor Tile		
Classroom 113	Floor Tile VAT 12" x 12"		
Classroom 114	Mastic associated with Floor Tile		
Classroom 114	Floor Tile VAT 12" x 12"		
Classroom 115	Floor Tile VAT 12" x 12"		
Classroom 117	Floor Tile VAT 12" x 12"		
Classroom 119	Floor Tile VAT 12" x 12"		
Classroom 121	Floor Tile VAT 12" x 12"		
Classroom 123	Mastic associated with Floor Tile		
Classroom 123	Floor Tile VAT 12" x 12"		
Hallway from Table Storage Room to Classroom 123	Mastic associated with Floor Tile		
Hallway from Table Storage Room to Classroom 123	Floor Tile VAT 12" x 12"		
Hallway from Classrooms 112 to 114	Mastic associated with Floor Tile		
Hallway from Classrooms 112 to 114	Floor Tile VAT 12" x 12"		
Technical Equipment(Currently psychologist office)	Mastic associated with Floor Tile		

Henry W. Lawton School:  
Asbestos Hazard Report

Technical Equipment(Currently psychologist office)	Floor Tile VAT 12" x 12"		
Boy's Restroom	Mastic associated with Floor Tile		
Boy's Restroom	Floor Tile VAT 12" x 12"		
Girl's Restroom	Mastic associated with Floor Tile		
Girl's Restroom	Floor Tile VAT 12" x 12"		
Classroom 209	Mastic associated with Floor Tile		
Classroom 209	Floor Tile VAT 12" x 12"		
Classroom 211	Mastic associated with Floor Tile		
Classroom 211	Floor Tile VAT 12" x 12"		
Classroom 213	Floor Tile VAT 12" x 12"		
Classroom 215	Floor Tile VAT 12" x 12"		
Classroom 217	Floor Tile VAT 12" x 12"		
Classroom 219	Mastic associated with Floor Tile		
Classroom 219	Floor Tile VAT 12" x 12"		
Classroom 222	Mastic associated with Floor Tile		
Classroom 222	Floor Tile VAT 12" x 12"		
Classroom 224	Floor Tile VAT 12" x 12"		
Classroom 226	Mastic associated with Floor Tile		
Classroom 226	Floor Tile VAT 12" x 12"		
Hallway from Technical Equipment Storage Room to Classroom 219	Mastic associated with Floor Tile		
Hallway from Technical Equipment Storage Room to Classroom 219	Floor Tile VAT 12" x 12"		
Hallway from Classrooms 222 to 226	Mastic associated with Floor Tile		
Hallway from Classrooms 222 to 226	Floor Tile VAT 12" x 12"		
Stairwell adjacent to Classroom 226	Mastic associated with Floor Tile		
Stairwell adjacent to Classroom 226	Floor Tile VAT 12" x 12"		