

# Rhawnhurst School: Asbestos Hazard Report

The Philadelphia Regional Center for Children's Environmental Health has partnered with the Healthy Schools Initiative to analyze and report on public information regarding asbestos conditions in schools made available on the School District of Philadelphia's website.

This report is meant to communicate to parents, teachers, and staff the exposure risk at their school and help prioritize the removal of asbestos in high-risk exposure locations.

Our analysis is based on publicly available reports. We have not conducted inspections or verified the reports.

## Key Findings:

- 67 teacher / student occupied spaces have asbestos containing material (ACM)
- 12 spaces had damaged ACM
- 29 spaces contained friable ACM
- **All damaged** materials were scheduled to be abated

## Our Recommendations:

- The School District scheduled the abatement for all 12 damaged ACM identified during their latest inspection in Sep 2025.
- The School District is required to regularly monitor the condition of their ACM by the EPA. We recommend the complete removal of friable ACM instead of encapsulation for materials that have been repeatedly damaged such as the sheetrock/joint compound found in Classroom A1 (301) and rear closet area (See Table 1).



A Program of:





## What is asbestos?

**Asbestos is a fibrous material that is resistant to heat, water, and corrosion.**

See this link for a comprehensive list: <https://prcceh.upenn.edu/asbestos>

## What are the health effects of asbestos?

No immediate health impacts are expected from asbestos exposure in schools. However, breathing asbestos fibers in schools may increase the risk of developing cancer many years from now.

Children are very active, breathing more air while running and playing. Children take more breaths per minute than adults and are lower to the ground where asbestos fibers may settle. This puts them at an increased risk for asbestos exposure.

## How are damaged asbestos containing materials managed?

Asbestos can be removed. Sometimes damaged materials are managed in place by patching, encapsulating (using a specially formulated paint-like coating) or building an enclosure around damaged and/or accessible materials. All of these are forms of abatement.

The Environmental Protection Agency requires all remaining asbestos containing material to be inspected by the school district every six months. This is documented in an Asbestos Hazard Emergency Response Act Report (AHERA Report).

## Asbestos was used in materials in schools, including:

- Ceiling Tiles
- Floor Tiles
- Pipe Insulation
- Cement
- Paint and Caulk
- Soundproofing
- Fireproofing
- Plaster Materials

## Are all asbestos containing materials of equal risk?

Some asbestos containing materials like ceiling and floor tiles have asbestos fibers imbedded in other materials. As long as they are not broken or damaged the asbestos fibers are not released into the air.

Some asbestos containing materials like insulation on pipe remains fibrous and can easily be released in the air when damaged.

### Important Terms

*Get to know these terms to make the most out of this report.*

**Damaged Asbestos Containing Material (ACM)** can release asbestos fibers into the air.

**Friable Materials** can be reduced to a powder by applying hand pressure. **DO NOT TOUCH!**

**Non-Friable materials** are not easily damaged.

**Significantly damaged materials** are more than 10% damaged.

**Abated ACM** means repaired, removed, or reduced risk of exposure.

## Detailed Review for Rhawnhurst School

This school has 71 spaces with asbestos containing materials. 67 of them are in teacher / student occupied spaces. The School District last inspected ACM in Sep 2025 and published the AHERA report in Oct 2025. Since then, the School District scheduled the abatement for all 12 damaged asbestos containing materials identified during this inspection. 11 of the damaged materials identified were non-friable, and 1 was friable ACM (see Tables 1 and 2).



We recommend that the School District completely remove friable ACM that has been repeatedly damaged in the past, such as the sheetrock/joint compound in Classroom A1 (301) and Rear Closet Area, as listed in Table 1. A list of all the ACM in the school and their damage/abatement schedule can be found in the tables at the end of this report. The Air Management Services website does not confirm the completion status of the abatement scheduled for 2025 and 2026 in response to the Sep 2025 AHERA report.

### Information Reviewed to Make this Report:

The 2025/26 AHERA report from the School District of Philadelphia, and asbestos abatement notifications from the Air Management Services Online Portal.

**Not included** in this report are planned repairs to damaged asbestos materials that have not been uploaded to the Air Management Services website or any updated after December 16, 2025. To see the most current information, scan these QR Codes. After scanning, search for your school.

#### School Districts of Philadelphia Asbestos Reports:



AHERA Reports are documents generated from EPA required asbestos inspections

#### Office of the Controller Asbestos Project:



Asbestos abatement notification forms



Report what you see!

Parents and teachers should report hazardous conditions in schools on the Healthy Schools app.

Scan here to download the app:



### Disclaimer:

This report analyzes custodial and mechanical spaces like boiler rooms **only** when ACM is significantly damaged (damage > 10%).

## Questions?

Find more resources on our website!

[prcch.upenn.edu/asbestos](http://prcch.upenn.edu/asbestos)

- Photo gallery of different types of damaged asbestos containing materials
- Guide to how we classify materials in schools
- Our analysis and reporting methodology
- What we do with the information in this report



Email us at [prcch@pennmedicine.upenn.edu](mailto:prcch@pennmedicine.upenn.edu) or call 215-573-9076

Table 1: Friable Asbestos Containing Materials Identified

NOTE: Friable materials can be reduced to a powder by applying hand pressure.

**Do not touch it!** Damaged and significantly damaged friable materials readily release harmful asbestos fibers into the air.

Location	Material Name	Reported as Damaged or Significantly Damaged? (Blank = No)	Abatement scheduled since the inspection? (Blank = No)
Classroom 102	Electrical Wire Wrap associated with Unit Ventilator		
Classroom 102	Pipe Insulation 2-6 inch		
Classroom 102	Pipe Fitting Insulation		
Classroom 101	Electrical Wire Wrap associated with Unit Ventilator		
Nurse's Office	Pipe Insulation 2-6 inch		
Nurse's Office	Pipe Fitting Insulation		
Counselor's Office next to Nurse's Office	Pipe Insulation 2-6 inch		
Counselor's Office next to Nurse's Office	Pipe Fitting Insulation		
Classroom 103	Electrical Wire Wrap associated with Unit Ventilator		
Classroom 103	Pipe Insulation 2-6 inch		
Classroom 103	Pipe Fitting Insulation		
Girl's Restroom across from Stairway 1	Pipe Insulation 2-6 inch		

# Rhawnhurst School: Asbestos Hazard Report

Girl's Restroom across from Stairway 1	Pipe Fitting Insulation		
Classroom 104	Electrical Wire Wrap associated with Unit Ventilator		
Classroom 105	Electrical Wire Wrap associated with Unit Ventilator		
Classroom 106	Electrical Wire Wrap associated with Unit Ventilator		
Classroom 108	Electrical Wire Wrap associated with Unit Ventilator		
Classroom 108	Pipe Insulation 2-6 inch		
Classroom 108	Pipe Fitting Insulation		
Classroom 109	Electrical Wire Wrap associated with Unit Ventilator		
Classroom 109	Pipe Insulation 2-6 inch		
Classroom 109	Pipe Fitting Insulation		
Stage	Pipe Insulation 2-6 inch		
Stage	Pipe Fitting Insulation		
Copy Room	Pipe Insulation 2-6 inch		
Copy Room	Pipe Fitting Insulation		
Storage Room in the Copy Room	Pipe Insulation 2-6 inch		
Storage Room in the Copy Room	Pipe Fitting Insulation		
Classroom 110	Electrical Wire Wrap associated with Unit Ventilator		
Hallway from Nurse's Office to Classroom 110	Electrical Wire Wrap associated with Electrical Panel		
Hallway from Lobby by Main Office to Classroom 105	Electrical Wire Wrap associated with Electrical Panel		
Gym Office	Pipe Insulation 2-6 inch		
Gym Office	Pipe Fitting Insulation		
Custodial Closet next to Boy's Restroom	Paint associated with Ductwork, Exterior		
Boiler Room	Tank Insulation	Damaged.	
Building Exterior	Caulk associated with Window, Exterior		
Building Exterior	Caulk associated with Louver		
Building Exterior	Caulk		
Building Exterior	Glazing associated with Unit Ventilator, Exterior		
Classroom A1 (301) and Rear Closet Area	Sheetrock/Joint Compound Wall	Damaged. Previously reported damaged in Oct 2022.	Encapsulation scheduled for Nov 2025-Feb 2026. Previously encapsulated in Jan 2024 and Jan 2023.

# Rhawnhurst School: Asbestos Hazard Report

Classroom A2 (302) and Rear Closet Area	Sheetrock/Joint Compound Wall		
Classroom A3 (303) and Rear Closet Area	Sheetrock/Joint Compound Wall		
Classroom A4 (304) and Rear Closet Area	Sheetrock/Joint Compound Wall		
Classroom A5 (305) and Rear Closet Area	Sheetrock/Joint Compound Wall		
Classroom A5 (305) and Rear Closet Area	Pipe Fitting Insulation		
Classroom A6 (306) and Rear Closet Area	Sheetrock/Joint Compound Wall		
Hallway between Gym and Element 2 (A1-A6)	Sheetrock/Joint Compound Wall		
Stairwell from Gym to Element 2 (A1-A6)	Sheetrock/Joint Compound Wall		
Outside Annex Building	Paint associated with Wall, Exterior		
Outside Annex Building	Glazing associated with Window, Exterior		

Table 2: Non-Friable Asbestos Containing Materials Identified

NOTE: Significantly Damaged non-friable materials (damage  $\geq$  10% of the material) can release harmful asbestos fibers into the air.

Location	Material Name	Reported as Damaged or Significantly Damaged? (Blank = No)	Abatement scheduled since the inspection? (Blank = No)
Classroom 100	Transite associated with Fuse Box		
Classroom 100	ACM Unit Ventilator		
Classroom 100	Mastic associated with Floor Tile		
Classroom 100 Coat Room	Mastic associated with Floor Tile		
Classroom 100 Coat Room	Floor Tile VAT 9" x 9"		
Classroom 100 Closet across from Girl's Restroom	Mastic associated with Floor Tile		
Classroom 100 Closet across from Girl's Restroom	Floor Tile VAT 9" x 9"		
Classroom 100 Closet across from Boy's Restroom	Mastic associated with Floor Tile		
Classroom 100 Closet across from Boy's Restroom	Floor Tile VAT 9" x 9"		
Classroom 100 Girl's Restroom	Thinset associated with Floor, Ceramic Tile		
Classroom 100 Boy's Restroom	Thinset associated with Floor, Ceramic Tile		

# Rhawnhurst School: Asbestos Hazard Report

Classroom 100 Closet on windows side	Glue Dots associated with Ceiling Tile 1' x 1'	Significantly damaged.	Encapsulation scheduled for Nov 2025-Feb 2026.
Classroom 100 Closet on Hallway side	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 102	Transite associated with Fuse Box		
Classroom 102	ACM Unit Ventilator		
Classroom 102	Mastic associated with Floor Tile		
Classroom 102	Heat Shield Insulation associated with Unit Ventilator		
Classroom 102	Glue Dots associated with Blackboard		
Classroom 102	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 102	Floor Tile VAT 9" x 9"		
Classroom 102 Closet	Mastic associated with Floor Tile		
Classroom 102 Closet	Floor Tile VAT 9" x 9"		
Classroom 102 Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 102 Closet next to Coat Area	Mastic associated with Floor Tile		
Classroom 102 Closet next to Coat Area	Floor Tile VAT 9" x 9"		
Classroom 102 Closet next to Coat Area	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 101	Transite associated with Fuse Box		
Classroom 101	ACM Unit Ventilator		
Classroom 101	Mastic associated with Floor Tile		
Classroom 101	Floor Tile VAT 12" x 12"		
Classroom 101	Floor Tile VAT 9" x 9"		
Classroom 101	Glue Dots associated with Ceiling Tile 1' x 1'		
Nurse's Office	Mastic associated with Floor Tile		
Nurse's Office	Floor Tile VAT 12" x 12"		
Nurse's Office	Floor Tile VAT 9" x 9"		
Counselor's Office next to Nurse's Office	Mastic associated with Floor Tile		
Counselor's Office next to Nurse's Office	Floor Tile VAT 9" x 9"		
Women's Restroom by Counselor's Office	Thinset associated with Floor, Ceramic Tile		
Women's Restroom by Counselor's Office	Thinset associated with Wall, Ceramic Tile		
Science Office	Mastic associated with Floor Tile		
Science Office	Floor Tile VAT 9" x 9"		
Counselor's Office	Mastic associated with Floor Tile		
Counselor's Office	Floor Tile VAT 12" x 12"		

# Rhawnhurst School: Asbestos Hazard Report

Counselor's Office	Floor Tile VAT 9" x 9"		
Counselor's Office	Glue Dots associated with Ceiling Tile 1' x 1'		
Counselor's Office Closet	Mastic associated with Floor Tile		
Counselor's Office Closet	Floor Tile VAT 9" x 9"		
Counselor's Office Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 101 Restrooms	Thinset associated with Floor, Ceramic Tile		
Hallway from Science Office to Counselor's Office	Mastic associated with Floor Tile		
Hallway from Science Office to Counselor's Office	Floor Tile VAT 9" x 9"		
Lobby area to Nurse's Office	Mastic associated with Floor Tile		
Lobby area to Nurse's Office	Floor Tile VAT 12" x 12"		
Lobby area to Nurse's Office	Floor Tile VAT 9" x 9"		
Classroom 101 Closet	Mastic associated with Floor Tile		
Classroom 101 Closet	Floor Tile VAT 9" x 9"		
Classroom 101 Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Closet in Lobby Area of Nurse's Office	Mastic associated with Floor Tile		
Closet in Lobby Area of Nurse's Office	Floor Tile VAT 9" x 9"		
Classroom 101 Closet next to Coat Area	Mastic associated with Floor Tile		
Classroom 101 Closet next to Coat Area	Floor Tile VAT 9" x 9"		
Classroom 101 Closet next to Coat Area	Glue Dots associated with Ceiling Tile 1' x 1'	Significantly damaged.	Encapsulation scheduled for Nov 2025-Feb 2026.
Staff Restroom next to Counselor's Office	Thinset associated with Wall, Ceramic Tile		
Classroom 102 Restrooms	Thinset associated with Floor, Ceramic Tile		
Classroom 103	Transite associated with Fuse Box		
Classroom 103	ACM Unit Ventilator		
Classroom 103	Mastic associated with Floor Tile		
Classroom 103	Floor Tile VAT 12" x 12"		
Classroom 103	Floor Tile VAT 9" x 9"		
Classroom 103	Glue Dots associated with Ceiling Tile 1' x 1'		
Main Office	Glue Dots associated with Blackboard		
Main Office	Glue Dots associated with Ceiling Tile 1' x 1'		
Principal's Conference Room	Mastic associated with Floor Tile		
Principal's Conference Room	Glue Dots associated with Ceiling Tile 1' x 1'	Damaged.	Encapsulation scheduled for Nov 2025-Feb 2026.

# Rhawnhurst School: Asbestos Hazard Report

Principal's Conference Room	Floor Tile VAT 12" x 12"		
Principal's Conference Room Closet	Mastic associated with Floor Tile		
Principal's Conference Room Closet	Floor Tile VAT 9" x 9"		
Principal's Conference Room Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Closet next to Principal's Conference Room	Floor Tile VAT 12" x 12"		
Closet next to Principal's Conference Room	Mastic associated with Floor Tile		
Closet next to Principal's Conference Room	Glue Dots associated with Ceiling Tile 1' x 1'		
Closet furthest from Principal's Conference Room	Mastic associated with Floor Tile		
Closet furthest from Principal's Conference Room	Floor Tile VAT 9" x 9"		
Closet furthest from Principal's Conference Room	Glue Dots associated with Ceiling Tile 1' x 1'	Significantly damaged.	Encapsulation scheduled for Nov 2025-Feb 2026.
Principal's Office	Mastic associated with Floor Tile		
Principal's Office	Glue Dots associated with Ceiling Tile 1' x 1'	Damaged.	Encapsulation scheduled for Nov 2025-Feb 2026.
Principal's Office	Floor Tile VAT 12" x 12"		
Principal's Office - Closet	Mastic associated with Floor Tile		
Principal's Office - Closet	Floor Tile VAT 9" x 9"		
Classroom 103 Closet	Mastic associated with Floor Tile		
Classroom 103 Closet	Floor Tile VAT 9" x 9"		
Classroom 103 Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Hallway between Main Office and Principal's Office	Mastic associated with Floor Tile		
Hallway between Main Office and Principal's Office	Floor Tile VAT 12" x 12"		
Hallway between Main Office and Principal's Office	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 103 Closet next to Coat Area	Mastic associated with Floor Tile		
Classroom 103 Closet next to Coat Area	Floor Tile VAT 9" x 9"		
Classroom 103 Closet next to Coat Area	Glue Dots associated with Ceiling Tile 1' x 1'		
Principal's Hallway	Glue Dots associated with Ceiling Tile 1' x 1'	Significantly damaged.	Encapsulation scheduled for Nov 2025-Feb 2026.
Principal's Hallway	Mastic associated with Floor Tile		

# Rhawnhurst School: Asbestos Hazard Report

Principal's Hallway	Floor Tile VAT 12" x 12"		
Main Office Restroom	Thinset associated with Floor, Ceramic Tile		
Main Office Restroom	Thinset associated with Wall, Ceramic Tile		
Classroom 104	Transite associated with Fuse Box		
Classroom 104	ACM Unit Ventilator		
Classroom 104	Mastic associated with Floor Tile		
Classroom 104	Floor Tile VAT 12" x 12"		
Classroom 104	Floor Tile VAT 9" x 9"		
Classroom 104	Glue Dots associated with Ceiling Tile 1' x 1'	Significantly damaged.	Encapsulation scheduled for Nov 2025-Feb 2026.
Classroom 104 Closet	Mastic associated with Floor Tile		
Classroom 104 Closet	Floor Tile VAT 9" x 9"		
Classroom 104 Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 104 Closet next to Coat Area	Mastic associated with Floor Tile		
Classroom 104 Closet next to Coat Area	Floor Tile VAT 9" x 9"		
Classroom 104 Closet next to Coat Area	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 105	ACM Unit Ventilator		
Classroom 105	Mastic associated with Floor Tile		
Classroom 105	Floor Tile VAT 9" x 9"		
Classroom 105	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 105 Closet next to Sink Alcove	Mastic associated with Floor Tile		
Classroom 105 Closet next to Sink Alcove	Floor Tile VAT 9" x 9"		
Classroom 105 Closet next to Sink Alcove	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 105 Closet next to Door	Mastic associated with Floor Tile		
Classroom 105 Closet next to Door	Floor Tile VAT 9" x 9"		
Classroom 105 Closet next to Door	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 106	ACM Unit Ventilator		
Classroom 106	Mastic associated with Floor Tile		
Classroom 106	Floor Tile VAT 12" x 12"		
Classroom 106	Floor Tile VAT 9" x 9"		
Classroom 106 Closet	Mastic associated with Floor Tile		
Classroom 106 Closet	Floor Tile VAT 9" x 9"		
Classroom 106 Closet	Glue Dots associated with Ceiling Tile 1' x 1'		

# Rhawnhurst School: Asbestos Hazard Report

Classroom 106 Closet next to Coat Area	Mastic associated with Floor Tile		
Classroom 106 Closet next to Coat Area	Floor Tile VAT 9" x 9"		
Classroom 106 Closet next to Coat Area	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 107	Transite associated with Fuse Box		
Classroom 107	ACM Unit Ventilator		
Classroom 107	Mastic associated with Floor Tile		
Classroom 107	Floor Tile VAT 12" x 12"		
Classroom 107	Floor Tile VAT 9" x 9"		
Classroom 107	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 107 Closet	Mastic associated with Floor Tile		
Classroom 107 Closet	Floor Tile VAT 9" x 9"		
Classroom 107 Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 107 Closet next to Coat Area	Mastic associated with Floor Tile		
Classroom 107 Closet next to Coat Area	Floor Tile VAT 9" x 9"		
Classroom 107 Closet next to Coat Area	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 108	Transite associated with Fuse Box		
Classroom 108	ACM Unit Ventilator		
Classroom 108	Mastic associated with Floor Tile		
Classroom 108	Gasket associated with Unit Ventilator		
Classroom 108	Floor Tile VAT 9" x 9"		
Classroom 108	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 108 Closet	Mastic associated with Floor Tile		
Classroom 108 Closet	Floor Tile VAT 9" x 9"		
Classroom 108 Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 108 Closet next to Coat Area	Mastic associated with Floor Tile		
Classroom 108 Closet next to Coat Area	Floor Tile VAT 9" x 9"		
Classroom 108 Closet next to Coat Area	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 109	Transite associated with Fuse Box		
Classroom 109	ACM Unit Ventilator		
Classroom 109	Mastic associated with Floor Tile		
Classroom 109	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 109	Floor Tile VAT 9" x 9"		

# Rhawnhurst School: Asbestos Hazard Report

Auditorium	Mastic associated with Floor Tile		
Auditorium	Floor Tile VAT 12" x 12"		
Auditorium	Floor Tile VAT 12" x 12"		
Classroom 109 Closet	Mastic associated with Floor Tile		
Classroom 109 Closet	Floor Tile VAT 9" x 9"		
Classroom 109 Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 109 Closet next to Coat Area	Mastic associated with Floor Tile		
Classroom 109 Closet next to Coat Area	Floor Tile VAT 9" x 9"		
Classroom 109 Closet next to Coat Area	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 109 Restroom	Thinset associated with Floor, Ceramic Tile		
Classroom 110	Transite associated with Fuse Box		
Classroom 110	ACM Unit Ventilator		
Classroom 110	Mastic associated with Floor Tile		
Classroom 110	Floor Tile VAT 12" x 12"		
Classroom 110	Floor Tile VAT 9" x 9"		
Classroom 110	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 110 Restroom	Thinset associated with Floor, Ceramic Tile		
Classroom 110 Closet	Mastic associated with Floor Tile		
Classroom 110 Closet	Floor Tile VAT 9" x 9"		
Classroom 110 Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 110 Closet next to Coat Area	Mastic associated with Floor Tile		
Classroom 110 Closet next to Coat Area	Floor Tile VAT 9" x 9"		
Classroom 110 Closet next to Coat Area	Glue Dots associated with Ceiling Tile 1' x 1'		
Cafeteria	Transite associated with Fuse Box		
Cafeteria	ACM Unit Ventilator		
Cafeteria	Glue Dots associated with Ceiling, Concrete		
Cafeteria	Heat Shield Insulation associated with Unit Ventilator		
Cafeteria	Mastic associated with Floor Tile		
Cafeteria	Floor Tile VAT 9" x 9"		
Kitchen Office	Mastic associated with Floor Tile		
Kitchen Office	Floor Tile VAT 9" x 9"		
Cafeteria Serving Area	Glue Dots associated with Ceiling, Concrete	Significantly damaged.	Encapsulation scheduled for Nov 2025-Feb 2026.

# Rhawnhurst School: Asbestos Hazard Report

Exit Vestibule off Kitchen Hallway and Gym/Cafeteria Lobby	Glue Dots associated with Ceiling Tile 1' x 1'	Significantly damaged.	Encapsulation scheduled for Nov 2025-Feb 2026.
Hallway between Classrooms 100 and 101	Mastic associated with Floor Tile		
Hallway between Classrooms 100 and 101	Floor Tile VAT 9" x 9"		
Hallway between Classrooms 100 and 101	Glue Dots associated with Ceiling Tile 1' x 1'		
Hallway from Nurse's Office to Classroom 110	Transite associated with Electrical Panel		
Hallway from Nurse's Office to Classroom 110	Mastic associated with Floor Tile		
Hallway from Nurse's Office to Classroom 110	Heat Shield Insulation associated with Radiator		
Hallway from Nurse's Office to Classroom 110	Floor Tile VAT 9" x 9"		
Hallway from Nurse's Office to Classroom 110	Glue Dots associated with Ceiling Tile 1' x 1'		
Hallway between Main Entrance and Auditorium	Mastic associated with Floor Tile		
Hallway between Main Entrance and Auditorium	Floor Tile VAT 9" x 9"		
Hallway between Main Entrance and Auditorium	Glue Dots associated with Ceiling Tile 1' x 1'		
Hallway from Lobby by Main Office to Classroom 105	Transite associated with Electrical Panel		
Hallway from Lobby by Main Office to Classroom 105	Mastic associated with Floor Tile		
Hallway from Lobby by Main Office to Classroom 105	Glue Dots associated with Blackboard		
Hallway from Lobby by Main Office to Classroom 105	Heat Shield Insulation associated with Radiator		
Hallway from Lobby by Main Office to Classroom 105	Floor Tile VAT 9" x 9"		
Hallway from Lobby by Main Office to Classroom 105	Glue Dots associated with Ceiling Tile 1' x 1'		
Hallway from next to Stair 1 to Gym/Cafeteria Lobby	Glue Dots associated with Ceiling Tile 1' x 1'	Damaged.	Encapsulation scheduled for Nov 2025-Feb 2026.
Hallway from next to Stair 1 to Gym/Cafeteria Lobby	Mastic associated with Floor Tile		
Hallway from next to Stair 1 to Gym/Cafeteria Lobby	Floor Tile VAT 12" x 12"		
Hallway from next to Stair 1 to Gym/Cafeteria Lobby	Heat Shield Insulation associated with Radiator		

# Rhawnhurst School: Asbestos Hazard Report

Hallway from next to Stair 1 to Gym/Cafeteria Lobby	Floor Tile VAT 9" x 9"		
Gym/Cafeteria Lobby	Mastic associated with Floor Tile		
Gym/Cafeteria Lobby	Glue Dots associated with Ceiling Tile 1' x 1'	Damaged.	Encapsulation scheduled for Nov 2025-Feb 2026.
Gym/Cafeteria Lobby	Floor Tile VAT 9" x 9"		
Stairwell 2 across from Classroom 102	Heat Shield Insulation associated with Radiator		
Exit Foyer between Classrooms 105 and 106	Glue Dots associated with Ceiling Tile 1' x 1'		
Exit Foyer between Classrooms 105 and 106	Heat Shield Insulation associated with Radiator		
Stairwell - Main Entrance to School	Thinset associated with Floor, Terrazzo		
Stairwell - Main Entrance to School	Heat Shield Insulation associated with Radiator		
Stairwell 1 adjacent to Classroom 108	Heat Shield Insulation associated with Radiator		
Exit Stairs next to Classroom 100	Heat Shield Insulation associated with Radiator		
Exit Stairs next to Classroom 100	Glue Dots associated with Ceiling Tile 1' x 1'		
Exit Stairs next to Classroom 110	Heat Shield Insulation associated with Radiator		
Exit Stairs next to Classroom 110	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 200	Transite associated with Fuse Box		
Classroom 200	Mastic associated with Floor Tile		
Classroom 200	Glue Dots associated with Blackboard		
Classroom 200	Floor Tile VAT 12" x 12"		
Classroom 200	Floor Tile VAT 9" x 9"		
Classroom 200	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 200 Closet	Mastic associated with Floor Tile		
Classroom 200 Closet	Floor Tile VAT 9" x 9"		
Classroom 200 Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 200 Closet next to Coat Area	Mastic associated with Floor Tile		
Classroom 200 Closet next to Coat Area	Floor Tile VAT 9" x 9"		
Classroom 200 Closet next to Coat Area	Glue Dots associated with Ceiling Tile 1' x 1'		
IMC/Library	Floor Tile VAT 9" x 9"		
IMC/Library	Transite associated with Fuse Box		

Rhawnhurst School:  
Asbestos Hazard Report

IMC/Library	Heat Shield Insulation associated with Unit Ventilator		
IMC/Library	ACM Unit Ventilator		
IMC/Library	Floor Tile VAT 12" x 12"		
IMC/Library	Glue Dots associated with Ceiling Tile 1' x 1'		
IMC/Library	Mastic associated with Floor Tile		
IMC/Library	Floor Tile VAT 12" x 12"		
Teacher Lounge/Dining	Mastic associated with Floor Tile		
Teacher Lounge/Dining	Floor Tile VAT 9" x 9"		
Teacher Lounge/Dining	Floor Tile VAT 12" x 12"		
Computer Server Room in 201A	Mastic associated with Floor Tile		
Computer Server Room in 201A	Floor Tile VAT 9" x 9"		
ESOL	Mastic associated with Floor Tile		
ESOL	Floor Tile VAT 12" x 12"		
ESOL	Floor Tile VAT 9" x 9"		
ESOL	Glue Dots associated with Ceiling Tile 1' x 1'		
Staff Restroom next to ESOL Room	Thinset associated with Floor, Ceramic Tile		
Staff Restroom next to ESOL Room	Thinset associated with Wall, Ceramic Tile		
ESOL Closet	Mastic associated with Floor Tile		
ESOL Closet	Floor Tile VAT 9" x 9"		
ESOL Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 202	Transite associated with Fuse Box		
Classroom 202	Mastic associated with Floor Tile		
Classroom 202	Heat Shield Insulation associated with Unit Ventilator		
Classroom 202	Floor Tile VAT 12" x 12"		
Classroom 202	Floor Tile VAT 9" x 9"		
Classroom 202	Glue Dots associated with Ceiling Tile 1' x 1'		
Custodial Closet next to Boy's Restroom	Mastic associated with Floor Tile		
Custodial Closet next to Boy's Restroom	Floor Tile VAT 9" x 9"		
Classroom 202 Closet	Mastic associated with Floor Tile		
Classroom 202 Closet	Floor Tile VAT 9" x 9"		
Classroom 202 Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 202 Closet next to Coat Area	Mastic associated with Floor Tile		

# Rhawnhurst School: Asbestos Hazard Report

Classroom 202 Closet next to Coat Area	Floor Tile VAT 9" x 9"		
Classroom 202 Closet next to Coat Area	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 203	Transite associated with Fuse Box		
Classroom 203	Mastic associated with Floor Tile		
Classroom 203	Floor Tile VAT 12" x 12"		
Classroom 203	Floor Tile VAT 12" x 12"		
Classroom 203	Glue Dots associated with Ceiling Tile 1' x 1'		
Office next to Stair 2	Mastic associated with Floor Tile		
Office next to Stair 2	Floor Tile VAT 9" x 9"		
Classroom 203 Closet	Mastic associated with Floor Tile		
Classroom 203 Closet	Floor Tile VAT 12" x 12"		
Classroom 203 Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 203 Closet next to Coat Area	Mastic associated with Floor Tile		
Classroom 203 Closet next to Coat Area	Floor Tile VAT 12" x 12"		
Classroom 203 Closet next to Coat Area	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 204	Transite associated with Fuse Box		
Classroom 204	Mastic associated with Floor Tile		
Classroom 204	Floor Tile VAT 12" x 12"		
Classroom 204	Glue Dots associated with Blackboard		
Classroom 204	Floor Tile VAT 9" x 9"		
Classroom 204	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 204 Closet	Mastic associated with Floor Tile		
Classroom 204 Closet	Floor Tile VAT 9" x 9"		
Classroom 204 Closet	Glue Dots associated with Ceiling Tile 1' x 1'		
Classroom 204 Closet next to Coat Area	Mastic associated with Floor Tile		
Classroom 204 Closet next to Coat Area	Floor Tile VAT 9" x 9"		
Classroom 204 Closet next to Coat Area	Glue Dots associated with Ceiling Tile 1' x 1'		
Hallway from Classrooms 200 to 204	Mastic associated with Floor Tile		
Hallway from Classrooms 200 to 204	Glue Dots associated with Ceiling Tile 1' x 1'		
Hallway from Classrooms 200 to 204	Floor Tile VAT 12" x 12"		
Hallway from Classrooms 200 to 204	Floor Tile VAT 9" x 9"		

# Rhawnhurst School: Asbestos Hazard Report

Hallway to ESOL Room from Main Hallway	Mastic associated with Floor Tile		
Hallway to ESOL Room from Main Hallway	Floor Tile VAT 9" x 9"		
Hallway to ESOL Room from Main Hallway	Glue Dots associated with Ceiling Tile 1' x 1'		
Stairwell 2 adjacent to Classroom 204	Heat Shield Insulation associated with Radiator		
Stairwell 1 adjacent to Classroom 203	Heat Shield Insulation associated with Radiator		
Electrical Room next to Building Engineer's Office	Expansion Seam Caulking		
Building Engineer's Restroom	Thinset associated with Floor, Ceramic Tile		
Classroom A1 (301) and Rear Closet Area	Transite associated with Fuse Box		
Classroom A1 (301) and Rear Closet Area	Mastic associated with Floor Tile		
Classroom A1 (301) and Rear Closet Area	Floor Tile VAT 12" x 12"		
Classroom A2 (302) and Rear Closet Area	Transite associated with Fuse Box		
Classroom A2 (302) and Rear Closet Area	Mastic associated with Floor Tile		
Classroom A2 (302) and Rear Closet Area	Floor Tile VAT 12" x 12"		
Classroom A2 (302) and Rear Closet Area	Floor Tile VAT 9" x 9"		
Classroom A3 (303) and Rear Closet Area	Floor Tile VAT 12" x 12"		
Classroom A3 (303) and Rear Closet Area	Floor Tile VAT 12" x 12"		
Classroom A3 (303) and Rear Closet Area	Transite associated with Fuse Box		
Classroom A3 (303) and Rear Closet Area	Mastic associated with Floor Tile		
Classroom A3 (303) and Rear Closet Area	Floor Tile VAT 9" x 9"		
Classroom A4 (304) and Rear Closet Area	Transite associated with Fuse Box		
Classroom A4 (304) and Rear Closet Area	Mastic associated with Floor Tile		
Classroom A4 (304) and Rear Closet Area	Floor Tile VAT 12" x 12"		
Classroom A4 (304) and Rear Closet Area	Floor Tile VAT 12" x 12"		
Classroom A5 (305) and Rear Closet Area	Transite associated with Fuse Box		

# Rhawnhurst School: Asbestos Hazard Report

Classroom A5 (305) and Rear Closet Area	Mastic associated with Floor Tile		
Classroom A5 (305) and Rear Closet Area	Floor Tile VAT 12" x 12"		
Classroom A5 (305) and Rear Closet Area	Floor Tile VAT 9" x 9"		
Classroom A6 (306) and Rear Closet Area	Transite associated with Fuse Box		
Classroom A6 (306) and Rear Closet Area	Mastic associated with Floor Tile		
Classroom A6 (306) and Rear Closet Area	Floor Tile VAT 12" x 12"		
Classroom A6 (306) and Rear Closet Area	Floor Tile VAT 12" x 12"		
Classroom A6 (306) and Rear Closet Area	Floor Tile VAT 9" x 9"		
Classroom A6 (306) and Rear Closet Area	Floor Tile VAT 9" x 9"		
Hallway from Classrooms A1 to A4	Transite associated with Fuse Box		
Hallway from Classrooms A1 to A4	Mastic associated with Floor Tile		
Hallway from Classrooms A1 to A4	Floor Tile VAT 12" x 12"		
Hallway from Classrooms A1 to A4	ACM Unit Ventilator		
Hallway from Classrooms A1 to A4	Floor Tile VAT 9" x 9"		
Hallway between Gym and Element 2 (A1-A6)	Transite associated with Fuse Box		
Hallway between Gym and Element 2 (A1-A6)	ACM Unit Ventilator		
Hallway between Gym and Element 2 (A1-A6)	Mastic associated with Floor Tile		
Hallway between Gym and Element 2 (A1-A6)	Floor Tile VAT 12" x 12"		
Stairwell from Gym to Element 2 (A1-A6)	Mastic associated with Floor Tile		
Stairwell from Gym to Element 2 (A1-A6)	Floor Tile VAT 12" x 12"		
Building Exterior	Mortar associated with Wall, Exterior		