

James Rhoads School: Asbestos Hazard Report

The Philadelphia Regional Center for Children's Environmental Health has partnered with the Healthy Schools Initiative to analyze and report on public information regarding asbestos conditions in schools made available on the School District of Philadelphia's website.

This report is meant to communicate to parents, teachers, and staff the exposure risk at their school and help prioritize the removal of asbestos in high-risk exposure locations.

Our analysis is based on publicly available reports. We have not conducted inspections or verified the reports.

Key Findings:

- 90 teacher / student occupied spaces have asbestos containing material (ACM)
- 22 spaces had damaged ACM
- 19 spaces contained friable ACM
- **20 of 22 damaged** materials were scheduled to be abated

Our Recommendations:

- The School District scheduled the abatement for twenty of the twenty-two damaged ACM identified during their latest inspection in May 2025. The School District did not abate significantly damaged friable ACM in the pipe chase in the girls' restroom next to classroom 100 (see Table 1). We recommend that this material be abated immediately.
- The School District is required to regularly monitor the condition of its ACM by the EPA. We recommend the complete removal of friable ACM instead of encapsulation for materials that have been repeatedly damaged, such as the pipe chase insulation in the girls' restroom (See Table 1).



A Program of:





What is asbestos?

Asbestos is a fibrous material that is resistant to heat, water, and corrosion.

See this link for a comprehensive list: <https://prcch.upenn.edu/asbestos>

Asbestos was used in materials in schools, including:

- Ceiling Tiles
- Floor Tiles
- Pipe Insulation
- Cement
- Paint and Caulk
- Soundproofing
- Fireproofing
- Plaster Materials

What are the health effects of asbestos?

No immediate health impacts are expected from asbestos exposure in schools. However, breathing asbestos fibers in schools may increase the risk of developing cancer many years from now.

Children are very active, breathing more air while running and playing. Children take more breaths per minute than adults and are lower to the ground where asbestos fibers may settle. This puts them at an increased risk for asbestos exposure.

Are all asbestos containing materials of equal risk?

Some asbestos containing materials like ceiling and floor tiles have asbestos fibers imbedded in other materials. As long as they are not broken or damaged the asbestos fibers are not released into the air.

Some asbestos containing materials like insulation on pipe remains fibrous and can easily be released in the air when damaged.

How are damaged asbestos containing materials managed?

Asbestos can be removed. Sometimes damaged materials are managed in place by patching, encapsulating (using a specially formulated paint-like coating) or building an enclosure around damaged and/or accessible materials. All of these are forms of abatement.

The Environmental Protection Agency requires all remaining asbestos containing material to be inspected by the school district every six months. This is documented in an Asbestos Hazard Emergency Response Act Report (AHERA Report).

Important Terms

Get to know these terms to make the most out of this report.

Damaged Asbestos Containing Material (ACM) can release asbestos fibers into the air.

Friable Materials can be reduced to a powder by applying hand pressure. **DO NOT TOUCH!**

Non-Friable materials are not easily damaged.

Significantly damaged materials are more than 10% damaged.

Abated ACM means repaired, removed, or reduced risk of exposure.

Detailed Review for James Rhoads School

This school has 104 spaces with asbestos-containing materials. 90 of them are in teacher / student-occupied spaces. The School District last inspected ACM in May 2025 and published the AHERA report in May 2025. Since then, the School District scheduled the abatement of 20 of the 22 damaged asbestos-containing materials identified during this inspection.



We recommend that the school district immediately abate the damaged friable asbestos-containing pipe insulation fittings found in the pipe chase in the girls' bathroom next to classroom 100 and schedule abatement for the low-risk asbestos-containing floor tile found in the library. We recommend that the School District completely remove friable ACM that have been repeatedly damaged in the past, such as the pipe chase insulation fittings, as listed in Table 1. Abatement of 20 materials was scheduled in 2025, however the website does not confirm that the abatement was completed. A list of all the ACM in the school and their damage/abatement schedule can be found in the tables at the end of this report.

Information Reviewed to Make this Report:

The 2024/25 AHERA report from the School District of Philadelphia, and asbestos abatement notifications from the Air Management Services Online Portal.

Not included in this report are planned repairs to damaged asbestos materials that have not been uploaded to the Air Management Services website or any updates after October 7, 2025. To see the most current information, scan these QR Codes. After scanning, search for your school.



Report what you see!

Parents and teachers should report hazardous conditions in schools on the Healthy Schools app.

Scan here to
download the app:



School Districts of Philadelphia Asbestos Reports:



AHERA Reports are documents generated from EPA required asbestos inspections

Office of the Controller Asbestos Project:



Asbestos abatement notification forms

Questions?

Find more resources on our website!

- Photo gallery of different types of damaged asbestos containing materials
- Guide to how we classify materials in schools
- Our analysis and reporting methodology
- What we do with the information in this report

prcceh.upenn.edu/asbestos



Email us at prcceh@penntestmed.upenn.edu or call 215-573-9076

Table 1: Friable Asbestos Containing Materials Identified

NOTE: Friable materials can be reduced to a powder by applying hand pressure.
Do not touch it! Damaged and significantly damaged friable materials readily release harmful asbestos fibers into the air.

Location	Material Name	Reported as Damaged or Significantly Damaged? (Blank = No)	Abatement scheduled since the inspection? (Blank = No)
Classroom 102 Restroom	Paint associated with Wall, CMU		
Main Office	Pipe Fitting Insulation		
Auditorium	Duct Insulation		
Kitchen Storage Area next to Boy's Restroom	Paint associated with Wall, CMU		
Gym/Cafeteria	Paint associated with Wall, CMU	Damaged. Previously reported damaged in Mar 2022. Previously reported damaged in May 2024.	Partial removal in Jun 2025. Previous partial removal in Feb 2025. Encapsulated in Nov 2024. Previous partial removal in Nov 2024. Previous partial removal in May 2022.
Hallway from the Auditorium to Classroom 100	Paint associated with Wall, CMU		
Pipe Chase in IMC	Pipe Fitting Insulation		
Pipe Chase in Gym (near Boy's Restroom)	Paint associated with Wall, CMU	Significantly damaged. Previously reported damaged in Nov 2024.	Partial removal in May 2025.
Pipe Chase in Girl's Restroom next to Classroom 100 (behind sinks on hallway side)	Paint associated with Wall, CMU	Significantly damaged. Previously reported damaged in Mar 2022.	Current damage is not scheduled for abatement. Previous

James Rhoads School: Asbestos Hazard Report

			partial removal in Apr 2022.
Pipe Chase in Girl's Restroom next to Classroom 100 (behind sinks on hallway side)	Pipe Fitting Insulation		
Classroom 209 Closet	Paint associated with Wall, CMU		
Hallway from Elevator to Classroom 210	Paint associated with Wall, CMU		
Women's Restroom across from Classroom 300	Paint associated with Wall, CMU		
Nurse's Office	Paint associated with Wall, CMU		
Stairwell B	Paint associated with Wall, CMU		
Classroom 404	Paint associated with Wall, CMU		
Women's Restroom across from Classroom 400	Paint associated with Wall, CMU		
Hallway from Classroom 400 to Classroom 401	Paint associated with Wall, CMU		
Pipe Chase in Men's Restroom across from Classroom 402	Paint associated with Wall, CMU		
High Voltage Room	Pipe Fitting Insulation		
High Voltage Room	Emergency Generator Insulation		
Crawl Space - Under Long Hallway	Duct Insulation		

Table 2: Non-Friable Asbestos Containing Materials Identified

NOTE: Significantly Damaged non-friable materials (damage \geq 10% of the material) can release harmful asbestos fibers into the air.

Location	Material Name	Reported as Damaged or Significantly Damaged? (Blank = No)	Abatement scheduled since the inspection? (Blank = No)
Classroom 100	Floor Tile VAT 12" x 12"		
Classroom 100	Mastic associated with Floor Tile		
Classroom 100	Glue Dots associated with Blackboard		
Classroom 100	Expansion Seam Caulking		
Classroom 100	Floor Tile VAT 12" x 12"		
Girl's Restroom next to Classroom 100	Transite associated with Door Transom		
Girl's Restroom next to Classroom 100	Expansion Seam Caulking		
Boy's Restroom between Girl's Restroom and Fan Room	Transite associated with Door Transom		
Boy's Restroom between Girl's Restroom and Fan Room	Expansion Seam Caulking	Damaged.	Encapsulation scheduled for Sept 2025.
Classroom 102 Kindergarten	Mastic associated with Floor Tile		
Classroom 102 Kindergarten	Floor Tile VAT 9" x 9"		
Classroom 102 Kindergarten	Transite associated with Window Sill		
Classroom 102 Kindergarten	Expansion Seam Caulking		
Classroom 102 Kindergarten	Floor Tile VAT 12" x 12"		
Classroom 102 Restroom	Expansion Seam Caulking		
Classroom 102 Supply Closet	Mastic associated with Floor Tile		
Classroom 102 Supply Closet	Expansion Seam Caulking		
Classroom 102 Supply Closet	Floor Tile VAT 12" x 12"		
Classroom 102 Coat Closet	Mastic associated with Floor Tile		
Classroom 102 Coat Closet	Floor Tile VAT 12" x 12"		

James Rhoads School: Asbestos Hazard Report

Classroom 102 Coat Closet	Expansion Seam Caulking		
IMC (Library)	Floor Tile VAT 9" x 9"		
IMC (Library)	Transite associated with Window Sill		
IMC (Library)	Floor Tile VAT 12" x 12"	Damaged.	
IMC (Library)	Expansion Seam Caulking		
IMC (Library)	Transite associated with Window Sill		
IMC (Library) Office	Mastic associated with Floor Tile		
IMC (Library) Office	Transite associated with Window Sill		
IMC (Library) Office	Transite associated with Window Sill		
IMC (Library) Office	Expansion Seam Caulking		
Classroom 104 Kindergarten	Mastic associated with Floor Tile		
Classroom 104 Kindergarten	Glue Dots associated with Blackboard		
Classroom 104 Kindergarten	Transite associated with Window Sill		
Classroom 104 Kindergarten	Expansion Seam Caulking		
Classroom 104 Kindergarten	Floor Tile VAT 12" x 12"		
Classroom 104 Restroom	Expansion Seam Caulking		
Teacher's Lounge across from the IMC (Library)	Floor Tile VAT 12" x 12"		
Teacher's Lounge across from the IMC (Library)	Mastic associated with Floor Tile		
Teacher's Lounge across from the IMC (Library)	Floor Tile VAT 12" x 12"		
Teacher's Lounge across from the IMC (Library)	Transite associated with Window Sill		
Teacher's Lounge across from the IMC (Library)	Expansion Seam Caulking		
Teacher's Lounge across from the IMC (Library)	Floor Tile VAT 9" x 9"		
Classroom 104 Supply Closet	Mastic associated with Floor Tile		
Classroom 104 Supply Closet	Expansion Seam Caulking		
Classroom 104 Supply Closet	Floor Tile VAT 12" x 12"		
Classroom 104 Coat Closet	Mastic associated with Floor Tile		
Classroom 104 Coat Closet	Floor Tile VAT 12" x 12"		
Classroom 104 Coat Closet	Expansion Seam Caulking		
Principal's Office attached to Main Office to the East	Floor Tile VAT 12" x 12"		
Principal's Office attached to Main Office to the East	Mastic associated with Floor Tile		
Principal's Office attached to Main Office to the East	Glue Dots associated with Ceiling Tile 1' x 1'		
Principal's Office attached to Main Office to the East	Transite associated with Window Sill		
Principal's Office attached to Main Office to the East	Expansion Seam Caulking		
Principal's Office attached to Main Office to the East	Floor Tile VAT 9" x 9"		
Principal's Office Restroom attached to Main Office	Mastic associated with Floor Tile		
Principal's Office Restroom attached to Main Office	Expansion Seam Caulking		
Principal's Office Restroom attached to Main Office	Floor Tile VAT 12" x 12"		
Principal's Office attached to Main Office to the East - Closet	Expansion Seam Caulking		
Principal's Office attached to Main Office to the East - Closet	Floor Tile VAT 9" x 9"		
Attendance Office	Mastic associated with Floor Tile		
Attendance Office	Glue Dots associated with Ceiling Tile 1' x 1'		

James Rhoads School: Asbestos Hazard Report

Attendance Office	Transite associated with Window Sill		
Attendance Office	Expansion Seam Caulking		
Attendance Office	Floor Tile VAT 9" x 9"		
Main Office	Mastic associated with Floor Tile		
Main Office	Floor Tile VAT 12" x 12"		
Main Office	Glue Dots associated with Blackboard		
Main Office	Transite associated with Window Sill		
Main Office	Glue Dots associated with Ceiling Tile 1' x 1'		
Main Office	Floor Tile VAT 9" x 9"		
Main Office	Expansion Seam Caulking		
Main Office Storage Closet	Mastic associated with Floor Tile		
Main Office Storage Closet	Expansion Seam Caulking	Significantly damaged.	Encapsulation scheduled for Sept 2025.
Main Office Storage Closet	Floor Tile VAT 9" x 9"		
Assistant Principal's Office	Mastic associated with Floor Tile		
Assistant Principal's Office	Glue Dots associated with Ceiling Tile 1' x 1'		
Assistant Principal's Office	Expansion Seam Caulking		
Assistant Principal's Office	Floor Tile VAT 12" x 12"		
Assistant Principal's Office Restroom	Mastic associated with Floor Tile		
Assistant Principal's Office Restroom	Floor Tile VAT 9" x 9"		
Assistant Principal's Office Restroom	Expansion Seam Caulking		
Nurse's Office Closet	Mastic associated with Floor Tile		
Nurse's Office Closet	Expansion Seam Caulking		
Nurse's Office Closet	Floor Tile VAT 9" x 9"		
Auditorium	Floor Tile VAT 12" x 12"		
Auditorium	Expansion Seam Caulking		
Stage	Floor Tile VAT 12" x 12"		
Stage	Mastic associated with Floor Tile		
Stage	Floor Tile VAT 9" x 9"		
Stage	Floor Tile VAT 12" x 12"		
Stage	Expansion Seam Caulking		
Auditorium Storage Room	Mastic associated with Floor Tile		
Auditorium Storage Room	Expansion Seam Caulking	Damaged.	Encapsulation scheduled for Sept 2025.
Auditorium Storage Room	Floor Tile VAT 12" x 12"		
Cafeteria Girl's Restroom	Expansion Seam Caulking		
Cafeteria Boy's Restroom	Expansion Seam Caulking		
Storage Closet in Hallway across from the Boy's and Girl's Restroom	Mastic associated with Floor Tile		
Storage Closet in Hallway across from the Boy's and Girl's Restroom	Transite associated with Door Transom		
Storage Closet in Hallway across from the Boy's and Girl's Restroom	Expansion Seam Caulking		
Storage Closet in Hallway across from the Boy's and Girl's Restroom	Floor Tile VAT 9" x 9"		
Custodial Closet in Hallway across from the Boy's Restroom	Transite associated with Door Transom		
Custodial Closet in Hallway across from the Boy's Restroom	Expansion Seam Caulking		
Kitchen/Kitchen Office	Mastic associated with Floor Tile		
Kitchen/Kitchen Office	Expansion Seam Caulking		
Kitchen/Kitchen Office	Floor Tile VAT 9" x 9"		
Kitchen Storage Area next to Boy's Restroom	Mastic associated with Floor Tile		

James Rhoads School: Asbestos Hazard Report

Kitchen Storage Area next to Boy's Restroom	Floor Tile VAT 12" x 12"		
Kitchen Storage Area next to Boy's Restroom	Expansion Seam Caulking		
Gym/Cafeteria	Expansion Seam Caulking		
Fan Room in Hallway next to Boy's Restroom	Transite associated with Door Transom		
Fan Room in Hallway next to Boy's Restroom	Expansion Seam Caulking		
Men's Restroom behind Elevator	Transite associated with Door Transom		
Men's Restroom behind Elevator	Expansion Seam Caulking		
Closet next to Main entrance Foyer	Expansion Seam Caulking		
School Police Office across from Classroom 100	Floor Tile VAT 12" x 12"		
School Police Office across from Classroom 100	Mastic associated with Floor Tile		
School Police Office across from Classroom 100	Transite associated with Door Transom		
School Police Office across from Classroom 100	Expansion Seam Caulking		
School Police Office across from Classroom 100	Floor Tile VAT 9" x 9"		
Gym Equipment Storage Room	Expansion Seam Caulking		
Women's Restroom next to the Auditorium	Transite associated with Door Transom		
Women's Restroom next to the Auditorium	Expansion Seam Caulking		
Hallway from the Auditorium to Classroom 100	Mastic associated with Floor Tile		
Hallway from the Auditorium to Classroom 100	Glue Dots associated with Ceiling Tile 1' x 1'		
Hallway from the Auditorium to Classroom 100	Expansion Seam Caulking		
Hallway from the Auditorium to Classroom 100	Floor Tile VAT 12" x 12"		
Hallway from the Auditorium to Classroom 100	Floor Tile VAT 12" x 12"		
Hallway from the Auditorium to Classroom 100	Floor Tile VAT 9" x 9"	Damaged.	Removal scheduled for Jun-Sep 2025.
Main Entrance Foyer	Glue Dots associated with Ceiling Tile 1' x 1'		
Main Entrance Foyer	Expansion Seam Caulking		
Hallway leading into the Cafeteria	Mastic associated with Floor Tile		
Hallway leading into the Cafeteria	Floor Tile VAT 9" x 9"		
Hallway leading into the Cafeteria	Expansion Seam Caulking		
Hallway leading into the Cafeteria	Floor Tile VAT 12" x 12"		
Hallway from the Auditorium to the IMC (Library)	Mastic associated with Floor Tile		
Hallway from the Auditorium to the IMC (Library)	Glue Dots associated with Blackboard		
Hallway from the Auditorium to the IMC (Library)	Expansion Seam Caulking		
Hallway from the Auditorium to the IMC (Library)	Floor Tile VAT 12" x 12"		
Hallway from the Auditorium to the IMC (Library)	Floor Tile VAT 9" x 9"	Damaged.	Removal scheduled for Jun-Sep 2025.
East Entrance Foyer by IMC (Library) and Teacher's Lounge	Floor Tile VAT 12" x 12"		

James Rhoads School: Asbestos Hazard Report

East Entrance Foyer by IMC (Library) and Teacher's Lounge	Mastic associated with Floor Tile		
East Entrance Foyer by IMC (Library) and Teacher's Lounge	Glue Dots associated with Ceiling Tile 1' x 1'		
East Entrance Foyer by IMC (Library) and Teacher's Lounge	Expansion Seam Caulking		
East Entrance Foyer by IMC (Library) and Teacher's Lounge	Floor Tile VAT 9" x 9"		
Hallway behind Stairwell A to School Yard	Expansion Seam Caulking		
Stairwell A - in Front of Classroom 100	Expansion Seam Caulking		
Stairwell C	Expansion Seam Caulking		
Stairwell B	Expansion Seam Caulking		
Classroom 200	Mastic associated with Floor Tile		
Classroom 200	Glue Dots associated with Blackboard		
Classroom 200	Transite associated with Closet		
Classroom 200	Transite associated with Window Sill		
Classroom 200	Floor Tile VAT 9" x 9"		
Classroom 200 Closet	Mastic associated with Floor Tile		
Classroom 200 Closet	Floor Tile VAT 12" x 12"		
Classroom 200 Coat Closet	Mastic associated with Floor Tile		
Classroom 200 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 201	Mastic associated with Floor Tile		
Classroom 201	Glue Dots associated with Blackboard		
Classroom 201	Transite associated with Closet		
Classroom 201	Transite associated with Window Sill		
Classroom 201	Floor Tile VAT 12" x 12"		
Classroom 201 Closet	Mastic associated with Floor Tile		
Classroom 201 Closet	Floor Tile VAT 12" x 12"		
Classroom 202	Mastic associated with Floor Tile		
Classroom 202	Glue Dots associated with Blackboard		
Classroom 202	Transite associated with Window Sill		
Classroom 202	Transite associated with Closet		
Classroom 202	Floor Tile VAT 12" x 12"		
Classroom 202 Closet	Mastic associated with Floor Tile		
Classroom 202 Closet	Floor Tile VAT 12" x 12"		
Classroom 202 Coat Closet	Mastic associated with Floor Tile		
Classroom 202 Coat Closet	Floor Tile VAT 12" x 12"		
Classroom 203	Glue Dots associated with Blackboard		
Classroom 203	Transite associated with Closet		
Classroom 203	Transite associated with Window Sill		
Classroom 203	Floor Tile VAT 12" x 12"		
Classroom 203 Closet	Mastic associated with Floor Tile		
Classroom 203 Closet	Floor Tile VAT 12" x 12"		
Classroom 203 Coat Closet	Mastic associated with Floor Tile		
Classroom 203 Coat Closet	Floor Tile VAT 12" x 12"		
Classroom 204	Mastic associated with Floor Tile		
Classroom 204	Transite associated with Closet		
Classroom 204	Transite associated with Window Sill		
Classroom 204	Floor Tile VAT 12" x 12"		
Classroom 204	Floor Tile VAT 12" x 12"		
Classroom 204	Floor Tile VAT 9" x 9"		
Classroom 204 Closet	Mastic associated with Floor Tile		
Classroom 204 Closet	Floor Tile VAT 12" x 12"		
Classroom 204 Closet	Floor Tile VAT 9" x 9"		
Classroom 204 Coat Closet	Mastic associated with Floor Tile		
Classroom 204 Coat Closet	Floor Tile VAT 12" x 12"		

James Rhoads School: Asbestos Hazard Report

Classroom 205	Mastic associated with Floor Tile		
Classroom 205	Glue Dots associated with Blackboard		
Classroom 205	Transite associated with Closet		
Classroom 205	Transite associated with Window Sill		
Classroom 205	Floor Tile VAT 12" x 12"		
Classroom 205 Closet	Mastic associated with Floor Tile		
Classroom 205 Closet	Floor Tile VAT 12" x 12"		
Classroom 205 Coat Closet	Mastic associated with Floor Tile		
Classroom 205 Coat Closet	Floor Tile VAT 12" x 12"		
Classroom 206	Mastic associated with Floor Tile		
Classroom 206	Glue Dots associated with Blackboard		
Classroom 206	Transite associated with Closet		
Classroom 206	Transite associated with Window Sill		
Classroom 206	Floor Tile VAT 12" x 12"		
Classroom 206	Floor Tile VAT 12" x 12"		
Classroom 206	Floor Tile VAT 9" x 9"		
Classroom 206 Closet	Mastic associated with Floor Tile		
Classroom 206 Closet	Floor Tile VAT 12" x 12"		
Classroom 206 Closet	Floor Tile VAT 9" x 9"		
Classroom 206 Coat Closet	Mastic associated with Floor Tile		
Classroom 206 Coat Closet	Floor Tile VAT 12" x 12"		
Classroom 206 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 207	Mastic associated with Floor Tile		
Classroom 207	Glue Dots associated with Blackboard		
Classroom 207	Transite associated with Closet		
Classroom 207	Transite associated with Window Sill		
Classroom 207	Floor Tile VAT 9" x 9"		
Classroom 207 Closet	Mastic associated with Floor Tile		
Classroom 207 Closet	Floor Tile VAT 9" x 9"		
Classroom 208	Mastic associated with Floor Tile		
Classroom 208	Glue Dots associated with Blackboard		
Classroom 208	Transite associated with Closet		
Classroom 208	Transite associated with Window Sill		
Classroom 208	Floor Tile VAT 12" x 12"		
Classroom 208 Closet	Mastic associated with Floor Tile		
Classroom 208 Closet	Floor Tile VAT 12" x 12"		
Classroom 208 Coat Closet	Mastic associated with Floor Tile		
Classroom 208 Coat Closet	Floor Tile VAT 12" x 12"		
Classroom 209	Floor Tile VAT 12" x 12"		
Classroom 209	Glue Dots associated with Blackboard		
Classroom 209	Transite associated with Closet		
Classroom 209	Transite associated with Window Sill		
Classroom 209	Mastic associated with Floor Tile		
Classroom 209 Closet	Mastic associated with Floor Tile		
Classroom 209 Closet	Floor Tile VAT 12" x 12"		
Classroom 209 Coat Closet	Mastic associated with Floor Tile		
Classroom 209 Coat Closet	Floor Tile VAT 12" x 12"		
Classroom 210	Glue Dots associated with Blackboard		
Classroom 210	Transite associated with Closet		
Classroom 210	Transite associated with Window Sill		
Classroom 210 Closet	Mastic associated with Floor Tile		
Classroom 210 Closet	Floor Tile VAT 12" x 12"		
Classroom 210 Coat Closet	Mastic associated with Floor Tile		
Classroom 210 Coat Closet	Floor Tile VAT 12" x 12"		
Room 200A across from Classroom 200	Mastic associated with Floor Tile		

James Rhoads School: Asbestos Hazard Report

Room 200A across from Classroom 200	Glue Dots associated with Blackboard		
Room 200A across from Classroom 200	Floor Tile VAT 12" x 12"		
Room 200A across from Classroom 200	Transite associated with Window Sill		
Room 200A across from Classroom 200	Transite associated with Door Transom		
Women's Restroom across from Classroom 202	Transite associated with Door Transom		
Custodial Closet across from Classroom 202	Transite associated with Door Transom		
Boy's Restroom across from Classroom 202	Transite associated with Door Transom		
Girl's Restroom across from Classroom 202	Transite associated with Door Transom		
Men's Restroom across from Classroom 202	Mastic associated with Floor Tile		
Men's Restroom across from Classroom 202	Transite associated with Door Transom		
Men's Restroom across from Classroom 202	Floor Tile VAT 12" x 12"		
Fan Room next to Classroom 202	Transite associated with Door Transom	Significantly damaged.	Encapsulation scheduled for Jun-Sep 2025.
Book Closet next to Fan Room next to Classroom 202	Mastic associated with Floor Tile		
Book Closet next to Fan Room next to Classroom 202	Transite associated with Door Transom		
Book Closet next to Fan Room next to Classroom 202	Floor Tile VAT 9" x 9"		
Hallway from Classroom 200 to Classroom 201	Mastic associated with Floor Tile		
Hallway from Classroom 200 to Classroom 201	Floor Tile VAT 12" x 12"		
Hallway from Classroom 200 to Classroom 201	Floor Tile VAT 9" x 9"	Damaged.	Removal scheduled for Jun-Sep 2025.
Hallway from Elevator to Classroom 210	Mastic associated with Floor Tile		
Hallway from Elevator to Classroom 210	Floor Tile VAT 12" x 12"		
Hallway from Elevator to Classroom 210	Floor Tile VAT 9" x 9"	Damaged.	Removal scheduled for Jun-Sep 2025.
Stairwell C	Transite associated with Window Sill		
Stairwell B	Transite associated with Window Sill		
Classroom 300	Mastic associated with Floor Tile		
Classroom 300	Floor Tile VAT 12" x 12"		
Classroom 300	Glue Dots associated with Blackboard		
Classroom 300	Transite associated with Window Sill		
Classroom 300	Transite associated with Closet		
Classroom 300	Floor Tile VAT 12" x 12"		
Classroom 300	Floor Tile VAT 9" x 9"		
Teachers Lounge 300A	Transite associated with Door Transom		
Teachers Lounge 300A	Transite associated with Window Sill		
Teachers Lounge 300A	Floor Tile VAT 9" x 9"	Damaged.	Removal scheduled for Jun-Sep 2025.
Classroom 300 Coat Closet	Mastic associated with Floor Tile		
Classroom 300 Coat Closet	Floor Tile VAT 9" x 9"		

James Rhoads School: Asbestos Hazard Report

Classroom 300 Closet	Mastic associated with Floor Tile		
Classroom 300 Closet	Floor Tile VAT 9" x 9"		
Classroom 301	Mastic associated with Floor Tile		
Classroom 301	Glue Dots associated with Blackboard		
Classroom 301	Transite associated with Window Sill		
Classroom 301	Transite associated with Closet		
Classroom 301	Floor Tile VAT 12" x 12"		
Classroom 301 Closet	Mastic associated with Floor Tile		
Classroom 301 Closet	Floor Tile VAT 12" x 12"		
Classroom 302	Mastic associated with Floor Tile		
Classroom 302	Glue Dots associated with Blackboard		
Classroom 302	Transite associated with Window Sill		
Classroom 302	Transite associated with Closet		
Classroom 302	Floor Tile VAT 9" x 9"		
Classroom 302	Floor Tile VAT 9" x 9"		
Classroom 302 Closet	Mastic associated with Floor Tile		
Classroom 302 Closet	Floor Tile VAT 9" x 9"		
Classroom 302 Coat Closet	Mastic associated with Floor Tile		
Classroom 302 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 303	Floor Tile VAT 12" x 12"		
Classroom 303	Mastic associated with Floor Tile		
Classroom 303	Glue Dots associated with Blackboard		
Classroom 303	Transite associated with Window Sill		
Classroom 303	Transite associated with Closet		
Classroom 303	Floor Tile VAT 12" x 12"		
Classroom 303	Floor Tile VAT 9" x 9"		
Classroom 303 Closet	Mastic associated with Floor Tile		
Classroom 303 Closet	Floor Tile VAT 9" x 9"		
Classroom 303 Coat Closet	Mastic associated with Floor Tile		
Classroom 303 Coat Closet	Floor Tile VAT 12" x 12"		
Classroom 303 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 304	Floor Tile VAT 12" x 12"		
Classroom 304	Mastic associated with Floor Tile		
Classroom 304	Glue Dots associated with Blackboard		
Classroom 304	Transite associated with Window Sill		
Classroom 304	Transite associated with Closet	Damaged.	Encapsulation scheduled for Jun-Sep 2025.
Classroom 304	Floor Tile VAT 9" x 9"	Damaged.	Removal scheduled for Jun-Sep 2025.
Classroom 304 Coat Closet	Mastic associated with Floor Tile		
Classroom 304 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 305	Mastic associated with Floor Tile		
Classroom 305	Glue Dots associated with Blackboard		
Classroom 305	Transite associated with Window Sill		
Classroom 305	Transite associated with Closet	Damaged.	Encapsulation scheduled for Jun-Sep 2025.
Classroom 305	Floor Tile VAT 9" x 9"		
Classroom 305 Closet	Mastic associated with Floor Tile		
Classroom 305 Closet	Floor Tile VAT 12" x 12"		
Classroom 305 Coat Closet	Mastic associated with Floor Tile		
Classroom 305 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 306	Glue Dots associated with Blackboard		
Classroom 306	Transite associated with Window Sill		
Classroom 306	Transite associated with Closet		
Classroom 306	Mastic associated with Floor Tile		

James Rhoads School: Asbestos Hazard Report

Classroom 306 Closet	Mastic associated with Floor Tile		
Classroom 306 Closet	Floor Tile VAT 12" x 12"		
Classroom 306 Coat Closet	Mastic associated with Floor Tile		
Classroom 306 Coat Closet	Floor Tile VAT 12" x 12"		
Classroom 307	Mastic associated with Floor Tile		
Classroom 307	Glue Dots associated with Blackboard		
Classroom 307	Transite associated with Window Sill		
Classroom 307	Transite associated with Closet		
Classroom 307	Floor Tile VAT 12" x 12"		
Classroom 307	Floor Tile VAT 9" x 9"		
Classroom 307 Closet	Mastic associated with Floor Tile		
Classroom 307 Closet	Floor Tile VAT 9" x 9"		
Classroom 307 Coat Closet	Mastic associated with Floor Tile		
Classroom 307 Coat Closet	Floor Tile VAT 12" x 12"		
Classroom 307 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 308	Glue Dots associated with Blackboard		
Classroom 308	Transite associated with Window Sill		
Classroom 308	Transite associated with Closet		
Classroom 308 Closet	Mastic associated with Floor Tile		
Classroom 308 Closet	Floor Tile VAT 12" x 12"		
Classroom 308 Coat Closet	Mastic associated with Floor Tile		
Classroom 309	Mastic associated with Floor Tile		
Classroom 309	Glue Dots associated with Blackboard		
Classroom 309	Transite associated with Window Sill		
Classroom 309	Transite associated with Closet		
Classroom 309	Floor Tile VAT 12" x 12"		
Classroom 309 Closet	Mastic associated with Floor Tile		
Classroom 309 Closet	Floor Tile VAT 12" x 12"		
Classroom 309 Coat Closet	Mastic associated with Floor Tile		
Classroom 309 Coat Closet	Floor Tile VAT 12" x 12"		
Classroom 310	Floor Tile VAT 12" x 12"		
Classroom 310	Glue Dots associated with Blackboard		
Classroom 310	Transite associated with Window Sill		
Classroom 310	Transite associated with Closet		
Classroom 310	Mastic associated with Floor Tile		
Classroom 310 Closet	Mastic associated with Floor Tile		
Classroom 310 Closet	Floor Tile VAT 12" x 12"		
Classroom 310 Coat Closet	Mastic associated with Floor Tile		
Classroom 310 Coat Closet	Floor Tile VAT 12" x 12"		
Women's Restroom across from Classroom 300	Transite associated with Door Transom		
Women's Restroom across from Classroom 300	Transite associated with Window Sill		
Custodial Closet across from Classroom 302	Transite associated with Door Transom		
Boy's Restroom across from Classroom 302	Transite associated with Door Transom		
Boy's Restroom across from Classroom 302	Transite associated with Window Sill		
Girl's Restroom across Classroom 302	Transite associated with Door Transom		
Girl's Restroom across Classroom 302	Transite associated with Window Sill		
Nurse's Office	Transite associated with Door Transom		
Nurse's Office	Partition Room Dividers		
Nurse's Office	Floor Tile VAT 12" x 12"		
Nurse's Office Restroom	Mastic associated with Floor Tile		
Nurse's Office Restroom	Floor Tile VAT 12" x 12"		
Fan Room near Classroom 302	Transite associated with Door Transom		

James Rhoads School: Asbestos Hazard Report

Book Closet across from the Nurse's Office	Mastic associated with Floor Tile		
Book Closet across from the Nurse's Office	Transite associated with Door Transom		
Book Closet across from the Nurse's Office	Floor Tile VAT 9" x 9"		
Hallway from Elevator to Classroom 310	Mastic associated with Floor Tile		
Hallway from Elevator to Classroom 310	Floor Tile VAT 12" x 12"		
Hallway from Elevator to Classroom 310	Floor Tile VAT 9" x 9"		
Hallway from Elevator to Classroom 310	Glue Dots associated with Ceiling Tile 1' x 1'		
Hallway from Classroom 301 to Classroom 300	Mastic associated with Floor Tile		
Hallway from Classroom 301 to Classroom 300	Glue Dots associated with Ceiling Tile 1' x 1'		
Hallway from Classroom 301 to Classroom 300	Floor Tile VAT 12" x 12"		
Hallway from Classroom 301 to Classroom 300	Floor Tile VAT 9" x 9"	Damaged.	Removal scheduled for Jun-Sep 2025.
Stairwell A	Transite associated with Window Sill		
Stairwell C	Transite associated with Window Sill		
Stairwell B	Transite associated with Window Sill		
Classroom 400	Mastic associated with Floor Tile		
Classroom 400	Glue Dots associated with Blackboard		
Classroom 400	Transite associated with Closet		
Classroom 400	Transite associated with Window Sill		
Classroom 400	Floor Tile VAT 9" x 9"		
Classroom 400	Floor Tile VAT 9" x 9"		
Room 400A across from Classroom 400	Mastic associated with Floor Tile		
Room 400A across from Classroom 400	Transite associated with Door Transom		
Room 400A across from Classroom 400	Transite associated with Window Sill		
Room 400A across from Classroom 400	Floor Tile VAT 12" x 12"		
Classroom 400 Coat Closet	Mastic associated with Floor Tile		
Classroom 400 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 400 Closet	Mastic associated with Floor Tile		
Classroom 400 Closet	Floor Tile VAT 9" x 9"		
Classroom 401	Mastic associated with Floor Tile		
Classroom 401	Glue Dots associated with Blackboard		
Classroom 401	Transite associated with Closet		
Classroom 401	Transite associated with Window Sill		
Classroom 401	Floor Tile VAT 12" x 12"		
Classroom 401	Floor Tile VAT 9" x 9"		
Classroom 401 Closet	Floor Tile VAT 12" x 12"		
Classroom 401 Closet	Mastic associated with Floor Tile		
Classroom 401 Coat Closet	Mastic associated with Floor Tile		
Classroom 401 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 402	Mastic associated with Floor Tile		
Classroom 402	Glue Dots associated with Blackboard		
Classroom 402	Transite associated with Closet		
Classroom 402	Transite associated with Window Sill		
Classroom 402	Floor Tile VAT 12" x 12"		

James Rhoads School: Asbestos Hazard Report

Classroom 402	Floor Tile VAT 9" x 9"		
Classroom 402 Closet	Mastic associated with Floor Tile		
Classroom 402 Closet	Floor Tile VAT 12" x 12"		
Classroom 402 Coat Closet	Mastic associated with Floor Tile		
Classroom 402 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 403	Mastic associated with Floor Tile		
Classroom 403	Glue Dots associated with Blackboard		
Classroom 403	Transite associated with Closet		
Classroom 403	Transite associated with Window Sill		
Classroom 403	Floor Tile VAT 9" x 9"		
Classroom 403 Closet	Mastic associated with Floor Tile		
Classroom 403 Closet	Floor Tile VAT 12" x 12"		
Classroom 403 Coat Closet	Mastic associated with Floor Tile		
Classroom 403 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 404	Mastic associated with Floor Tile		
Classroom 404	Glue Dots associated with Blackboard		
Classroom 404	Transite associated with Closet		
Classroom 404	Transite associated with Window Sill		
Classroom 404 Closet	Mastic associated with Floor Tile		
Classroom 404 Closet	Floor Tile VAT 12" x 12"		
Classroom 404 Coat Closet	Mastic associated with Floor Tile		
Classroom 404 Coat Closet	Floor Tile VAT 12" x 12"		
Classroom 405	Mastic associated with Floor Tile		
Classroom 405	Glue Dots associated with Blackboard		
Classroom 405	Transite associated with Closet		
Classroom 405	Floor Tile VAT 9" x 9"	Damaged.	Removal scheduled for Jun-Sep 2025.
Classroom 405 Closet	Mastic associated with Floor Tile		
Classroom 405 Closet	Floor Tile VAT 9" x 9"		
Classroom 405 Coat Closet	Mastic associated with Floor Tile		
Classroom 405 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 406	Mastic associated with Floor Tile		
Classroom 406	Glue Dots associated with Blackboard		
Classroom 406	Transite associated with Closet		
Classroom 406	Transite associated with Window Sill		
Classroom 406	Floor Tile VAT 9" x 9"		
Classroom 406 Closet	Mastic associated with Floor Tile		
Classroom 406 Closet	Floor Tile VAT 9" x 9"		
Classroom 406 Coat Closet	Mastic associated with Floor Tile		
Classroom 406 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 407	Glue Dots associated with Blackboard		
Classroom 407	Transite associated with Closet		
Classroom 407	Transite associated with Window Sill		
Classroom 407 Closet	Mastic associated with Floor Tile		
Classroom 407 Closet	Floor Tile VAT 12" x 12"		
Classroom 407 Closet	Floor Tile VAT 9" x 9"		
Classroom 407 Coat Closet	Mastic associated with Floor Tile		
Classroom 407 Coat Closet	Floor Tile VAT 12" x 12"		
Classroom 408	Mastic associated with Floor Tile		
Classroom 408	Glue Dots associated with Blackboard		
Classroom 408	Transite associated with Closet		
Classroom 408	Transite associated with Window Sill		
Classroom 408	Floor Tile VAT 12" x 12"		
Classroom 408	Floor Tile VAT 9" x 9"	Damaged.	Removal scheduled for Jun-Sep 2025.
Classroom 408 Closet	Mastic associated with Floor Tile		
Classroom 408 Closet	Floor Tile VAT 9" x 9"		

James Rhoads School: Asbestos Hazard Report

Classroom 408 Coat Closet	Mastic associated with Floor Tile		
Classroom 408 Coat Closet	Floor Tile VAT 12" x 12"		
Classroom 408 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 409	Mastic associated with Floor Tile		
Classroom 409	Floor Tile VAT 12" x 12"		
Classroom 409	Glue Dots associated with Blackboard		
Classroom 409	Transite associated with Closet		
Classroom 409	Transite associated with Window Sill	Damaged.	Encapsulation scheduled for Jun-Sep 2025.
Classroom 409	Floor Tile VAT 9" x 9"		
Classroom 409 Closet	Mastic associated with Floor Tile		
Classroom 409 Closet	Floor Tile VAT 9" x 9"		
Classroom 409 Coat Closet	Mastic associated with Floor Tile		
Classroom 409 Coat Closet	Floor Tile VAT 9" x 9"		
Classroom 410	Mastic associated with Floor Tile		
Classroom 410	Floor Tile VAT 12" x 12"		
Classroom 410	Floor Tile VAT 12" x 12"		
Classroom 410	Glue Dots associated with Blackboard		
Classroom 410	Transite associated with Closet		
Classroom 410	Transite associated with Window Sill		
Classroom 410	Floor Tile VAT 9" x 9"		
Classroom 410 Closet	Mastic associated with Floor Tile		
Classroom 410 Closet	Floor Tile VAT 9" x 9"		
Classroom 410 Coat Closet	Mastic associated with Floor Tile		
Classroom 410 Coat Closet	Floor Tile VAT 9" x 9"		
Women's Restroom across from Classroom 400	Transite associated with Door Transom		
Women's Restroom across from Classroom 400	Transite associated with Window Sill		
Custodial Closet across from Classroom 400	Transite associated with Door Transom		
Boy's Restroom across from Classroom 402	Transite associated with Door Transom		
Boy's Restroom across from Classroom 402	Transite associated with Window Sill	Significantly damaged.	Encapsulation scheduled for Jun-Sep 2025.
Girl's Restroom across from Classroom 402	Transite associated with Door Transom		
Girl's Restroom across from Classroom 402	Transite associated with Window Sill		
Men's Restroom across from Classroom 402	Transite associated with Door Transom		
Men's Restroom across from Classroom 402	Transite associated with Window Sill		
Fan Room next to Classroom 402	Transite associated with Door Transom		
Book Closet next to Fan Room	Mastic associated with Floor Tile		
Book Closet next to Fan Room	Transite associated with Door Transom		
Book Closet next to Fan Room	Floor Tile VAT 9" x 9"		
Hallway from Elevator to Classroom 410	Mastic associated with Floor Tile		
Hallway from Elevator to Classroom 410	Glue Dots associated with Blackboard		
Hallway from Elevator to Classroom 410	Glue Dots associated with Ceiling Tile 1' x 1'		
Hallway from Elevator to Classroom 410	Floor Tile VAT 12" x 12"		

James Rhoads School: Asbestos Hazard Report

Hallway from Elevator to Classroom 410	Floor Tile VAT 9" x 9"	Damaged.	Removal scheduled in Jun-Sep 2025.
Hallway from Classroom 400 to Classroom 401	Mastic associated with Floor Tile		
Hallway from Classroom 400 to Classroom 401	Transite associated with Window Sill		
Hallway from Classroom 400 to Classroom 401	Glue Dots associated with Ceiling Tile 1' x 1'		
Hallway from Classroom 400 to Classroom 401	Floor Tile VAT 12" x 12"		
Hallway from Classroom 400 to Classroom 401	Floor Tile VAT 9" x 9"		
Stairwell A	Transite associated with Window Sill		
Stairwell C	Transite associated with Window Sill		
Stairwell B	Transite associated with Window Sill		
Boiler Room	Fire Brick		
High Voltage Room	Transite associated with Electrical Panel		
Rooftop	Mortar		
Rooftop	Chimney Brick		